

22/03/2002

ASS. REC. BY:

REF: CS/CT119006155/P19d3⁵²

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

Minim

From (Person): Elaine Cheongof CT1Date/Time: 5.4.19 16.39pm

Estimated Cost:

Bill to:

OD-TP+WS+TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLL 3222B

Insured:

at Workshop m/s Lkt Group Pte LtdTel: 68461836of Blk 3006 ubi road 1, # 01-384 Kamping ubiPolicy No: BMPCSN 3025091801Claim No: SNM19D 20142401

Sum Insured:

Excess: \$750.00

Make of Veh:

D.O.A. 30.3.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 8.5.19 9.08am

Person Contacted:

mabel thngVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 3222B-CS/CT1 19005769/ud3 D.O.A- 30/3/2019
09/4/19 @ 3.19pm	Revert to Elaine Cheong re Meimner.
11/4/19 @ 10.09am	Wine Tay informed C/A via Meimner.
11/4/19 @ 2.06pm	Informed Mabel C/A on US basis & ex: \$750 by email.
	Rasul finalised with Mabel US \$10600, 7 days.
	Prod @ 12284.45, 54%.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Apr 2019		05 Apr 2019 16:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:

CHENG WEE LING KAREN, ID: S6807388Z, Tel: +6586661518, Email: NOEMAIL

Vehicle Reg. No.:

SLL3222B

Date of Loss:

30/03/2019 14:00 - :59

Claim Type:

OD / SNM19D201424C01

Policy/Cover Note No.:

DMPCSN3025091801
(Comprehensive)

Excess:

S\$750.00

Repairer:

Lkt Group Pte Ltd (HQ) Blk 3006 Ubi Road 1, #01 - 384 Kampong Ubi Industrial Estate, 408700 Ubi -
Tel: 68461836

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/04/2019]

Driver/Custodian:

CHENG WEE LING KAREN (51 / Female), NRIC: S6807388Z, Tel: +6586661518 Email: NOEMAIL

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 11 April 2019 2:06 PM
To: lkt.mabel@gmail.com
Cc: SUR
Subject: CHINA OD VEHICLE SLL 3222B (DOA: 30/03/2019)

Dear Mabel,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SLL 3222B at repair cost on Lump Sum basis (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	05 Apr 2019 16:38	Clim Veh Model Changed	(205988) MINI COOPER 1.5 HATCHBACK 3DR LED DSC (A).	[I] Elaine Cheong
2	05 Apr 2019 16:38	Clim Created	Reg No: SLL3222B. Policy No: DMPCSN3025091801. Acct Date: 2019/03/30. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Lkt Group Pte Ltd (HQ). Ins.Status => Incoming Claim. Created from SAS:MNA119042344	[I] Elaine Cheong
3	05 Apr 2019 16:39	Clim Registration Modified	Excess Waived: -> 0.00.	[I] Elaine Cheong
4	05 Apr 2019 16:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[I] Elaine Cheong
5	05 Apr 2019 16:39	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/16	[I] Elaine Cheong
6	05 Apr 2019 16:39	Adj Mandate Set	Approved:0.00.	[I] Elaine Cheong
7	05 Apr 2019 16:41	Assignment 1st Accessed		[A] LEE SU THING
8	08 Apr 2019 15:30	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] LEE SU THING
9	09 Apr 2019 15:13	Adj Rpt Initiated		[A] SHIAU CHAN
10	09 Apr 2019 15:13	Clim Dtl Modified	JPJ Reg. Date: -> 2014/07/17.	[A] SHIAU CHAN
11	09 Apr 2019 15:13	Clim Details Notified		[A] SHIAU CHAN
12	09 Apr 2019 15:18	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/04/16	[A] SHIAU CHAN
13	09 Apr 2019 15:19	Adj Mandate Request	Cur.Req:14401.40:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER REQUEST COST PLUS 15% ON PART ITEMS, KINDLY ADVISE. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
14	11 Apr 2019 10:09	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/16	[I] Irene Tay Hui Ping
15	11 Apr 2019 10:09	Adj Mandate Set	Approved:14401.40.	[I] Irene Tay Hui Ping

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2111337	09/04/2019 15:13	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLL3222B		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 09 Apr 2019

Preliminary Advice

Vehicle No	: SLL3222B	Accident Date	: 30/03/2019
Make	: MINI COOPER	Policy No.	: DMPCSN3025091801
Assignment Date	: 05/04/2019	Excess	: S\$750.00
Date of Inspection	: 08/04/2019	Est. Duration of Repair	: 6.00
Inspection At	: LKT GROUP PTE LTD (HQ) BLK 3006 UBI ROAD 1, #01 - 384 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,884.45
Revised Amount	:S\$	7,254.30
Check Items (Estimated)	:S\$	7,147.10
Total	:S\$	14,401.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	84,000.00
COE / PARF Rebate	:S\$	53,370.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,630.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER REQUEST COST PLUS 15% ON PART ITEMS, KINDLY ADVISE.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/04/2019 17:36
Date Of Accident	30/03/2019 14:25
Exact Location Of Accident	CTE (AYE) NEAR EXIT 8B
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL3222B
Insured/Policyholder	
Name Of Registered Owner	CHENG WEE LING KAREN
NRIC No	S6807388Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86661518
Alternative Phone No	OFFICE-86661518

Vehicle Particulars

Manufacturer	MINI
Model	COOPER S HATCHBACK 3DR LED DSC NAV
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3025091801
Cover Note Number	

Driver

Name of Driver	CHENG WEE LING KAREN
NRIC No	S6807388Z
Date Of Birth	19/02/1968
Occupation	OUTDOOR
Date Of Driving Pass	19/09/2003
Driving Experience	15 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-86661518
Fax Number	
Contact Number	OFFICE-86661518
Email Address	NOEMAIL

Address	550 YISHUN AVENUE 6 #11-01
Postcode	768961
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG THE STATED VENUE. SUDDENLY VEHICLE B JAMMED BRAKE, I COULDN'T BRAKE MY VEHICLE IN TIME AND HIT ONTO VEHICLE B REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGE7923G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LAI YILONG
NRIC/Passport Number	S8135998I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHA7562Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LOW SIN TUAN
NRIC/Passport Number	S1407237C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: : GENDER: :

DETAILS OF INJURED PERSON 1

Name	CHENG WEE LING KAREN
Approximate Age	
Injuries Sustain	CHEST
Injured person in which vehicle?	SLL3222B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders



Policyholder's Signature

Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7388Z
Vehicle Details	
Vehicle No.:	SLL3222B
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Apr 2019
Vehicle Make:	MINI
Vehicle Model:	COOPER S HATCHBACK 3DR LED DSC NAV
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	F5990778B48A20A
Chassis No.:	WMWXM72030T930849
Maximum Power Output:	141.0 kW (189 bhp)
Open Market Value:	\$31,126.00
Original Registration Date:	17 Jul 2014
First Registration Date:	17 Jul 2014
Transfer Count:	1
Actual ARF Paid:	\$25,577.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jul 2024
PARF Rebate Amount:	\$19,182.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jul 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$64,889.00
COE Rebate Amount:	\$34,188.00
Total Rebate Amount:	\$53,370.00

The information contained herein is correct as at 09 Apr 2019

OK

84,000
53,370

30,630



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8a RSZ



2.88%P.A Low Interest@GV
Finance, 2 Years Warranty.
\$2500 Down Monthly From \$73
GV Credit Pte Ltd StarAd

• Free VICOM evaluation
 • Free grooming and 6 months maintenance
 • In-house workshop ensures quality service
 • Member of SVTA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

3 vehicles

MINI COOPER 2.0

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	MINI COOPER 2.0	Any	Any	2014	Any	Any	Any	Available
	MINI Cooper S 2.0A	\$86,500	\$13,850 /yr	29-Aug-2014	1,998 cc	66,000 km	Sports	Available
Well Taken Care Of Cooper S. Still On Mini Warranty. All Wear And Tear Parts Replaced With Receipts To Prove. Confirm 100% Problem Free. Glass Coating Applied. Oz High Light Technology Rims With Ps4 T...								
Posted: 08-Apr-2019 Tags: 2014 MINI Cooper, 2014 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used MINI								
	MINI Cooper S 2.0A	\$87,778	\$13,590 /yr	26-Sep-2014	1,998 cc	81,000 km	Sports	Available
Beautiful Red Combination With Light Color Tone Interior Maintained By Meticulous Owner. Servicing Just Done, Hurry Quick And Arrange An Viewing Before It Is Gone.								
Posted: 30-Mar-2019 Tags: 2014 MINI Cooper, 2014 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used MINI								
	MINI Cooper S 2.0A	\$82,800	\$13,690 /yr	15-May-2014	1,998 cc	58,000 km	Sports	Available
Graded B by STA								
Lowest Interest Rate Of 1.99% For This Unit! Comes With Bidded Carplate 5050. Unit Comes With Gearbox Warranty, The Only STA Evaluated Cooper S 2.0A Unit, High PARF At \$13,000. Most Trendy Mini Cooper...								
Posted: 16-Mar-2019 Tags: 2014 MINI Cooper, 2014 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used MINI								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used MINI COOPER 2.0, MINI COOPER 2.0 Singapore, used MINI COOPER 2.0 Singapore, used MINI COOPER 2.0, used vehicles Singapore or even buy used MINI COOPER 2.0 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow **sgCarMart.com**

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

Compare

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Tel: 63896111

CERTIFICATE No.

DMPCSN3025091801

Engine No : F5990778B48A20A
Chassis No: WMWXM72030T930849

1. Index Mark and Registration Number of Vehicle

SLL3222B

2. Name of Policy Holder

CHENG WEE LING KAREN

3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment

18 MARCH 2019

NAMED DRIVERS EX SECT. I \$5750.00

4. Date of Expiry of Insurance

16 JULY 2019

ADDITIONAL EX OTHER THAN NAMED DRIVERS:

EX SECT. I - AGE <= 25 \$3,000.00

EX SECT. I - AGE >= 26 \$500.00

* AGE AS AT DATE OF ACCIDENT

EX ON WINDSCREEN \$100.00

5. Persons or Classes of Persons entitled to drive *

(A) THE POLICYHOLDER.

(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use: *

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.
THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.


EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS/THEFT) WILL BE DOUBLED.

ONE TIME WAIVER OF EXCESS FOR THE FIRST \$5500 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF OWN DAMAGE CLAIM AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.

HIRE PURCHASE CO. : TOKYO CENTURY LEASING (S) PTE LTD

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.


I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).
Please see reverse




Co-signed By:

Authorised Officer

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.



Authorised Signatory

550 #11-01 2nd Car Annex A

Transaction ref 20170322150435712067

The owner and vehicle particulars for Vehicle No. SLL3222B as at 22 Mar 2017 are as follows:

1. Name	: CHENG WEE LING KAREN
2. Identification No. Type	: Singapore NRIC
3. Identification No.	: S6807388Z
4. Place Of Passport Issue	: -
5. Vehicle No.	: SLL3222B
6. Previous Vehicle No.	: -
7. Effective Date of Ownership	: 22 Mar 2017
8. Original Registration Date	: 17 Jul 2014
9. First Registration Date	: 17 Jul 2014
10. Vehicle Type	: P10 - Passenger Motor Car
11. Vehicle Scheme	: Normal
12. Attachment 1	: No Attachment
13. Attachment 2	: -
14. Attachment 3	: -
15. Vehicle Make	: MINI
16. Vehicle Model	: COOPER S HATCHBACK 3DR LED DSC NAV
17. Year of Manufacture	: 2014
18. Primary Colour	: Silver
19. Secondary Colour	: -
20. Passenger Capacity	: 3
21. Chassis/Trailer Chassis No.	: WMWXM72030T930849 / -
22. Propellant	: Petrol
23. Engine No./Motor No.	: F5990778B48A20A / -
24. Engine Capacity(cc)/Power Rating(kW)	: 1998 / -
26. Unladen Weight(kg)	: 1175
27. Maximum Laden Weight(kg)	: 1655
28. Open Market Value	: \$31,126.00
29. PARF Eligibility	: Yes
30. PARF Eligibility Expiry Date	: 16 Jul 2024
31. Minimum PARF Benefit	: \$12,788.00
32. No. of Transfers	: 1
33. IU Label No.	: 1125372978
34. COE No.	: 2014080103000422N
35. COE Expiry Date	: 16 Jul 2024
36. COE Category	: B - Car (above 1600cc or 97kW (130bhp))
37. Quota Premium/Prevailing Quota Premium	: \$64,889.00 / -
38. Actual Quota Premium/PQP Paid	: \$64,889.00
39. Actual ARF Paid	: \$25,577.00
44. Vehicle Lifespan Expiry Date	: -
45. Road Tax Amount	: -
46. Road Tax Start Date	: -
47. Road Tax End Date	: -
48. Remarks	: To renew the COE, the Prevailing Quota Premium payable is that of Category B. The PARF eligibility of the vehicle will expire on 16 Jul 2024.



3887151

NRIC No. S6807388Z



Date of Issue
16-05-2006

550 YISHUN AVENUE 6 #11-01
SINGAPORE 768961

NRIC No. S6807388Z

Date: 02/05/2014

15151A

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver, and other motor vehicles < 2500kg 19 Sep 2003

NP 428A



Licence No. S6907300Z

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6807388Z

Name

CHENG WEE LING KAREN

鄭 薇 玲

Race

CHINESE

Date of birth

19-02-1968

Sex

F

Country of birth

SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE



CHENG WEE LING KAREN

Date: 19 Feb 1968

Date: 04 Jan 2006



001391776E

LKT Group Pte Ltd

Blk 3006 Ubi Road 1 #01-384 Singapore 408700

Tel: 68466260 Fax: 67449002

Email: lkt.mabel@gmail.com

The Motor Claims Department

4 April 2019

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

DID: 6389 6177

Fax: 6224 7478 / 6224 7175

Email: claimsdept@sg.cntaiping.com

REPAIR ESTIMATE FOR SLL3222B MINI COPPER S HATCHBACK

OWN DAMAGE CLAIM UNDER POLICY DMPCSN3025091801

SPARE PARTS

		\$
Front bonnet	1	1,120.00 ✓
Front bonnet hinge LH/RH	2	160.00 X
Front bonnet gas spring	2	200.00 X
Front bonnet lock, LH	1	65.00 ✓
Front bonnet lock, RH	1	65.00 X
Front bonnet air inlet scoop	1	125.00 X
Front bonnet Mini emblem	1	60.00 ✓
Front bonnet rear seal	1	65.00 ✓
Front bonnet insulator	1	145.00 X
Front support panel	1	115.00 ✓
Front bumper carrier/reinforcement	1	1,340.00 ✓
Front bumper reinforcement bracket LH/RH	2	190.00 95 ✓
Front bumper reinforcement compensating plate LH/RH	2	120.00 60 ✓
Front bumper cover	1	110.00 ✓
Front bumper trim	1	560.00 ✓
Front bumper adhesive film	1	65.00 ✓
Front bumper centre finisher	1	136.00 ✓
Front bumper grille	1	84.00 ✓
Front bumper air intake duct, LH/RH	1	100.00 50 ✓
Front grille	1	180.00 ✓
Front grille base plate	1	120.00 ✓
Front grille trim ring	1	110.00 ✓
Front grille S emblem	1	59.00 ✓
Front air duct	1	44.00 ✓
Tow cover	1	56.00 X
Front number plate holder	1	35 40.00 S/N ✓
Front bumper centre spoiler	1	195.00 X
Front bumper spoiler, LH	1	65.00 ✓
Front bumper spoiler, RH	1	65.00 X
Front bumper spoiler top trim panel	1	105.00 X
Front bumper side marker light, LH	1	100.00 X
Front bumper side marker light, RH	1	100.00 X
Xenon headlight, LH	1	1,650.00 ✓
Xenon headlight, RH	1	1,650.00 X
Headlight chrome ring LH/RH	2	112.00 ✓
Xenon light bulb, LH/RH	2	1,500.00 X
Xenon light control unit, LH/RH	2	1,300.00 X
Fog light, LH	1	175.00 ✓
Fog light, RH	1	175.00 X
Front fender, LH	1	350.00 X
Front fender liner, LH	1	102.00 ✓

6542 S/N 35

REPAIR ESTIMATE FOR SLL3222B MINI COPPER S HATCHBACK
OWN DAMAGE CLAIM UNDER POLICY DMPCSN3025091801

Front fender bracket, LH *Xsuc*
 Front wheel arc garnish, LH *end*
 Radiator *? bt*
 Radiator top/bottom foam seal *? ne*
 Radiator fan unit *? bt*
 Turbo air cooler *? bt*
 Turbo air cooler top cover *? Xsuc*
 Aircon condenser *? bt*
 Aircon receiver-dryer *? Xsuc*
 Aircon pressure hose, condenser to evaporator *? X*
 Aircon pressure hose, condenser to compressor *? X*
 Aircon pressure top hose, condenser to compressor *? X*
 Aircon suction hose *? Xsuc*

1	50.00	X
1	120.00	✓
1	500.00	✓
1	48.00	✓
1	680.00	✓
1	1,250.00	✓
1	125.00	X
1	700.00	✓
1	50.00	✓
1	215.00	X
1	195.00	✓
1	201.00	✓
1	225.00	X

Subtotal 17,443.00
 Add 15% 2,616.45
 Subtotal 1 20,059.45

LABOUR CHARGES

To check and repair wiring.

To align headlamps and refocus headlamp beams.

To remove and replace radiator and fan assy. Conduct pressure test to ensure no leak.

To remove and replace aircon condenser and hoses; vacuum and charge aircon gas.

Panel beating charges for repairing, replacing, welding and knocking damaged parts and areas.

Spray painting charges for painting new parts and repaired areas.

Towing fee

40 45.00 *1595*
~~80.00~~ *30*

~~120.00~~ *80?*

~~120.00~~ *80?*

~~1,200.00~~ *900*

~~1,200.00~~ *700*

60.00 *? receipt*

Subtotal 2 2,825.00

Total repair cost 22,884.45



LKT Group Pte Ltd
 Mabel Teng

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10/4/19
Subtotal 2

Resur
Hp 90010068

6 days
HS

6 days
08/04/19 P1530

EXCESS: 750

REVERT

Resurvey after repair

P-11316

S/N- 35

L-1895

T-131246

20%

10,596.80

L/S-10,600

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Apr 2019		05 Apr 2019 16:39 Edit Adj Rpt	S\$10,600.00 Edit Estimates	S\$10,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHENG WEE LING KAREN, ID: S6807388Z, Tel: +6586661518, Email: NOEMAIL			
Vehicle Reg. No.:	SLL3222B	Date of Loss:	30/03/2019 14:00 - :59 [56 Months and 13 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / SNM19D201424C01	Policy/Cover Note No.:	DMPCSN3025091801 (Comprehensive)	
		Excess:	S\$750.00	
Repairer:	Lkt Group Pte Ltd (HQ) Blk 3006 Ubi Road 1, #01 - 384 Kampong Ubi Industrial Estate, 408700 Ubi - Tel: 68461836			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 16/04/2019]			
Driver/Custodian:	CHENG WEE LING KAREN (51 / Female), NRIC: S6807388Z, Tel: +6586661518 Email: NOEMAIL			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- CHINA_TAIPING (11/04/2019): Alert - Adj Mandate Approved (S\$14401.40) - SLL3222B - Claim Handler: Elaine Che...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLL3222B (SNM19D201424C01)

OD

Mar 30 2019 2:00PM

[CHENG WEE LING KAREN]

Lkt Group Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Video			1 per page ▼	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	01/04/19 17:53	Video - Accident [Linked Accident Report Documents]	Load AVI	
Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/19 15:18	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/19 15:20	Odometer Reading	Load JPG	☒
2	09/04/19 15:20	Chassis Number	Load JPG	☒
3	09/04/19 15:20	General View	Load JPG	☒
4	09/04/19 15:20	General View	Load JPG	☒
5	09/04/19 15:20	General View	Load JPG	☒
6	09/04/19 15:20	General View	Load JPG	☒
7	09/04/19 15:20	General View	Load JPG	☒
8	09/04/19 15:20	General View	Load JPG	☒
9	09/04/19 15:20	General View	Load JPG	☒
10	09/04/19 15:20	General View	Load JPG	☒
11	09/04/19 15:20	General View	Load JPG	☒
12	09/04/19 15:20	General View	Load JPG	☒
13	09/04/19 15:20	General View	Load JPG	☒
14	09/04/19 15:20	General View	Load JPG	☒
15	09/04/19 15:20	General View	Load JPG	☒
16	09/04/19 15:20	General View	Load JPG	☒
17	09/04/19 15:20	General View	Load JPG	☒
18	09/04/19 15:20	General View	Load JPG	☒
19	09/04/19 15:20	General View	Load JPG	☒
20	09/04/19 15:20	General View	Load JPG	☒
21	09/04/19 15:20	General View	Load JPG	☒
22	09/04/19 15:20	General View	Load JPG	☒
23	09/04/19 15:20	General View	Load JPG	☒
24	09/04/19 15:20	General View	Load JPG	☒
25	09/04/19 15:20	General View	Load JPG	☒
26	09/04/19 15:20	General View	Load JPG	☒
27	09/04/19 15:20	General View	Load JPG	☒
28	09/04/19 15:20	General View	Load JPG	☒
29	09/04/19 15:20	General View	Load JPG	☒

Video			1 per page ▾	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
30	09/04/19 15:20	General View	 Load JPG	☒
31	09/04/19 15:20	General View	 Load JPG	☒
32	09/04/19 15:20	General View	 Load JPG	☒
33	09/04/19 15:20	General View	 Load JPG	☒
34	09/04/19 15:20	General View	 Load JPG	☒
35	09/04/19 15:20	General View	 Load JPG	☒
36	09/04/19 15:20	General View	 Load JPG	☒
37	09/04/19 15:20	General View	 Load JPG	☒
38	09/04/19 15:20	General View	 Load JPG	☒
39	09/04/19 15:20	General View	 Load JPG	☒
40	09/04/19 15:20	General View	 Load JPG	☒
41	09/04/19 15:20	General View	 Load JPG	☒
42	09/04/19 15:20	General View	 Load JPG	☒
43	09/04/19 15:20	General View	 Load JPG	☒
44	09/04/19 15:20	General View	 Load JPG	☒
45	09/04/19 15:20	General View	 Load JPG	☒
46	09/04/19 15:20	General View	 Load JPG	☒
47	09/04/19 15:20	General View	 Load JPG	☒
48	09/04/19 15:20	General View	 Load JPG	☒
49	09/04/19 15:20	General View	 Load JPG	☒
50	09/04/19 15:20	General View	 Load JPG	☒
51	09/04/19 15:20	General View	 Load JPG	☒
52	09/04/19 15:20	General View	 Load JPG	☒
53	09/04/19 15:20	General View	 Load JPG	☒
54	09/04/19 15:20	General View	 Load JPG	☒
55	09/04/19 15:20	General View	 Load JPG	☒
56	09/04/19 15:20	General View	 Load JPG	☒
57	09/04/19 15:20	General View	 Load JPG	☒
58	09/04/19 15:20	General View	 Load JPG	☒
59	09/04/19 15:20	General View	 Load JPG	☒
60	09/04/19 15:20	General View	 Load JPG	☒
61	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
62	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
63	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
64	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
65	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
66	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
67	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
68	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
69	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
70	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
71	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
72	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
73	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
74	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
75	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
76	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
77	22/05/19 13:44	Reinspection Photo	Load JPG	☒

Video			1 per page ▾	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
78	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
79	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
80	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
81	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
82	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
83	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
84	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
85	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
86	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
87	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
88	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
89	22/05/19 13:44	Reinspection Photo	 Load JPG	☒
90	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
91	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
92	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
93	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
94	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
95	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
96	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
97	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
98	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
99	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
100	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
101	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
102	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
103	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
104	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
105	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
106	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
107	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
108	22/05/19 13:45	Reinspection Photo	 Load JPG	☒
109	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
110	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
111	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
112	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
113	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
114	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
115	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
116	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
117	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
118	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
119	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
120	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
121	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
122	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
123	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
124	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
125	22/05/19 13:48	Reinspection Photo	Load JPG	☒

Video			1 per page	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
126	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
127	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
128	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
129	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
130	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
131	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
132	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
133	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
134	22/05/19 13:48	Reinspection Photo	 Load JPG	☒
135	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
136	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
137	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
138	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
139	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
140	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
141	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
142	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
143	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
144	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
145	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
146	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
147	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
148	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
149	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
150	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
151	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
152	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
153	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
154	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
155	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
156	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
157	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
158	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
159	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
160	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
161	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
162	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
163	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
164	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
165	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
166	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
167	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
168	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
169	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
170	22/05/19 13:49	Reinspection Photo	 Load JPG	☒
171	22/05/19 13:49	Reinspection Photo	Load JPG	☒
172	22/05/19 13:49	Reinspection Photo	Load JPG	☒
173	22/05/19 13:49	Reinspection Photo	Load JPG	☒

Video			1 per page ▾	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
174	22/05/19 13:49	Reinspection Photo	 Load JPG	✓
175	22/05/19 13:49	Reinspection Photo	 Load JPG	✓
176	22/05/19 13:49	Reinspection Photo	 Load JPG	✓
177	22/05/19 13:49	Reinspection Photo	 Load JPG	✓
178	22/05/19 13:49	Reinspection Photo	 Load JPG	✓
179	22/05/19 13:49	Reinspection Photo	 Load JPG	✓
180	22/05/19 13:49	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▾	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119006155/R1QD3S2

Date: 24/05/2019

REFERENCE

Insured/Claimant: CHENG WEE LING KAREN Policy No: DMPCSN3025091801
Date of Loss: 30/03/2019 Nature of Claim: OD Claim No: SNM19D201424C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL3222B**
Make & Model: MINI COOPER S, 2.0 (A) Engine No: F5990778B48A20A
Reg. Date: 17/07/2014 (Man. Year: 2014) Chassis No: WMWXM72030T930849
Colour: White Odometer: 65341 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$84,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,059.45	11,351.00	8,708.45	43.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,825.00	1,895.00	930.00	32.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,884.45	13,246.00	9,638.45	42.12
Approved Total (Overridden) (S\$)		10,600.00		
- Excess (S\$)	750.00	750.00	0.00	0.00
Nett Amount (S\$)	22,134.45	9,850.00	12,284.45	55.50

INSPECTION

Date of Assignment: 05/04/2019

Date Inspected: 08/04/2019 Inspected At:

Lkt Group Pte Ltd (HQ)
Blk 3006 Ubi Road 1, #01 - 384 Kampong Ubi
Industrial Estate
Singapore 408700

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2019)
Parts:	144	MINI COOPER S 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL3222B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,120.00 F	*1,120.00 F
2	2		*FRONT BONNET HINGE LH/RH	Serviceable	160.00 F	*- F
3	2		*FRONT BONNET GAS SPRING	Serviceable	200.00 F	*- F
4	1		*FRONT BONNET LOCK, LH	Bent	65.00 F	*65.00 F
5	1		*FRONT BONNET LOCK, RH	Serviceable	65.00 F	*- F
6	1		*FRONT BONNET AIR INLET SCOOP	Serviceable	125.00 F	*- F
7	1		*FRONT BONNET MINI EMBLEM	Necessary	60.00 F	*60.00 F
8	1		*FRONT BONNET REAR SEAL	Necessary	65.00 F	*65.00 F
9	1		*FRONT BONNET INSULATOR	Serviceable	145.00 F	*- F
10	1		*FRONT SUPPORT PANEL	Bent	115.00 F	*115.00 F
11	1		*FRONT BUMPER CARRIER/REINFORCEMENT	Bent	1,340.00 F	*1,340.00 F
12	2		*FRONT BUMPER REINFORCEMENT BRACKET LH/RH	NS Necessary/Os Not Necessary	190.00 F	*95.00 F
13	2		*FRONT BUMPER REINFORCEMENT COMPENSATING PLATE LH/RH	N/S Not Necessary / O/S Bent	120.00 F	*60.00 F
14	1		*FRONT BUMPER COVER	Deformed	110.00 F	*110.00 F
15	1		*FRONT BUMPER TRIM	Cracked	560.00 F	*560.00 F
16	1		*FRONT BUMPER ADHESIVE FILM	Necessary	65.00 F	*65.00 F
17	1		*FRONT BUMPER CENTRE FINISHER	Cracked	136.00 F	*136.00 F
18	1		*FRONT BUMPER GRILLE	Cracked	84.00 F	*84.00 F
19	2		*FRONT BUMPER AIR INTAKE DUCT, LH/RH	Cracked (1pc Only)	100.00 F	*50.00 F
20	1		*FRONT GRILLE	Cracked	180.00 F	*180.00 F
21	1		*FRONT GRILLE BASE PLATE	Cracked	120.00 F	*120.00 F
22	1		*FRONT GRILLE TRIM RING	Cracked	110.00 F	*110.00 F
23	1		*FRONT GRILLE S EMBLEM	Necessary	59.00 F	*59.00 F
24	1		*FRONT AIR DUCT	Cracked	44.00 F	*44.00 F
25	1		*TOW COVER	Serviceable	56.00 F	*- F
26	1		*FRONT NUMBER PLATE HOLDER	Deformed	52.90 FS	*35.00 FS
27	1		*FRONT BUMPER SPOILER, LH	Deformed	65.00 F	*65.00 F
28	1		*FRONT BUMPER SPOILER, RH	Serviceable	65.00 F	*- F
29	1		*FRONT BUMPER SPOILER TOP TRIM PANEL	Serviceable	105.00 F	*- F
30	1		*FRONT BUMPER SIDE MARKER LIGHT, LH	Serviceable	100.00 F	*- F
31	1		*FRONT BUMPER SIDE MARKER LIGHT, RH	Serviceable	100.00 F	*- F
32	1		*XENON HEADLIGHT, LH	Cracked	1,650.00 F	*1,650.00 F
33	1		*XENON HEADLIGHT, RH	Serviceable	1,650.00 F	*- F
34	2		*HEADLIGHT CHROME RING LH/RH	Necessary	112.00 F	*112.00 F
35	2		*XENON LIGHT BULB, LH/RH	Serviceable	1,500.00 F	*- F
36	2		*XENON LIGHT CONTROL UNIT, LH/RH	Serviceable	1,300.00 F	*- F
37	1		*FOG LIGHT, LH	Scratched	175.00 F	*175.00 F
38	1		*FOG LIGHT, RH	Serviceable	175.00 F	*- F
39	1		*FRONT FENDER, LH	Repair	350.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT FENDER LINER, LH	Scratched	102.00 F	*102.00 F
41	1		*FRONT FENDER BRACKET, LH	Serviceable	50.00 F	*- F
42	1		*FRONT WHEEL ARC GARNISH, LH	Cut	120.00 F	*120.00 F
43	1		*RADIATOR	Bent	500.00 F	*500.00 F
44	1		*RADIATOR TOP/BOTTOM FOAM SEAL	Necessary	48.00 F	*48.00 F
45	1		*RADIATOR FAN UNIT	Bent	680.00 F	*680.00 F
46	1		*TURBO AIR COOLER	Bent	1,250.00 F	*1,250.00 F
47	1		*TURBO AIR COOLER TOP COVER	Serviceable	125.00 F	*- F
48	1		*AIRCON CONDENSER	Bent	700.00 F	*700.00 F
49	1		*AIRCON RECEIVER-DRYER	Serviceable	50.00 F	*- F
50	1		*AIRCON PRESSURE HOSE, CONDENSER TO EVAPORATOR	Serviceable	215.00 F	*- F
51	1		*AIRCON PRESSURE HOSE, CONDENSER TO COMPRESSOR	Serviceable	195.00 F	*- F
52	1		*AIRCON PRESSURE TOP HOSE, CONDENSER TO COMPRESSOR	Serviceable	201.00 F	*- F
53	1		*AIRCON SUCTION HOSE	Serviceable	225.00 F	*- F
54	1		*FRONT BUMPER CENTRE SPOILER	Serviceable	195.00 F	*- F

F=Franchise part, S=SpcNett.

Sub Total (S\$)	17,449.90	9,875.00
+ Margin on L,N Items 15.00/15.00% (S\$)	2,609.55	1,476.00

Total Parts (S\$)	20,059.45	11,351.00
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK AND REPAIR WIRING.	New	45.00	45.00
2	TO ALIGN HEADLAMPS AND REFOCUS HEADLAMP BEAMS.	New	80.00	30.00
3	TO REMOVE AND REPLACE RADIATOR AND FAN ASSY. CONDUCT PRESSURE TEST TO ENSURE NO LEAK.	New	120.00	80.00
4	TO REMOVE AND REPLACE AIRCON CONDENSER AND HOSES; VACUUM AND CHARGE AIRCON GAS.	New	120.00	80.00
5	PANEL BEATING CHARGES FOR REPAIRING, REPLACING, WELDING AND KNOCKING DAMAGED PARTS AND AREAS.	New	1,200.00	900.00
6	SPRAY PAINTING CHARGES FOR PAINTING NEW PARTS AND REPAIRED AREAS.	New	1,200.00	700.00
7	TOWING FEE.	New	60.00	60.00
Gross Labour Cost (S\$)			2,825.00	1,895.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >