



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19006231/Kkb3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 26-12-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 2874G		Veh. Inspected	SLN 4169E
Policy No.	Z18VC05000660		Coverage (\$)	0.00
Claim No.	18/19/19/VC05/021645		Excess (\$)	0.00
Assign From	ONG LI LI		Assign Date	08/04/2019
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)		c.c	1798
Engine No.	HIDDEN		Year of Reg.	2017
Chassis No.	JTDKB3FU203556663		Colour	METALLIC PEARL WHITE
Odometer	145928		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre		195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre		195/65 R15	YOKOHAMA	8 mm
L/H Rear Tyre		195/65 R15	YOKOHAMA	8 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/04/2019		Inspection Date	09/04/2019
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			11 Working Days	