

not added
note
urgent

4/5 \$6700/2

TEL: 62633561

12/4/19

8 day
The phone after 1 year



Automobile Integrated Management Pte Ltd
(Business Reg no. 201605297G)
Office: 28 Sin Ming Lane #07-147
Midview City Singapore 573972
Email: automim.claim@gmail.com

ESTIMATE

Our Ref: AC2019006/TP/SLX6952U-06.04.2019

Vehicle number: SLX6952U

Vehicle Made & Model: HONDA HRV

Items	Qty	List Items	Amount \$
1	1	Tailgate	1,209.10 ✓
2	1	Tailgate outer garnish	341.20 X
3	1	Tailgate emblem "H"	32.20 X
4	1	Tailgate emblem "HRV"	45.90 ✓
5	1	Tailgate emblem "i-VTEC"	42.20 ✓
6	2	Tailgate lamps - L/R @ 311.80	623.60 X
7	1 set	Tailgate glass moulding	112.20 ✓
8	1	Tailgate inner lock	204.10 ✓
9	1	Tailgate inner trim	310.60 ✓
10	1	Tailgate inner pull pocket	85.60 X
11	1	Tailgate lock striker	28.60 X
12	1	Tailgate w/strip	114.10 ✓
13	2	Tailgate dampers - L/R @ 108.50	217.00 X
14	2	Tailgate hinges @ 74.10	148.20 X
15	2	Tailgate stoppers @ 12.20	24.40 X
16	2	Taillamps - L/R @ 381.90	763.80 ✓
17	1	Rear bumper	761.60 ✓
18	2	Rear bumper reflectors - L/R @ 89.60	179.20 X
19	2	Rear bumper sides - L/R @ 241.60	483.20 ✓
20	2	Rear bumper side retainers - L/R @ 48.60	97.20 X
21	10	Rear bumper clips @ 4.50	45.00 ✓
22	1	Rear end panel	560.90 ✓
23	1	Rear end panel inner trim	182.90 ✓
24	1	Rear exhaust silencer	688.10 X
25	1	Rear exhaust insulator	70.80 X
26	2	Rear exhaust mountings @ 18.60	37.20 X
27	1	Rear floor board	380.60 ✓
28	1	Rear floor tray	391.20 ✓
29	1	Rear floor panel	911.40 ✓
30	1	Rear floor panel undercover	241.20 ✓
31	2	Rear fender inner trims - L/R @ 290.80	581.60 X
32	1	Rear smart keyless antenna	180.90 X
33	1	Rear smart keyless buzzel	192.90 ✓
34	2	Rear fender wheel arch garnishes - L/R @ 241.20	482.40 ✓
Sub-total			10,772.10
Less 20%			2,154.42
Total List			8,617.68

P-6572.90

Vehicle number: SLX6952U

Vehicle Made & Model: HONDA HRV

Special Nett Items

35	1 set	Rear reverse sensor - 4 Pcs
36	1	Rear reverse camera
37	1 set	Tailgate glass sealant
38	1 set	Tailgate glass foam tape

shel	480.00	200
shub	450.00	380
ner	80.00	40
ner	65.00	30

Total Special Nett 1,075.00

Labour charges

39	To check rear electrical wiring
40	To remove, refix tailgate glass
41	To remove, refix rear reverse camera / sensor
42	To remove, refix rear exhaust systems
43	To respray undercoating
44	To remove, refix rear interior trims to assist repair
45	Reinstall tailgate electrical & mechanical to new tailgate
46	To respray painting and etc
47	Panel beating, cut, weld remove & replacing above parts

50.00	30
180.00	120
80.00	50
100.00	60
120.00	60
120.00	80
180.00	60
1,400.00	1100
1,500.00	1200

Total Labour 3,730.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

13,422.68

- UPON THE COMPLETION OF THE REPAIRS, THE WORK WILL BE:
- To be inspected by the insurance company
 - To be inspected by the insurance company
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by: [Signature]

P- 6572-90

50%

P- 3286.45

S.N- 660.00

Chm - 2760.00

6706.45