

VOLKSWAGEN CENTRE SINGAPORE

Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2
Document no.
Document date 15-04-2019
Customer no. 5211000859
Customer GST-ID 196900406D
Dealer 39999
Job order number 2019000149/ 1
Job order date 08-04-2019
Service Advisor TIOW CHUAN CHEE

Company
AXA Insurance Pte Ltd
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

Customer Details:
Mr
WOON
SI XIANG
130 PUNGOL WALK
#09-13
Singapore 828776

License plate SMJ3583H	Model code 5T13NZ	First registration 28-02-2019	VIN WVGZZZ1TZKW034634	Model Touran 1.4 CL GT110 TSDI7F	Mileage 200
---------------------------	----------------------	----------------------------------	--------------------------	-------------------------------------	----------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	R&R RIMS & BALANCE	1	pcs.	50.00	#1	50.00	53.50 ✓
	B&P WHEEL ALIGNMENT	1	pcs.	360.00	#1	360.00	385.20 ✓
	B&P MECH	1	pcs.	200.00	#1	200.00	214.00 3X
	Harness and Short Circuit Check						
	B&P DIAG	1	pcs.	360.00	#1	360.00	385.20 ✓
	For Diagnostic and Programming						
	B&P MACP SPRAY PAINT x 2	42	pcs.	500.00	#1	2,000.00	2,140.00 1000
	B&P MACP LABOUR	1.5	pcs.	580.00	#1	2,320.00	2,482.40 870
5TA807417 GRU	Cover For Bumper Primed	1	pcs.	1,139.96	#1	1,139.96	1,219.76
	REAR BUMPER x R						
5TA807568A 9B9	Spoiler Satin Black ?	1	pcs.	273.34	#1	273.34	292.47
	SPOILER ?						
5TA807863	Attachment Strip ?	1	pcs.	55.98	#1	55.98	59.90
	BUMPER CENTRE BRACKET ?						
5TA807305	Bumper ?	1	pcs.	442.56	#1	442.56	473.54
	REINFORCEMENT ?						
5TA807394	Guide Piece ?	1	pcs.	29.49	#1	29.49	31.55
	RHR SIDE BRACKET ?						
5TA807454	Guide Piece ?	1	pcs.	36.27	#1	36.27	38.81
	RHR TAILLIGHT BRACKET ?						
WHT005263	Rivet	4	pcs.	1.09	#1	4.36	4.67
5TA601025E FZZ	Alloy Wheel Aluminium Shi / CUT	1	pcs.	1,107.18	#1	1,107.18	1,184.68
311601361	Rubber Valve - MC	1	pcs.	3.22	#1	3.22	3.45

Quotation valid till 15-04-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1		8,382.36	7%	586.77	8,382.36	8,969.13
Total		8,382.36		586.77	8,382.36	8,969.13

Steve (LKK) will diagnose 15/4/19 2.30pm
8322 8813 4 days
PIP
Ry before spray

Customer

Service Advisor

LKK Auto Consultants have notified the Repairer the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

VISIT OUR WEBSITE: www.volkswagen.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions)

VOLKSWAGEN CENTRE SINGAPORE

Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
AXA Insurance Pte Ltd
8 SHENTON WAY
Singapore 068811

Customer data:
Mr
WOON
SI XIANG
130 PUNGGOL WALK
828776 Singapore

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

09-04-2019
5211000859
196900406D
39999
2019000149/ 1
08-04-2019
TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SMJ3583H	5T13NZ	28-02-2019	WVGZZZ1TZKW034634	Touran 1.4 CL GT110 TSID7F	200
