

ASS. REC. BY:

REF: CS/MSG19006273/vqd3n2

Special Instruction:

Surveyor:

Markus

ASSIGNMENT (Office)

Meimun

From (Person):

Jowyn Tan mei ling

of

MSIG

Date/Time:

8.4.2019 16.52p.m

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 7872K

Insured:

YN 1710H

at Workshop m/s

Zoom Auto Works

Tel:

745 07920

of

130 Bedok Reservoir Road #08-1339

Policy No:

28645042 MKC

Claim No:

589955

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4.4.2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time:

8.4.19 9.52a.m

Person Contacted:

Gilean

Vehicle

IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

Inspection at Bartley B centre, Block 15 #01-53

SKL 7872K - X

YN 1710H - NA / FC1 13011798 / r3

D.O.A - 28/6/2013

10/4/19 @ 12.20pm Informed Jowyn Tan, we are pending estimate from repairer.

17/4/19 @ 1.19pm revised to Jowyn Tan via Meimun.

REF: MS14

ASSIGNMENT

From:

Date: 9.4.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL 787rk

at Workshop m/s Zoom Autoworks

of Bentley B Centre Block 15 # 01-53

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

#665

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lump Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"wp"

2220

Vehicle: IN / OUT

Date:

Person Contacted:

26/4

Veh No:

SKL 787rk

Yt Rego:

16/11 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Jaguar XF

C.C

2967

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

150328

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

SAJAC05D9CFS30484

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

4/4/19

D.O.I.

9/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 3rd

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/4 7th. < 7A 5/6 12 22413388

16/4/19 4/5 #10.500 costumed with E.L.A. (Red #29308.30, 74%)

RECEIVED 17 APR 2019

17/4/2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 17/4 17/4

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

MER-9P

Lump Sum / I.B.I. (\$

1050

Survey Fee:

Transportation:

S + RS. \$

Photos:

Others:

TOTAL

250

10

260

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 17 Apr 2019

Preliminary Advice

Insured Vehicle No	: YN1710H	Accident Date	: 04/04/2019
TP Vehicle No	: SKL7872K	Assignment Date	: 08/04/2019
Make	: JAGUAR XF	Est. Duration of Repair	: 5.00
Date of Inspection	: 09/04/2019		
Inspection At	: ZOOM AUTOWERKS PTE LTD (HQ) 130 BEDOK RESERVOIR ROAD, EUNOS SPRING, #08-1339 SINGAPORE 470130		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,808.30
Revised Amount	:S\$	13,733.03
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,733.03
Lump Sum Repair	:S\$	10,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Apr 2019 11:13		08 Apr 2019 16:52 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Hupco Pte Ltd, Co. Reg. No.: 199206471G		
Main Claimant:	REMO COMM PTE LTD, Co. Reg. No.: 200512222D		
Vehicle Reg. No.:	SKL7872K	Date of Loss:	04/04/2019 09:00 - :59 [88 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28645042MKC Coverage: 02/12/2018 - 01/12/2019
Vehicle Reg. No. (Insured):	YN1710H	Policy No. (Claimant):	
		Excess:	
Repairer:	Zoom Autowerks Pte Ltd (HQ) 130 Bedok Reservoir Road, Eunos Spring, #08-1339, 470130 Bedok - Tel: 94507920		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/04/2019]		
Driver/Custodian (Insured):	AW SENG CHAI (), NRIC: S1426836G Email:		
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY:100%. CONTACT: ELIN CAI 9450 7920. ON WP.		

ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.

 ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 10 April 2019 12:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SKL 7872A (YOUR REF: 589955)

This mail is associated with :

***SKL7872K (589955)**

[YN1710H]

TP

REMO COMM PTE LTD

Apr 4 2019 9:00AM

[Hupco Pte Ltd]

Zoom Autowerks Pte Ltd

Dear Jowyn,

Please be informed that we have inspected the vehicle SKL 7872K on 09/04/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

Australia's Northern Territory - Explore Australia Holidays

Explore Australia's Northern Territory. Discover the worlds #4 Best Region and travel deal
northernterritory.com

jaguar xf

Price Range

Depreciation

2011

Vehicle Type

Home » Used Cars » Cass Cars Pte Ltd » Jaguar XF 3.0A Luxury

Jaguar XF 3.0A Luxury

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$55,000

Depreciation \$14,530 /yr
View models with similar depre

Reg Date 18-Feb-2011
(1yr 10mths 7days COE left)

Mileage 100,000 km (12.3k /yr)

Manufactured 2010

Road Tax \$2,348 /yr

Transmission Auto

Dereg Value \$41,731 as of today (change)

OMV \$55,949

COE \$58,910

ARF \$55,949

Engine Cap 2,967 cc

Power 175.0 kW (234 bhp)

Curb Weight 1,735 kg

No. of Owners 2

Type of Vehicle Luxury Sedan

Features

View specs of the Jaguar XF (2008-2013)

Description

Engine Just Overhauled In Aug 2018, Beautiful British Racing Green, Beige Interior Seats

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Get the market value of your existing car for free. Get started

Compare



Shortlist

Com

Report Error

M

Seller Information

Company	Cas
	» de
	» 3
Address	130
	Sear
Contact Person(s)	Cas:
	Leoi



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

jaguar xf

Price Range ▼

Depreciation ▼

2011 ▼

Vehicle Type ▼



Home » Used Cars » Direct Owners » Jaguar XF Diesel 2.2A Luxury

Jaguar XF Diesel 2.2A Luxury

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$65,000	Fuel Type	Diesel (Euro 5 Engine and Above)
Depreciation ?	\$14,150 /yr View models with similar depre	Reg Date	19-Dec-2011 (2yrs 8mths 8days COE left)
Mileage	118,600 km (16.2k /yr)	Manufactured ?	2011
Road Tax ?	\$2,196 /yr	Transmission	Auto
Dereg Value ?	\$52,277 as of today (change)	OMV ?	\$53,761
COE ?	\$74,340	ARF ?	\$53,761
Engine Cap	2,179 cc	Power	140.0 kW (187 bhp)
Curb Weight ?	1,810 kg	No. of Owners ?	1
Type of Vehicle	Luxury Sedan		

Features

Powerful 2.2L Turbocharged Euro 5 Diesel Engine, 8 Speed (A) Transmission, Torque 450 Nm, Power 140kW, 6 Airbags, Low Fuel Consumption Of 18.5 Km/L. View specs of the Jaguar XF Diesel (2008-2012)

Accessories

Multi-Media Touch Screen Interface With GPS, Bluetooth, 600w Sound System, Reverse Camera, Dual Climate, Front/Rear Parking Sensors, HID Headlights.

Description

One Of The Most Eye-catching And Beautiful XF In Singapore, With White And Black 20" BC Forged Rims Worth Almost \$8k With Staggered Configuration. Premium Grade Satin White Gold Metallic Wrap Over Original White Body. No Expenses Spared During Servicing. Zero Accidents And Problem Free. Owner's 2nd Car. Reluctant To Sell As The Car Served Very Well For The Past 6 Years.

Category

PARF Car, Direct Owner Sale

Status

Avi Compare


[Shortlist](#)
[Corr](#)
[Report Error](#)
[M](#)

Seller Information

Contact Person(s)

Contact No.

Enquiry

ESSENTIAL TRANSACTION

» Indemnity form

» Receipt

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2222D
Vehicle Details	
Vehicle No.:	SKL7872K
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Apr 2019
Vehicle Make:	JAGUAR
Vehicle Model:	XF 3.0 V6 LUXURY AT ABS D\AB HID 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	601090334FC
Chassis No.:	SAJAC05D9CFS30484
Maximum Power Output:	175.0 kW (234 bhp)
Open Market Value:	\$57,933.00
Original Registration Date:	16 Nov 2011
First Registration Date:	16 Nov 2011
Transfer Count:	1
Actual ARF Paid:	\$57,933.00 28966
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Nov 2021
PARF Rebate Amount:	\$34,759.00
Intended COE Rebate Details	
COE Expiry Date:	15 Nov 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$64,889.00
COE Rebate Amount:	\$16,853.00
Total Rebate Amount:	\$51,612.00

The information contained herein is correct as at 10 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/04/2019 16:22
Date Of Accident	04/04/2019 10:40
Exact Location Of Accident	FROM PIE STEVENS ROAD TWDS DUNEARN RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL7872K
Insured/Policyholder	
Name Of Registered Owner	REMO COMM PTE LTD
Co Reg No	200512222D
Email Address	ACCOUNTS@REMOCOMM.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68422242
Vehicle Particulars	
Manufacturer	JAGUAR
Model	XF 3.0 V6 LUXURY AT ABS DIAB HID 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA105062/1
Cover Note Number	

Driver

Name of Driver	MO BOON CHOONG
NRIC No	S7384126G
Date Of Birth	08/12/1973
Occupation	INDOOR
Date Of Driving Pass	21/02/2002
Driving Experience	17 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91098995
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 448 BUKIT PANJANG #11-551 SINGAPORE 670448

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN1710H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver AW SENG CHAI
NRIC/Passport Number S1426836G
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)



redefining / insurance

AXA Insurance Pte Ltd

1800 800 4808 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4700
 carl@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

Account number
 03975

-Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third Party Risks and Compensation) Rules, 1990 - Road Transport Act, 1987 (Malaysia)
 -Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	REMO COMM PTE LTD	Certificate number	GA10E082 / 1
Cover	Comprehensive	Chassis number	SAJAC0500C1S30484
Plan name	Private AFW	Engine number	601090334FC
NCD application	50%		
Vehicle registration number	90L7872K		
Period of insurance	from 16/05/2018 to 15/05/2019 (both dates inclusive)		
Finance loan company	CENTURY TOKYO LEASING (S) PTE LTD		

Persons or classes of persons entitled to drive*

- (a) Any Named Driver as stated in the Policy:
 1. MU BOON CHOONG
 (b) Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.
 * Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS Basic Own Damage Excess
 Windscreen Excess

S\$0.00
 S\$0.00

An Additional Excess is applicable as follows:

- S\$500 for unnamed Authorized Driver
- S\$500 for declared Young and Inexperienced Driver
- S\$5,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 189).
 The Premium Variance Clause requires the premium to be paid in full within a specific period during which there would be no liability under the policy, renewal certificate, endorsement etc.

AXA Insurance Pte Ltd (199903512M)
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068811
 Customer Centre, #B1-01

1 of 3

Sketch Plan Pg. 2



redefining / insurance

Date: 04/04/2019

To: Owner of Vehicle Number: SKL7872K

The following has been advised to you via your workshop, ETHOZ PROTECT PTE LTD through their staff, HASBULLAH.

Please tick the applicable box if you had been advice on the content as seen below:

- ☒ (✓) You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☒ (✓) You had been advised by the workshop on the liability and merits of the case accordingly.
- ☒ (✓) You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ () There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ () There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ () The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
- ☐ () You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☐ () For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using *any combination* of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☐ () You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ () For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☐ () Others _____


Signed and acknowledge by:

Name and signature of policyholder/authorised driver

Name and signature of workshop personnel including company stamp

FAY 70. 66347343 (H958XL)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At today morning around 10.00 am 4/4/19, I'm turning from Whitley road towards to Dunearn rd towards City. I keep my car at right lane and suddenly a truck YN1710H change lane from left to right. I try my best to alert (horn) him but he still bang to my car. (Infront of school)

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

- Reporting Only
- Claim OD
- Claim TP
- Claim OD ☒ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.



Policyholder's signature
Date & Time

Driver's Signature
(if driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
Nr/c In No.

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Record Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Officer's Signature
 Name:
 NRIC/IN No.:



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

10 April 2019

REG NO.: SKL 7872 K
MAKE/MODEL: JAGUAR XR

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front door - L/H	3,537.40
1	Front door outer chrome moulding	333.50
1	Front door inner lock	529.00
1	Front door inner board	2,415.00
1	Front door side mirror assy	3,148.70
1	Front door outer handle	432.40
1	Front door weatherstrip	276.00
1	Rear door -L/H	3,542.00
1	Rear door checker	216.20
1	Rear door outer chrome moulding	333.50
2	Rear door hinges	312.80
1	Rear door inner board	2,116.00
1	Rear door lock	540.50
1	Rear door outer handle	432.40
1	Rear door glass regulator	478.40
1	Rear door regulator motor	299.00
1	Rear door weatherstrip	172.50
1	Rear windscreen moulding	156.40
1	Rear taillamp -L/H	1,081.00
1	Rear bumper	2,530.00
1	Rear bumper side retainer	87.40
1	Rear fender -L/H	4,991.00
1	Rear fender inner shield	494.50
1	Rear wheel hub bearing	149.50
1	Rear tie rod	1,196.00
1	Rear shock absorber	598.00
1	Rear lower arm	724.50
1	Rear knuckle arm	1,196.00
1	Rear drive shaft	3,105.00
1	Rear stay arm	662.40
		36,087.00
	Less 10%	3,608.70
		32,478.30

Not Authorised
H/L
1/54 10,500/-
9/4/19 Sdy.

3090.60

389.00

255.00

3079.93

4537.71

11681.14

102

10513.02

3220.00

13733.02

11886.

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	80.00	40
1	Rear bumper clip (1 set)	\$	80.00	X
1	Rear tyre	\$	300.00	X
1	Rear wheel rim -L/H	\$	1,500.00	800
		\$	1,960.00	

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$	180.00	100
3	To remove and refit rear undercarriage.	\$	450.00	X
4	To conduct wheel alignment.	\$	180.00	60
5	To remove and refit rear windscreen glass.	\$	180.00	120
6	To remove, refit doors fittings and replace damaged parts, transfer all fittings to new door.	\$	400.00	150
7	To apply undercoating.	\$	200.00	50
8	Panel beating.	\$	1,800.00	800
9	To re-spray painting on the affected areas.	\$	1,600.00	1000
10	To diagnose erase fault memory after repair.	\$	300.00	80
		\$	5,370.00	

2380.00

GRAND TOTAL :**\$ 39,808.30**

LKKA Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No ill or modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19006273/UQD3N2

Date: 24/04/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28645042
Claimant Vehicle No :	SKL7872K	Insured Vehicle No :	YN1710H
Date of Loss:	04/04/2019	Nature of Claim:	TP
		Claim No:	589955

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL7872K	Engine No:	601090334FC
Make & Model:	JAGUAR XF, 3.0 V6 LUXURY (A)	Chassis No:	SAJAC05D9CFS30484
Reg. Date:	16/11/2011 (Man. Year: 2001)	Odometer:	150329 km
Colour:	Black		
Engine Capacity:	2967 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,438.30	11,353.03	23,085.27	67.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,370.00	2,380.00	2,990.00	55.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,808.30	13,733.03	26,075.27	65.50
Approved Total (Overridden) (S\$)		10,500.00		
Nett Amount (S\$)	39,808.30	10,500.00	29,308.30	73.62

INSPECTION

Date of Assignment:	08/04/2019	
Date Inspected:	09/04/2019	Inspected At: Bartley B Centre Block 15 #01-53 Repairer: Zoom Autowerks Pte Ltd (HQ)
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2019)
Parts: 143	JAGUAR XF 3.0 V6 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL7872K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-L/H	Dented/Warped	3,537.40 FL	*3,090.60 FL
2	1		*FRONT DOOR OUTER CHROME MOULDING	Not Necessary	333.50 FL	*- FL
3	1		*FRONT DOOR INNER LOCK	Not Necessary	529.00 FL	*- FL
4	1		*FRONT DOOR INNER BOARD	Not Necessary	2,415.00 FL	*- FL
5	1		*FRONT DOOR SIDE MIRROR ASSY	Not Necessary	3,148.70 FL	*- FL
6	1		*FRONT DOOR OUTER HANDLE	Cut	432.40 FL	*389.00 FL
7	1		*FRONT DOOR WEATHERSTRIP	Necessary	276.00 FL	*255.00 FL
8	1		*REAR DOOR-L/H	Dented/Warped	3,542.00 FL	*3,079.93 FL
9	1		*REAR DOOR CHECKER	Not Necessary	216.20 FL	*- FL
10	1		*REAR DOOR OUTER CHROME MOULDING	Not Necessary	333.50 FL	*- FL
11	2		*REAR DOOR HINGES	Not Necessary	312.80 FL	*- FL
12	1		*REAR DOOR INNER BOARD	Not Necessary	2,116.00 FL	*- FL
13	1		*REAR DOOR LOCK	Not Necessary	540.50 FL	*- FL
14	1		*REAR DOOR OUTER HANDLE	Not Necessary	432.40 FL	*- FL
15	1		*REAR DOOR GLASS REGULATOR	Not Necessary	478.40 FL	*- FL
16	1		*REAR DOOR REGULATOR MOTOR	Not Necessary	299.00 FL	*- FL
17	1		*REAR DOOR WEATHERSTRIP	Necessary	172.50 FL	*172.50 FL
18	1		*REAR WINDSCREEN MOULDING	Necessary	156.40 FL	*156.40 FL
19	1		*REAR TAILLAMP-L/H	Not Necessary	1,081.00 FL	*- FL
20	1		*REAR BUMPER	Repair	2,530.00 FL	*- FL
21	1		*REAR BUMPER SIDE RETAINER	Not Necessary	87.40 FL	*- FL
22	1		*REAR FENDER-L/H	Badly Dented	4,991.00 FL	*4,537.71 FL
23	1		*REAR FENDER INNER SHIELD	Not Necessary	494.50 FL	*- FL
24	1		*REAR WHEEL HUB BEARING	Not Necessary	149.50 FL	*- FL
25	1		*REAR TIE ROD	Not Necessary	1,196.00 FL	*- FL
26	1		*REAR SHOCK ABSORBER	Not Necessary	598.00 FL	*- FL
27	1		*REAR LOWER ARM	Not Necessary	724.50 FL	*- FL
28	1		*REAR KNUCKLE ARM	Not Necessary	1,196.00 FL	*- FL
29	1		*REAR DRIVE SHAFT	Not Necessary	3,105.00 FL	*- FL
30	1		*REAR STAY ARM	Not Necessary	662.40 FL	*- FL
31	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
32	1		*SET REAR BUMPER CLIP	Not Necessary	80.00 FS	*- FS
33	1		*REAR TYRE	Serviceable	300.00 FS	*- FS
34	1		*REAR WHEEL RIM-L/H	Cut	1,500.00 FS	*800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	38,047.00	12,521.14
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,608.70	1,168.11
Total Parts (\$\$)	34,438.30	11,353.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	100.00
3	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	450.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	180.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO REMOVE,REFIT DOORS FITTINGS AND REPLACE DAMAGED PARTS,TRANSFER ALL FITTINGS TO NEW DOOR	New	400.00	150.00
7	TO APPLY UNDERCOATING	New	200.00	50.00
8	PANEL BEATING	New	1,800.00	800.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,600.00	1,000.00
10	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	New	300.00	80.00
Gross Labour Cost (\$\$)			5,370.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >