

INS. CASE OWNER:

CC 3, ALG 1900 6283, A Kaly

LKK:
IDAC:

Surveyor:

ADRIAN

DOI:

ASSIGNMENT

15/04/19

Date / Time:

9/4/19

Registered in Merimen:

9/4/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLP 8215E

Name of Insured:

Lee Yang Kwang

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

8/4/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

DATE / PIC

15/4

SLK 95564 X: SLP 8215E X

STAGE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

15/04/19

BANK LIABILITY CLAIM

15/4/19 P.

2pm

- Khorhuan

Spoke to OI He confirmed the mya. Informed OI on TP claim, agreed to settle and cause. NCD will be affected. Sent letter to OI

26/3/2020
Khorhuan

File pass to MK to close.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P SS 4,666.40 (3 days) Reduction: 78 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

4,993.05

Loss of Rental (LOR):

SS

-

(- days)

Loss of Use (LOU):

SS

240

(360 x 4 days)

Loss of Income (LOI):

SS

-

(\$ x - days)

LOR only ☐ LOU only ☒

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS

5,235.05

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

5,235.05

Name 1:

PREMIUM AUTOMOBILES PTELTO

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP

\$320

COI (Note - ENJOY TO)

CNA search date is diff

COPY SENT

27/3/2020

vof.

ASS-REC BY: .

REF:

6283 (AW)

Adrian

ASSIGNMENT

Front: . Date: .

Estimated Cost: .

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: .

at Workshop m/s .

of .

Insured .

Policy No: .

Claims No: .

Sum Insured: . Excess: .

(Client's Record)

Make of Veh: .

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: .

IDAC Accident Rpt: . Consistent? : Yes or No

GIA / PR Seen: . Consistent? : Yes or No

Est. Repairs: 03 88/5 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: . Person Contacted: . Vehicle: IN / OUT

Veh No: SKX9556Y. Yr Regn: 2015 / Dec

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q3 cc 1395

Colour: White AC: Insured / Std / NI / NA

Sp. Reading 36917. T/Radio: Insured / Std / NI / NA

Eng/No: .

C/No: WAUZZZ8U7G R041155

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R17.

R: 235/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 17/04/19

Survey held at Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

T7 A16.

CP/P \$4,666.40 / Red \$16,916.60 / 78/.)

MV :

PV :

3 days + 1 Sunday + 1 PH = 5 days

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report

Final Report

Part Prices Check

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0457/2019/DY
Date : 9-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : **SKP 8215 E**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Wong Kar Kean
Address : 20A Sea Avenue
Singapore 424241
Telephone : 90690132
Type of Claim : Third Party Claim
Policy No. :
Vehicle No : **SKX 9556 Y**
Model Code : Q3 1.4 TFSI S tronic
Model / Year : 31/12/2015
Engine No : CZD 217575
Chassis No : WAUZZZ8U7GR041155
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Apr-19
Place of Accident : Central Boulevard Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 9556 Y

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	s/n \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray rear bumper, rear bumper spoiler and both rear wheel arch trims. 400 added for rear spoiler, both wheel arch trim and front end with 600 for respraying	\$ 2,500.00 550 950	
4	To carry out diagnostic check.	s/n \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,022.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKX 9556 Y**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER COVER <i>2 parts cracked.</i>	\$ 1,238.00	✓ 990.40
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 104.00	✗
3	REAR BUMPER SPOILER <i>at</i>	\$ 716.00	✓ 572.40
4	REAR DIFFUSER - LH <i>at</i>	\$ 572.00	✓ 457.60
5	COVER FOR TOWING EYE - LH <i>3 new</i>	\$ 21.00	✗
6	COVER FOR TOWING EYE - RH	\$ 21.00	✗
7	TAIL LIGHT - RH <i>new</i>	\$ 387.00	✗
8	REAR BUMPER CARRIER <i>2</i>	\$ 525.00	✗
9	REAR PARKING SENSOR <i>3 new</i>	2 \$ 415.00	✗
10	SEAL RING	4 \$ 5.00	✗
11	REAR WHEEL COVER - LH <i>3 new</i>	\$ 453.00	✓ 362
12	REAR WHEEL COVER - RH	\$ 453.00	✓ 362
13	SUNDRIES <i>Reel new</i>	\$ 500.00	✗
14			
15			
16			
17			
18			
19			
20			

TOTAL SPARE PARTS	:	\$ 17,431.00
TOTAL LABOUR CHARGES	:	\$ 4,152.00
GRAND TOTAL	:	\$ 21,583.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian King

Surveyed Date

:

17/04/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

:

This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0457/2019/DY
Date : 9-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : **SKP 8215 E**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

3 days exclude 1 PH - JB - 22/6/19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Wong Kar Kean
Address : 20A Sea Avenue
Singapore 424241
Telephone : 90690132
Type of Claim : Third Party Claim
Policy No. :
Vehicle No : **SKX 9556 Y**
Model Code : Q3 1.4 TFSI S tronic
Model / Year : 31/12/2015
Engine No : CZD 217575
Chassis No : WAUZZZ8U7GR041155
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Apr-19
Place of Accident : Central Boulevard Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 9556 Y

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	s/n	\$ 280.00	\$ 280.00
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 1,050.00	\$ 500.00
3	To respray rear bumper, rear bumper spoiler and both rear wheel arch trims. (Added \$400.00 for rear spoiler, both wheel arch) Part No end with GRU must respray		\$ 2,500.00	\$ 950.00
4	To carry out diagnostic check.	s/n	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 4,022.00</u>	<u>\$ 1,922.00</u>

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 9556 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER COVER	\$ 1,238.00	\$ 990.40
2	REAR BUMPER FIXING PARTS	\$ 104.00	
3	REAR BUMPER SPOILER	\$ 716.00	\$ 572.40
4	REAR DIFFUSER - LH	\$ 572.00	\$ 457.60
5	COVER FOR TOWING EYE - LH	\$ 21.00	
6	COVER FOR TOWING EYE - RH	\$ 21.00	
7	TAIL LIGHT - RH	\$ 387.00	
8	REAR BUMPER CARRIER	\$ 525.00	
9	REAR PARKING SENSOR	2 \$ 415.00	
10	SEAL RING	4 \$ 5.00	
11	REAR WHEEL COVER - LH	\$ 453.00	\$ 362.00
12	REAR WHEEL COVER - RH	\$ 453.00	\$ 362.00
13	SUNDRIES	\$ 500.00	
14			
20			
TOTAL SPARE PARTS		\$ 17,431.00	\$ 2,744.40
TOTAL LABOUR CHARGES		\$ 4,152.00	\$ 1,922.00
GRAND TOTAL		\$ 21,583.00	\$ 4,666.40

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 23 September 2019 11:50 AM
To: Carrine Leong; Adrian Ling (LKKAuto); Vic (LKKAuto); CS A Team; Admin A
Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SKX9556Y - TP AIG - SURVEYED 17 APR 19

Without Prejudice

Dear Sirs/Mdm,

Thank you for your patience.

For COR, recommended amount at **P/P \$4,666.40(before GST)** with **3 repair days**.

** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Friday, 26 July 2019 2:29 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SKX9556Y - TP AIG - SURVEYED 17 APR 19

Hi Adrian and All,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.

Revised estimate was mailed to you 22 Jun 2019.

We sincerely appreciate your early closure.

Thanks & Best Regard
Carrine Leong

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Centre #01-21
Tel: 1800 8804888
Website: www.axa.com.sg
GST Registration Number: 199903512M
Customer.care@axa.com.sg



CERTIFICATE OF INSURANCE

• Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) • Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 • Road Transport Act, 1987 (Malaysia) • Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO.	: VPA/P1674059	Account No.	: 13950
Coverage	: Comprehensive		
Sum Insured	: Market Value At The Time Of Loss		
Name of Policy Holder	: WONG KAR KEAN		
Vehicle Registration No.	: SKX9556Y		
Period of Insurance	: From 31/12/2018 To 30/12/2019 (Both Dates Inclusive)		

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

(a) The Policyholder
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner
(b) Any other person who is driving on the Policyholder's order or with his permission
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business
The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess	: SGD	1200.00
Voluntary Excess	: SGD	1000.00
Final Basic Own Damage Excess	: SGD	2200.00

An additional Excess is applicable as follows:

\$5500.00 for Unnamed Authorized Driver &/or Declared Young & Inexperience Driver.

\$5,000.00 for Undeclared Young and Inexperienced Driver.

(Please refer to your policy on the terms & conditions)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certification relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Authorized Workshop

Elite AM Pte Ltd

AXA INSURANCE PTE LTD


Authorized Signature

Issued by - SGOMOHA on 28/12/2018

IMPORTANT:

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with the obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act, (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, cover note and endorsement etc.

Your Ref: CC3/AIG19006283/HA3

Authorization letter

PA/TP/0457/2019/KK

7 June 2019

Mr. Wong Kar Kean
20A Sea Avenue
Singapore 424241

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

Dear Sir/ Mdm,

**ACCIDENT INVOLVING VEHICLES SKX 9556 Y/ SKP 8215 E
AT CENTRAL BOULEVARD ROAD ON 07 JUNE 2019.**

I am the owner of SKX 9556 Y.

I confirmed that I will be claiming for Loss of Usages / Rental Charges and hereby authorized your esteemed company to settle the repair bill and Loss of Usages / Rental Charges and directly with Premium Automobiles Pte Ltd.

Your kind attention will be greatly appreciated.

Yours faithfully,



Mr. Wong Kar Kean.

Copy to Norah Khai, Premium Automobiles Pte Ltd

BREAKDOWN OF PAYMENT

Vehicle No: SKX9556Y

Accident on 8/4/2019 at Central Boulevard Road

Involving vehicle/s SKP8215E

1) Repair cost \$ 9993.05 Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 2.00 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 240.00 Payable to: Wong Kar Kean

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 26 March 2020 9:24 AM
To: Claims
Cc: Admin A
Subject: RE: LOD - ACCIDENT INVOLVING SKX 9556 Y AND YOUR INSURED SKP8215E DATED ON 08/04/2019 *** LKK REF: CC3/AIG19006283/Aka3

Without Prejudice

Dear Sir/Madam,

The above matter refers.

We confirm settlement as per your LOD for **(S\$235.05(all in))**.

We will proceed to do the necessary.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 23 March 2020 8:47 AM
To: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: LOD - ACCIDENT INVOLVING SKX 9556 Y AND YOUR INSURED SKP8215E DATED ON 08/04/2019 *** LKK REF: CC3/AIG19006283/Aka3

Dear Khanchna,

Any updates?

Best Regards,
Nadia
Claims Administrator

...CLAIM SUBFOLDER...(Pending for Survey Report)
Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Apr 2019 Edit Reg		17 Apr 2019 00:00 Edit Adj Rpt	S\$4,666.40 Edit Estimates	S\$4,666.40 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

Lee Yang Kwang, ID: S0184196C

Main Claimant:

WONG KAR KEAN, ID: S79757333

Vehicle Reg. No.:

SKX9556Y

Date of Loss:

08/04/2019 08:00 - :59
[39 Months and 8 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 5428549476SG

Policy/Cover Note No.:

(Comprehensive)

Vehicle Reg. No. (Insured):

SKP8215E

Policy No. (Claimant):

VPA/P1874059

Excess:

Repairer:

Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com

Claimant's Insurer:

AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/04/2019]

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX9556Y (5428549476SG)
[SKP8215E]
TP
WONG KAR KEAN
Apr 8 2019 8:00AM
[Lee Yang Kwang]
Premium Automobiles Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	<div>1</div> <div>Edit</div>	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/08/19 15:56	General View	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
2	30/08/19 15:56	General View	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
3	30/08/19 15:56	General View	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
4	30/08/19 15:56	General View	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
5	30/08/19 15:56	General View	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
6	30/08/19 15:56	General View	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
7	30/08/19 15:56	General View	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
8	30/08/19 15:56	General View	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
9	30/08/19 15:56	General View	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
10	30/08/19 15:56	General View	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
11	30/08/19 15:56	Reinspection Photo	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
12	30/08/19 15:56	Reinspection Photo	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
13	30/08/19 15:56	Reinspection Photo	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
14	30/08/19 15:57	Reinspection Photo	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
15	30/08/19 15:57	Reinspection Photo	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
16	30/08/19 15:57	Reinspection Photo	<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/19 16:49	TP GIA REPORT	<div>1</div> <div>Load PDF</div>	
2	15/04/19 15:10	LETTER TO OI	<div>1</div> <div>Load PDF</div>	
3	24/04/19 11:14	TP ESTIMATE - MARKED	<div>1</div> <div>Load PDF</div>	
4	01/04/20 09:02	WORKSHOP INVOICE	<div>1</div> <div>Load PDF</div>	
5	01/04/20 09:02	AUTHORISATION TO ACT FORM	<div>1</div> <div>Load PDF</div>	
6	01/04/20 09:02	Release Voucher	<div>1</div> <div>Load PDF</div>	
7	01/04/20 09:02	GIA SEARCH	<div>1</div> <div>Load PDF</div>	
8	01/04/20 09:02	LOD	<div>1</div> <div>Load PDF</div>	

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/04/19 14:07	OI GIA REPORT	<div>1</div> <div>Load PDF</div>	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SKP8215E (Insd veh)	Model:	AUDI Q3 1.4 TFSI (A)
	SKX9556Y (TP veh)		
Date of Accident:	08/04/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	10,092.24
Final Repair Cost	:	\$	4,993.05
Loss of Use	:	\$	240.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	5,235.05
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____100_____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 5,235.05
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

01 Apr
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19006283/AKA3Q2

Date: 01/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SKX9556Y

Insured Vehicle No : SKP8215E

Date of Loss: 08/04/2019

Nature of Claim: TP

Claim No: 5428549476SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX9556Y

Make & Model: AUDI Q3, 1.4 TFSI (A)

Engine No: CZD217575

Reg. Date: 31/12/2015 (Man. Year: 2015)

Chassis No: WAUZZZ8U7GR041155

Colour: White

Odometer: 36917 km

Engine Capacity: 1395 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R17

Rear Tyre Size: 235/55 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,410.00	2,744.40	2,665.60	49.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,022.00	1,922.00	2,100.00	52.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,432.00	4,666.40	4,765.60	50.53
+ GST 7.00/7.00% (S\$)	660.24	326.65	333.59	50.53
Nett Amount (S\$)	10,092.24	4,993.05	5,099.19	50.53
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,235.05		

INSPECTION

Date of Assignment: 17/04/2019

Date Inspected: 17/04/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Cracked	1,238.00 FS	*990.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	104.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	716.00 FS	*572.40 FS
4	1		*REAR DIFFUSER -LH	Cut	572.00 FS	*457.60 FS
5	1		*COVER FOR TOWING EYE -LH	Not Necessary	21.00 FS	*- FS
6	1		*COVER FOR TOWING EYE -RH	Not Necessary	21.00 FS	*- FS
7	1		*TAIL LIGHT -RH	Not Necessary	387.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Not Necessary	525.00 FS	*- FS
9	2		*REAR PARKING SENSOR	Not Necessary	415.00 FS	*- FS
10	4		*SEAL RING	Not Necessary	5.00 FS	*- FS
11	1		*REAR WHEEL COVER -LH	Necessary	453.00 FS	*362.00 FS
12	1		*REAR WHEEL COVER -RH	Necessary	453.00 FS	*362.00 FS
13	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
Total Parts (S\$)					5,410.00	2,744.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER ,REAR BUMPER ,SPOILER AND BOTH REAR WHEEL ARCH TRIMS	New	2,500.00	950.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,022.00	1,922.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >