





























PAR Automotive Consultancy

Regn. No. 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0119-19-TCA

04 March 2019

ACCIDENT VEHICLE SURVEY REPORT

Sng Sook Boon
42 Circuit Road #07-525
Singapore 370042

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SLF9289B	<i>Odometer:</i>	25435km
<i>Make & Model:</i>	Hyundai Elantra 1.6 GLS	<i>Colour:</i>	White
<i>Chassis number:</i>	KMHD841CMHU198625	<i>Date of accident:</i>	23/10/2018
<i>Year of Regn.:</i>	16/09/2016	<i>Date inspected:</i>	24/10/2018
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	30/10/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:



We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.




































SLF9289B