

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

LEONG LAI PENG

TPALG.
Poh Kin.

DATE	9/4/2019
VEHICLE NO:	SLP 790 B
MAKE:	KIA
MODEL:	CERATO

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	REAR BUMPER <i>replaced</i>	768.47	768.47
1 PC	REAR BUMPER LOWER GARNISH <i>replaced</i>	387.12	387.12
1 PC	REINFORCEMENT <i>replaced</i>	358.31	358.31
1 PC	END PANEL <i>Painted</i>	349.84	349.84
1 PC	END PANEL TOP GARNISH <i>replaced</i>	87.29	87.29
1 PC	WEATHER STRIP <i>new</i>	121.44	121.44
1 PC	BOOTLID <i>Rebuilt</i>	974.54	974.54
1 PC	CERATO LOGO <i>new</i>	35.74	35.74
1 PC	KIA LOGO	37.56	37.56
	----- SUBTOTAL		3,120.31
LESS 10%	----- LESS 10%	-10.00%	-312.03
1 SET	REVERSE SENSOR <i>engd</i>	280.00	280.00 <i>200</i>
-	TO SUPPLY FITTINGS AND INSTALL REVERSE SENSOR	60.00	60.00 <i>40</i>
-	TO REPLACE END PANEL INCLUDE KNOCKING AND WELDING TO INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC.	950.00	950.00 <i>800</i>
-	TRANSFER BOOTLID MECHANISMS, TRIMS AND FITTINGS TO NEW BOOTLID	150.00	150.00 <i>+</i>
-	TO REMOVE AND REFIX INNER TRIMS AND BOARDS TO FACILITATE REPAIR WORK	150.00	150.00 <i>50</i>
-	TO SPRAY PAINT END PANEL, REAR BUMPER AND BOOTLID.	850.00	850.00 <i>600</i>
-	TO SUPPLY AND TUFF KOTE AFFECTED PARTS	80.00	80.00 <i>60</i>
-	TO CARRY OUT WIRE CHECKING	100.00	100.00 <i>30</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Adrian Lg
2/5 09/04/19.
05 Apr.
Total: 4428.98
4/5: 3550

Tel: 6745 5783 Fax: 6744 9582

Email: sinhweemotor@gmail.com

Website: www.sinhweemotor.com

TOTAL \$5,428.28