

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

CARRO LEASING PTE LTD
GREEN FOREST LANDSCAPE PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

09th APRIL 2019

Accident date: 08th APRIL 2019

Estimated repair cost for vehicle no: SMG5742T TOYOTA AXIO 1.5X A '09

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet		\$980.20
2	1	Front headlamp -LH		\$681.80
3	1	Front support panel side cover		\$161.10
4	1	Front bumper		\$480.75
5	2	Front Bumper Side Bracket	\$161.10	\$322.20
6	8	Front bumper clips	\$12.90	\$103.20
7	1	Front Grille		\$381.40
8	1	Front Grille emble logo		\$61.00
9	4	Front Grille clips	\$12.90	\$51.60
10	1	Front bumper inner sponge		\$182.80
11	1	Front L/H fender		\$591.40
12	1	Front L/H fender inner shiled		\$182.25
13	1	Front L/H fender inner shiled clips		\$50.00
14	1	Front L/H rim		\$450.00
15	1	front L/H tyre		\$300.00
Subtotal :-				<u>\$4,979.70</u>

Labour charges

To remove & re-fix front windscreen	\$100.00
Gum	\$50.00
To Check Wiring System	\$6.00
Tuff kote	\$120.00
Panel beating	\$800.00
Spray painting	\$800.00

Subtotal :-	\$1,876.00
--------------------	-------------------

Total:-	\$6,855.70
----------------	-------------------