

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Milah Yeo

Date: 12 Apr 2019

## Preliminary Advice

Vehicle No	: SKR7813A	Accident Date	: 04/04/2019
Make	: PORSCHE PANAMERA	Policy No.	: 28727824MPP
Assignment Date	: 11/04/2019	Excess	: S\$0.00
Date of Inspection	: 12/04/2019	Est. Duration of Repair	: -
Inspection At	: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru Singapore 609025		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages caught fire.

Repairer's Estimate (Gross)	: \$	TOTAL LOSS
Revised Amount	: \$	TOTAL LOSS
Check Items (Estimated)	: \$	0.00
Total	: \$	TOTAL LOSS
Lump Sum Repair : \$		

### **Total Loss Consideration**

New for Old Value	: \$	
Pre-Accident Value	: \$	\$ 105,000.00
COE / PARF Rebate	: \$	\$ 67,132.00
Salvage Value	: \$	
Margin for Repair	: \$	\$ 37,868.00

### Remarks

( X ) The vehicle is not economical for repair. Vehicle recommended total loss. Pending investigation.

( ) The above survey was conducted on a 'without prejudice' basis.