

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref

: S9M01J58

Date: 16th April 2019

Our Ref

: CS/ASM19006487/T1vd3s2

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01 AXA Tower Singapore 068811 (The Motor Claims Department)

Attn; Jas Tan

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGQ 3468S ACCIDENT ON 02/04/2019

Instruction was received to inspect the vehicle Reg. No. SGQ 3468S. The inspection was conducted on 11/04/2019 at the premises of M/s Performance Motors Ltd, 303 Alexandra Road Singapore 159941.

The following vehicle information was recorded:

Registration Number

: SGQ 3468S

Make/Model

: B.M.W. 740LI

Year of Registration

: 2012

Body Colour

: White

Chassis Number

: WBAKB42030CY84079

Engine Capacity

: 2979 cc

Speedometer Reading

: 95093 km

The vehicle sustained damages at the o/s and n/s body and undercarriage. The undercarriage affected due to collision. The Estimated repair cost of such vehicle is S\$101,886.96 (Sin Dollars: One Hundred One Thousand Eight Hundred Eighty-Six and Ninety-Six Cents only.) (Include check items S\$5,596.25Nett) (Details see photographs enclosed)



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

In view of this repair work, we are of the opinion that it would be uneconomical to proceed with the repairs and recommend it's to be written off as "uneconomical Total Loss".

(a)	If the vehicle to be "Total Loss"
	Market Value

S\$ 110,000.00

Less: LTA Reimbursement Value (RV)

69,332.00)

Nett Liability

S\$ 40,668.00

> S\$ 40,668.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) (Include check items S\$5,596.25Nett) S\$ 101,886.96

Nett Liability

101,886.96 S\$

(a) - (b) =

(S\$ 61,218.96)

The amount of estimated saving of \$\$61,218.96 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust),MBA(UK), IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA),

AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.