

SJE : \_\_\_\_\_  
 Date of Survey : \_\_\_\_\_  
 Date of ReSurvey: \_\_\_\_\_ **After-Paint:** \_\_\_\_\_  
 Contacts : \_\_\_\_\_

Vehicle Nos : **SFE 9119K**  
 Model : \_\_\_\_\_  
 Year : \_\_\_\_\_  
 Chassis No : \_\_\_\_\_

**Supplementary Report**

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_

Working Day: \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bonnet	1	\$ 1,850.00	\$ <del>1,850.00</del>
2	Headlamp bracket LH	1	\$ 388.50	\$ ✓ 388.50
3	Bonnet Lock assy	1	\$ 328.50	\$ ✓ 328.50
4	Air intake duct	1	\$ 62.60	\$ 62.60
5	Head lamp nozzle	1	\$ 138.40	\$ ✓ 138.40
6	Head lamp nozzle bracket	1	\$ 36.70	\$ ✓ 36.70
7	Head lamp nozzle cover	1	\$ 28.10	\$ ✓ 28.10
<b>Amt</b>				\$ 2,832.80
5% <b>Discount(5.00%)</b>				\$ 141.64
<b>Subtotal</b>				\$ 2,691.16

BT RX  
 BR ✓  
 BT ✓  
 BA ✓  
 BR ✓  
 BR ✓  
 BR ✓

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_