

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
GST:201006949C RCB NO:201006949C

not Authorized  
27/5/19  
The Auto Attorney  
Hohy.  
8/5 44501

M/S : FABIAN ANG GUO YANG  
BLK 132 GEYLANG EAST AVENUE 1 #09-241  
SINGAPORE 380132

Estimate No: EST1504752  
Date: 10 Apr 2019  
Policy No: PNPV2019-00004861  
Veh Reg No: SKH4226S  
Make/Model: MERCEDES BEN C 180  
BLUEEFFICIENCY  
Chassis No: WDD2040312A784948  
Engine No: 27491030021495  
Reg. Date: 06/12/2012

ATTN: LONPAC

Your Ref No: TP 0419-5476  
Claim Type: Third Party  
Accident Date: 10/04/2019  
TP Veh Reg No: SCV 129 L

## Estimate Repair Cost to Vehicle No :SKH4226S

| Description                                                                         | U/Price  | Quantity | Price<br>S\$ | Amount<br>S\$ |
|-------------------------------------------------------------------------------------|----------|----------|--------------|---------------|
| <b>List Price</b>                                                                   |          |          |              |               |
| 1 REAR BUMPER W/TOWING COVER <del>W/T</del>                                         | 1,442.00 | 1 PC     | 1,442.00     | ✓             |
| 2 REAR BUMPER SIDE HOLDER - LH, RH                                                  | 39.00    | 2 PCS    | 78.00        | X             |
| 3 REAR BUMPER CLIPS                                                                 | 6.00     | 10 PC    | 60.00        | ✓             |
| 4 REAR BUMPER LOWER GARNISH                                                         | 0.00     | 1 PC     | 0.00         | X             |
| 5 REAR BUMPER REINFORCEMENT                                                         | 720.00   | 1 PC     | 720.00       | ✓             |
| 6 REAR BUMPER FOAM                                                                  | 0.00     | 1 PC     | 0.00         | X             |
| 7 REAR BUMPER INNER FRAME - LH, RH                                                  | 73.00    | 2 PCS    | 146.00       | ✓             |
| 8 REAR BUMPER INNER FRAME - CENTRE                                                  | 145.00   | 1 PC     | 145.00       | ✓             |
| 9 REAR BUMPER CHROME MOULDING - LH                                                  | 142.00   | 1 PC     | 142.00       | ✓             |
| 10 REAR BUMPER CHROME MOULDING - RH                                                 | 142.00   | 1 PC     | 142.00       | ✓             |
| 11 REAR BUMPER CHROME MOULDING - CENTRE                                             | 202.00   | 1 PC     | 202.00       | ✓             |
| 12 REAR BUMPER UNDER LOWER GARNISH                                                  | 50.00    | 1 PC     | 50.00        | X             |
| 13 REAR BOOT MER LOGO                                                               | 52.00    | 1 PC     | 52.00        | ✓             |
| 14 REAR BOOT C180 WORDING                                                           | 86.00    | 1 PC     | 86.00        | ✓             |
| 15 REAR BOOT 7G-TRONIC WORDING                                                      | 86.00    | 1 PC     | 86.00        | ✓             |
| 16 REAR BOOT OUTER CHROME                                                           | 214.00   | 1 PC     | 214.00       | X             |
| 17 REAR PANEL                                                                       | 1,320.00 | 1 PC     | 1,320.00     | ✓             |
| 18 REAR PANEL TOP GARNISH                                                           | 124.00   | 1 PC     | 124.00       | ✓             |
|                                                                                     |          |          | 5,009.00     |               |
|                                                                                     |          | Less 10% | 500.90       | 4,508.10      |
| <b>Special Net</b>                                                                  |          |          |              |               |
| 19 REAR BUMPER SENSOR (4PCS)                                                        | 440.00   | 1 SET    | 440.00       | 250           |
|                                                                                     |          |          | 440.00       | 440.00        |
| <b>Labour</b>                                                                       |          |          |              |               |
| 20 TO KNOCK OUT DENTS, REAR BOOT, REAR PANEL, PANEL, REMOVE, REPLACE ACCIDENT PARTS | 600.00   | 1 JOB    | 600.00       | ✓             |
| 21 TO RESPRAY PAINT ON ACCIDENT PORTIONS                                            | 600.00   | 1 JOB    | 600.00       | ✓             |
| 22 TO CHECK WIRING                                                                  | 20.00    | 1 JOB    | 20.00        | ✓             |
| 23 TO REMOVE, REPLACE REAR BUMPER SENSOR                                            | 100.00   | 1 JOB    | 100.00       | 50            |
| 24 TO TUFF-KOTE                                                                     | 30.00    | 1 JOB    | 30.00        | ✓             |
| 25 TO REMOVE, REFIX REAR GARNISH                                                    | 80.00    | 1 JOB    | 80.00        | 60            |
|                                                                                     |          |          | 1,430.00     | 1,430.00      |

4416  
3974.4

5584.4

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
GST:201006949C RCB NO:201006949C

M/S : FABIAN ANG GUO YANG  
BLK 132 GEYLANG EAST AVENUE 1 #09-241  
SINGAPORE 380132

ATTN: LONPAC

Your Ref No: TP 0419-5476  
Claim Type: Third Party  
Accident Date: 10/04/2019  
TP Veh Reg No: SCV 129 L

Estimate No: **EST1504752**  
Date: 10 Apr 2019  
Policy No: PNPV2019-00004861  
Veh Reg No: **SKH4226S**  
Make/Model: MERCEDES BEN C 180  
BLUEEFFICIENCY  
Chassis No: WDD2040312A784948  
Engine No: 27491030021495  
Reg. Date: 06/12/2012

## Estimate Repair Cost to Vehicle No :SKH4226S

| Description          | U/Price | Quantity | Price<br>S\$ | Amount<br>S\$ |
|----------------------|---------|----------|--------------|---------------|
| Total                |         |          |              | S\$ 6,378.10  |
| Add GST @ 7%         |         |          |              | 446.47        |
| Total Amount Payable |         |          |              | S\$ 6,824.57  |

TOTAL: SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED TWENTY FOUR AND CENTS FIFTY SEVEN ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: