

ASSIGNMENT

REF: CS/FCI119006545/VS d3 | n2
quest of instruction

Assigned By

Marcus

ASSIGNMENT (Office)

aws

Person (Person)

Sithara

of

FCI

Date/Time

11:50am @ 12/4/19

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SKN9413D

Insured

SHC7042Y

at Workshop no

SME Motor

Tel

67476106

of

11caki Bulkit Ave G #02-15 Autobay

Policy No

Claim No

D19002424MPST

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

8/4/2019

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time

12:09pm @ 12/4/19

Person Contacted

ee ying

Vehicle IN /

OUT

Date/Time

Action/Instruction (—) Estimate

SKN9413B-X

SHC7042Y-C8/12119004556/R1sd3n2

Don: 9/3/19

17/04/19

@ 14:37 pm. revised PA to Sithara via email.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

FCI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKN9413Dat Workshop m/s sm

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 72k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 10% % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LIA 52608

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKN9413D Yr Regn: 7.14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Toyota harrier c.c. 1986Colour: purple A/C: Insured / Std / NI / NASp. Reading: 86815 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 25N 600015474Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65-R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 8/4/19 D.O.I. 16/4/19

Survey held at _____

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop orO/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

(* Note: new parts replacement, → check with marcus)
 Note: repayer want repair 2k
 26/4/19 Confirmed Repair sum \$ 2000 with AH yoy.
 (\$ 4,074.26 red - 67%)

RECEIVED 29 APR 2019

Date/Time, File Pass to?

29/04/191) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Survey Fee: 145Transportation: 50

) \$ + RS, \$ SI

) Photos 50) Others 33

TOTAL

278Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ 2000/- RF)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002424MFSH

Date: 17 April 2019

Our Ref: CS/FCI19006545/Usd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKN 9413D .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/04/2019 at the premises of M/s SME Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 6,074.26 .
Revised Estimate Amount (lump sum)	: S\$ 2,107.50 .
"Check" Items Amount	: S\$ 2,169.52 .
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 3 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	10-04-2019	Our Ref No. D19002424MFSH
Accident Date	08-04-2019	Claim Type. Third Party
Insured Vehicle	SHC7042Y	Third Party Vehicle. SKN9413B
Survey Location	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY @ KAKI BUKIT	
Contact Person.	PEI YING	
Contact No.	67476106/ 0	Fax No. 67442368
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SME MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 17 April 2019 2:37 PM
To: 'Sithara'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19002424MFSH/1
Attachments: SKN 9413D - Preli Advise.pdf

Dear Sithara,

Enclosed preliminary revised of vehicle SKN 9413D.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 12 April 2019 12:14 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002424MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 12 April 2019 11:18 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002424MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6A



2.88% P.A. Low Interest@GV
Finance. 2 Years Warranty.
\$2000 Down Monthly From \$568
GV Credit Pte Ltd - StarAd



VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

VIEW OUR CARS

Browse by Category

Sort by Date Posted 20 results/page

2 vehicles

Toyota Harrier

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Harrier		Any	Any	2014	Any	Any	Any	Available
	Toyota Harrier	2.0A Elegance Panoramic	\$74,800	\$11,990 /yr	16-Jul-2014	1,986 cc	63,000 km	SUV	Available
Flawless Pearl White Harrier Just Arrived. 1 Owner And At It Ultimate Best Condition. Upgraded Rims With Almost New Tyres. 100% Accident Free. Nicely Taken Care By Owner. STA Welcome. View To Believe. ... Starise Automobile Posted: 10-Apr-2019 Tags: 2014 Toyota Harrier, 2014 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota Harrier	Hybrid 2.5A	\$94,800	\$13,430 /yr	23-Sep-2014	2,493 cc	-	SUV	Available
Fuel Type: Petrol-Electric Elegant White, Powerful Drive With 194 BHP, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Flexible In-House Loan Packages Available. Prime Motor & Leasing Posted: 24-Mar-2019 Tags: 2014 Toyota Harrier, 2014 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Harrier, Toyota Harrier Singapore, used Toyota Harrier Singapore, used Toyota Harrier, used vehicles Singapore or even buy used Toyota Harrier Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 0963A

Vehicle Details

Vehicle No.: SKN9413D

Vehicle to be Exported: No

Intended Deregistration Date: 16 Apr 2019

Vehicle Make: TOYOTA

Vehicle Model: HARRIER 2.0 ELEGANCE SUNROOF

Primary Colour: Black

Manufacturing Year: 2014

Engine No.: 3ZRB386264

Chassis No.: ZSU600015474

Maximum Power Output: 111.0 kW (148 bhp)

Open Market Value: \$29,074.00

Original Registration Date: 31 Jul 2014

First Registration Date: 31 Jul 2014

Transfer Count: 0

Actual ARF Paid: \$22,704.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Jul 2024

PARF Rebate Amount: \$17,028.00

Intended COE Rebate Details

COE Expiry Date: 30 Jul 2024

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$67,290.00

COE Rebate Amount: \$35,580.00

Total Rebate Amount: \$52,608.00

The information contained herein is correct as at 16 Apr 2019

OK

LETTER OF UNDERTAKING

I/We, Lim Eileen, the owner of vehicle no. 8CN 9413D

My/Our Insurance is under M/s AXA Insurance Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Pte Ltd with all relevant facts and documents **within 14(fourteen) days of occurrence or discovery of damage.**

My/Our Third Party claim is handle by my/our preferred workshop, 3M15 MOTOR PTE LTD

Signed and Acknowledge by:

87040963A Eileen

Nric no. & signature of policyholder

Company stamp

8 Apr 2019

Date

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

not Authorized
Mark
16/4/19
Wheights Suburgary
3 dy.

M/S: MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 19/FC/TP-066 (04)

Claim Type: Third Party

Accident Date: 08/04/2019

TP Veh Reg No: SHC7042Y

Estimate No: EST0004790

Date: 09 Apr 2019

Policy No: P1525750

Veh Reg No: SKN9413D

Make/Model: TOYOTA HARRIER

Chasis No: 0

Engine No:

Reg. Date:

Estimate Repair Cost to Vehicle No :SKN9413D

Description	Quantity	List Price	Amount
		SS	SS
List Price			
1 REAR BUMPER	1 PC	1,700.00	✓
2 REAR BUMPER RETAINER (RH)	1 PC	80.00	X
3 REAR BUMPER CLIP	10 PC	50.00	✓
4 REAR RH SPORT RIM	1 PC	2,892.70	✓
5 REAR RH SHOCK ABSORBER	1 PC	145.90	✓
6 REAR RH KNUCKLE ARM	1 PC	396.40	✓
7 REAR RH KNUCKLE BEARING	1 PC	737.60	✓
8 REAR RH LOWER ARM	1 PC	396.40	✓
		6,399.00	
	Less 25%	1,599.75	4,799.26
Special Net			
9 REAR RH TYRE	1 PC	280.00	✓
		280.00	280.00
Labour			
10 WIRE CHECKING	1 UNIT	30.00	20
11 REMOVE & REFIX REAR UNDERCARRIAGE	1 UNIT	200.00	X
12 4 WHEEL ALIGNMENT	1 UNIT	65.00	✓
13 LABOUR CHARGE	1 UNIT	300.00	✓
14 SPRAY PAINTING	1 UNIT	400.00	✓
		995.00	995.00
		Total	SS 6,074.26
		Add GST @ 7%	425.20
		Total Amount Payable	SS 6,499.46

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FOUR HUNDRED NINETY NINE AND CENTS FORTY SIX ONLY

LKK Auto Consultants hereby notify
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repainter
Signature
Date

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

2286.32
102



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19006545/Usd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7042Y	Veh. Inspected	SKN 9413D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002424MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	12/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	ZSU600015474	Colour	PURPLE	
Odometer	86815	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	GOODYEAR	7 mm	
L/H Front Tyre	225/65 R17	GOODYEAR	7 mm	
R/H Rear Tyre	225/65 R17	GOODYEAR	7 mm	
L/H Rear Tyre	225/65 R17	GOODYEAR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/04/2019	Inspection Date	16/04/2019	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 9413D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEEP CUT	1,700.00	1,685.10
1	REAR BUMPER RETAINER (RH)	NOT NECESSARY	80.00	-
10	REAR BUMPER CLIP	NECESSARY	50.00	50.00
1	REAR RH SHOCK ABSORBER	NOT NECESSARY	145.90	-
1	REAR RH KNUCKLE ARM	NOT NECESSARY	396.40	-
1	REAR RH KNUCKLE BEARING	NOT NECESSARY	737.60	-
1	REAR RH LOWER ARM	NOT NECESSARY	396.40	-
	LESS 25% DISCOUNT		-876.58	-433.78
			2,629.72	1,301.32
1	REAR RH SPORT RIM (LOCAL REPAIR)(SN)	CUT	2,892.70	200.00
	LESS 25% DISCOUNT		-723.18	-
			2,169.52	200.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR RH TYRE (SN)	SERVICEABLE	280.00	-
			280.00	-
	<u>LABOUR</u>			
	WIRE CHECKING.		30.00	20.00
	REMOVE & REFIX REAR UNDERCARRIAGE.	NOT NECESSARY	200.00	-
	4 WHEEL ALIGNMENT.		65.00	65.00
	LABOUR CHARGE.		300.00	300.00
	SPRAY PAINTING.		400.00	400.00
			995.00	785.00
	GRAND TOTAL		6,074.24	2,286.32
	RECOMMENDED COST OF REPAIR SUM			2,000.00

Report Ref No. CS/FCI19006545/Usd3n2

NOTE: NEW PARTS REPLACEMENT*CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.