

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 23/04/2019

Survey Details:

Date of loss	7-Apr-19
Date of appointment	11-Apr-19
Date of survey	11-Apr-19
Location of survey	NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLT 7205H
Make and Model	TOYOTA HARRIER 2.4GL A
Date of registration	30-Aug-13
Excess	\$700
Market Value	\$65,000
Parf Rebate	\$31,485
Nett Loss	\$33,515

Repair details:

Initial Estimate	7,367.44 (inclusive supplementary)
------------------	------------------------------------

Proposed/Revised repair cost:

Parts	\$3,241.50 (inclusive supplementary)
Check items (estimate)	\$1,956.10
Labour	\$1,263.03
Total	\$6,460.63
Lump Sum(if applicable)	\$

Number of days for repair	<u>4 DAYS</u>
----------------------------------	----------------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL.
KINDLY LET US HAVE YOUR APPROVAL OF
SUPPLEMENTARY AMOUNT IS \$ 90.20. WE HAVE NOT
AUTHORIZE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	