

CASE OWNER:

CC 3, 11/16 1900 6564, P1 KAS/v

LKK:
IDAC:

Signature:

RASUL

DOI:

ASSIGNMENT

16/5/19

Date / Time:

17/4/19

Registered in Merimen:

17/4/19

Pre-assign / CCU / FTE

SKN 22586



Insured Vehicle No.:

Claim No.:

Name of Insured:

PINA CAN (H)

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

7/4/19

Place of Accident:

Is driver the owner?

(YES) / NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SKP 406 m



INSRS:

WSP:

Tel:

Liability:

RMKS:

pmc



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

16/4
16/4/19

16/4/19 - x, SKN 22586 - x

16/4/19
4:10pm
- Khanchua- spoken to OI she confirmed the NVC
informed OI on TP claim and quote NCD
will be affected. Sent letter to OI.17/4/19
Khanchua

- File pass to type mandate.

6/11/19
Khanchua

File pass to mei kwan to close

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

RP SS 9,572.70 5 days) Reduction: 14 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with Caroline

Email ☒ Call ☐

Final Liability:

100 (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: (41459)

SS 10,242.79

COI CHANGED NAME

Loss of Rental (LOR):

SS - (- days)

Loss of Use (LOU):

SS 550 (\$ 10 x 5 days)

Loss of Income (LOI):

SS - (\$ - x days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 10,794.79

Global Sum SS:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

JP \$320

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 10,794.79

Name 1:

PERFORMANCE MOTORS LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Signature: *[Signature]*

REF: A19

65641 P1(h)

6380c

ASSIGNMENT

From: Date: 16.5.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 406M

at Workshop m/s Performance motor

of 303 Alexandra Road

Insured:

Policy No

Claims No.

Sum Insured


Excess:

(Client's Record)

Make of Veh: Inthiran Thurasamy

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: 1/1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

my?

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKR 406M Yr Regn: 2017 JULY

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W X4 XDRIVE 20i c.c 1997

Colour: Gold A/C: Insured / Std / NI / NA

Sp. Reading: 43680 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA XW 1206 00V 44 791

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / R/Rim / STD A/Rim or

Tyre Size: F: 245/50R18 R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal: 6 mm L/Bal: 6 mm

D.O.A. 07/04/19 D.O.I. 16/05/19

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or 0/3 Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

(P/P \$ 9,572.70 / Red \$ 1,535.25 / 14%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

3 + RS. 51

Photos

Others

TOTAL

Report Format :

Lump Sum / L.B.I: (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Kanchan

Survey & rep
16.05 @ 10am
LKK VIC

Performance Motors Limited

A Siew Derby Motors Company
Co. Reg. No. 197401109K GST Reg. No. M2-0020081-X
Toll-Free Number: (1800-2251249)311, Alexandra Road
Siew Derby Business Centre
Singapore 119941
Fax: 64747770290, Karpong Aseag Road
East Coast Centre
Singapore 438181
Fax: 63449775311, Alexandra Road
Siew Derby Business Centre
Singapore 119941
Fax: 64796601 (AfterSales)
64796624 (Motors)

GST REG. NO : M2 - 0020081 - X

12 APR 2019

E S T I M A T E

Estimate No. : b1 50825
Date Estimated : 11/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Manokaran S/O Mookkayyah
290G Bukit Batok Street 24
#05-91

Singapore 656290

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR406M	OV44791	03/07/2017	X4 xDrive20i	0

DESCRIPTION

To replace front bumper, fender right and attachments

Painting front bumper and fender right.

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.To carry out body cavity preservation.
(Per panel).

To replace right headlight.

To carry out body cavity preservation.
(Per panel).

Sundries.

VALUE

1700 2580.00

1996 2218.00

150 122.00

100 118.00

408 401.00

nn reported X 118.00

80.00

Total Labour 1: 5,742.00

DESCRIPTION

CLIP BEIGE *an X11 1.10*
RH GRILLE SIDE CLOSED *1.10*
GRID LATERAL RH (X LINE) *1.10*
CLADDING BUMPER FRT (PDC/SCHWARZ) *sea*
CLIP *an*
FRT RH WHEEL ARCH COVER *sea*
RH BI XENON HEADLIGHT *sea*

QTY	PRIC	VALUE
6	1.10	6.60
1	107.75	107.75
1	112.90	112.90
1	315.70	315.70
6	2.00	12.00
1	179.75	179.75
1	2,437.65	2,437.65

Total Parts : 3,172.35

T Super (Painted) *sea*

Performance Motors Limited

A Sime Darby Motors Company
Co Reg No: 13742159M GST Reg No M2-052081-X
Toll Free Number: 1800-2255243



111, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

191, Raffles Place
East Coast Centre
Singapore 458180
Fax: 61445773

111, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64746671 (ATTENTION: MOTORING)
64746624

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50825
Date Estimated : 11/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR406M	OV44791	03/07/2017	X4 xDrive20i	0

LKK Auto Consult will hence notify the Repairs of the following:

- Repairs to be carried out by the company
- To be carried out by the company
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modifications is allowed
- Supplementary item(s) must be reviewed and is subject to final approval from Insurance Company

Authorised by Person:
Signature:
Date:

16/05/19 14/10
Rasul
90010068
5 days

Labour 1	5,742.00
Parts	3,172.35
Labour 2	0.00
Excess	0.00
Total GST @ 7%	624.00
Grand Total	9,538.35

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19140359W, GST Reg. No. M2-000001-X



FINAL REPORT

Estimate No. : b1 50825
Date Estimated : 11/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Manokaran S/O Mookkayyah
290G Bukit Batok Street 24
#05-91

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 656290

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR406M	0V44791	03/07/2017	X4 xDrive20i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, front RH fender, front RH wheel arch cover include knocking out dents caused by the accident.	1700.00		1,700.00	✓
To spray paint front bumper and front RH fender	1996.00		1,996.00	✓
To check electrical wiring systems at the front section for proper function	150.00		150.00	✓
To carry out body cavity preservation (Per panel)	100.00		100.00	✓
To replace RH bi xenon headlight include programming and conducting tests for proper function	408.00		408.00	✓
Sundries	80.00		80.00	✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT RH FENDER *	804.50	1.00		804.50 (1)
CLADDING BUMPER FRT (PDC/SCHWARZ)	315.70	1.00		315.70 ✓
# FRT BUMPER PANEL PRIMED *	1,362.10	1.00		1,362.10 (3)
CLIP	2.00	6.00		12.00 ✓
# EXPANDING RIVET *	1.35	20.00		27.00 (4)
FRT RH WHEEL ARCH COVER	179.75	1.00		179.75 ✓
RH BI XENON HEADLIGHT	2,437.65	1.00		2,437.65 ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,434.00
Total Parts :	5,138.70
Total Labour & Parts :	9,572.70
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,572.70
GST @7%:	670.09
Grand Total :	10,242.79

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-A



SUPPLEMENTARY

Estimate No. : b1 50825
Date Estimated : 11/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Manokaran S/O Mookkayyah
290G Bukit Batok Street 24
#05-91

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 656290

REGN. NO	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR406M	0V44791	03/07/2017	X4 xDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT RH FENDER • <i>bf</i> /	804.50	1.00		804.50
# FRT BUMPER PANEL PRIMED • <i>Dent</i> /	1,362.10	1.00		1,362.10
# EXPANDING RIVET • <i>rm</i> /	1.35	20.00		27.00

Total Labour :	0.00
Total Parts :	2,193.60
Total Labour & Parts :	2,193.60



SUPPLEMENTARY

Estimate No. : b1 50825
Date Estimated : 11/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Manokaran S/O Mookkayyah
290G Bukit Batok Street 24
#05-91

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 656290

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR406M	0V44791	03/07/2017	X4 xDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT RH FENDER *	804.50	1.00	N/A	804.50 ✓
# FRT BUMPER PANEL PRIMED *	1,362.10	1.00	N/A	1,362.10 ✓
# EXPANDING RIVET *	1.35	20.00	N/A	27.00 ✓

Total Labour :	0.00
Total Parts :	2,193.60
Total Labour & Parts :	2,193.60

Khanchna (LKK Auto)

From: Rasul (LKKAuto)
Sent: Friday, 5 July 2019 9:47 AM
To: PBSP
Cc: Khanchna (LKK Auto)
Subject: RE: FINAL REPORT/ SKR406M

Hi Caroline,

Finalised amount confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 28 June, 2019 5:01 PM
To: Khanchna (LKK Auto); Rasul (LKKAuto)
Subject: FINAL REPORT/ SKR406M

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,434.00

Total Parts : 5,138.70

Total Labour & Parts : 9,572.70

Repair days: 5

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 187401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

309, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

12 APR 2019

E S T I M A T E

Estimate No. : b1 50825 Page No. : 1 of 5
Date Estimated : 11/04/2019
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -
Manokaran S/O Mookkayyah
290G Bukit Batok Street 24
#05-91

Singapore 656290

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR406M	0V44791	03/07/2017	X4 xDrive20i	0

DESCRIPTION

To replace front bumper, fender right and attachments.

VALUE

1700 ~~2580.00~~

Painting front bumper and fender right.

1996 ~~2218.00~~

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 ~~172.00~~To carry out body cavity preservation.
(Per panel).100 ~~118.00~~

To replace right headlight.

408 ~~481.00~~To carry out body cavity preservation.
(Per panel).

replaced X 118.00

Sundries.

80.00

Total Labour 1: 5,742.00

DESCRIPTION

CLIP BEIGE *sa*
RH GRILLE SIDE CLOSED *?*
GRID LATERAL RH (X LINE) *?*
CLADDING BUMPER FRT (PDC/SCHWARZ) *sa*
CLIP *sa*
FRT RH WHEEL ARCH COVER *sa*
RH BI XENON HEADLIGHT *sa*

QTY	PRIC	VALUE
6	1.10	6.60
1	107.75	107.75
1	112.90	112.90
1	315.70	315.70
6	2.00	12.00
1	179.75	179.75
1	2,437.65	2,437.65

Total Parts : 3,172.35

Put Super (Primed) sa

Performance Motors Limited

A/Sine Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



103, Alexandra Road
Sine Darby Performance Centre
Singapore 159941
Fax: 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63448773

315, Alexandra Road
Sine Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 50825
Date Estimated : 11/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR406M	0V44791	03/07/2017	X4 xDrive20i	0

LKK Auto Consultant, hence notify
the Reparer of the following:
• To reserve (padding) for spray painting
• To display damaged part(s) during recovery
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be reserved as it
is subject to final approval from Insurance Company

Acknowledged by Reparer:

Signature:

Date:

Choose OO (Ord Party / Uninsured losses / Direct Settlement)

Sign No. _____ Claim No. _____

Desk Time 16/05/19 @ 1410 Excess \$S _____

Surveyor's Name Rabul Sign _____

Surveyor's Tel 90010068 Authorized Yes / No _____

Surveyor's Title _____ Time _____

PLEASE ATTACH PHOTO BY SURVEYOR Yes / No Yes / No

Surveyor's E-mail _____

No. of Working Days Recommended 5 days

Labour 1	:	5,742.00
Parts	:	3,172.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	624.00
Grand Total	:	<u>9,538.35</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Claim Audit

AUDIT TRAIL

1	12 Apr 2019 16:49	Cim Dtl Modified	Claimant's Name: -> MANOKARAN S/O MOOKKAYAH. Claimant's ID: -> 51406380 C.	[A] HOW MEI KWAN
2	12 Apr 2019 16:49	Cim Veh Model Changed	(204188) BMW X4 2.0 xDrive20i (A).	[A] HOW MEI KWAN
3	12 Apr 2019 16:49	Cim Created	Reg No: SKR406M, Acct Date: 2019/04/07, Claim Type: TP, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Performance Motors Limited (Alexandra)	[A] HOW MEI KWAN
4	12 Apr 2019 16:49	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	12 Apr 2019 16:49	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2019/04/24	[A] HOW MEI KWAN
6	12 Apr 2019 16:49	Adj Mandate Set	Approved: 8000.00, Reinsp: Adj decides.	[A] HOW MEI KWAN
7	12 Apr 2019 16:49	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	12 Apr 2019 16:52	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] HOW MEI KWAN
9	25 Apr 2019 14:47	Label Added	(23): Express.	[A] HOW MEI KWAN
10	21 May 2019 09:10	Adj Adjuster Assigned	MOHD TAUFIKH BIN HAMID -> MOHD RASUL	[A] HOW MEI KWAN
11	23 Sep 2019 14:56	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
12	23 Sep 2019 14:56	Cim Dtl Modified	JPJ Reg. Date: -> 2017/07/03.	[A] JOANNE LEE KHANG MIN
13	23 Sep 2019 14:56	Cim Details Notified		[A] JOANNE LEE KHANG MIN
14	23 Sep 2019 16:40	Adj Mandate Request	Cur.Req: 10844.79; Liability: 100%; BOLA 15 (OI changed lane). 5 days recommendation for repair.	[A] Khanchna Pothuraj

Date From



Date To



Audit Type None

Go

ACTIVITY

[16/04/2019 12:13] Khanchna Pothuraj:
 16/4/2019 @12.10PM Spoken to OI (Ms. Phua Lan Shi -93366180). She confirmed the mva.
 Informed OI on TP claim and aware NCD will be affected. Sent letter to OI.

Merimen Billing for this case - Transaction History

2288478	23 Sep 2019 14:56:51	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKR406M	SKN2258G	11.77
---------	----------------------	-----------------------	-------	------------------------------	-----------------------------------	---------	----------	-------

✓ to offer

Khanchna (LKK Auto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 5 November 2019 2:16 PM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: Re: LOD REMINDER - SKR406M & SKN2258G ON 07/04/2019 *** LKK REF: CC3/AIG19006564/R1ka3

Dear Khanchna

We have instructions to accept your revised offer for LOU.

Please proceed with payment.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Sent: Tuesday, 5 November 2019 1:54 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: 甯瑤 @ <admin-a@lkkauto.com>
Subject: RE: LOD REMINDER - SKR406M & SKN2258G ON 07/04/2019 *** LKK REF: CC3/AIG19006564/R1ka3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter and your e-mail below.

For amicable settlement on a without prejudice basis, we propose settlement as follows:

1. Cost of Repair	\$ 10,242.79
2. Loss of Use (5 days x \$110.00)	\$ 550.00
3. LTA Search Fee	\$ 2.00
TOTAL	\$ 10,794.79

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 5 November 2019 1:54 PM
To: PBSP
Cc: Admin A
Subject: RE: LOD REMINDER - SKR406M & SKN2258G ON 07/04/2019 *** LKK REF: CC3/AIG19006564/R1ka3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter and your e-mail below.

For amicable settlement on a without prejudice basis, we propose settlement as follows:

1. Cost of Repair	\$ 10,242.79
2. Loss of Use (5 days x \$110.00)	\$ 550.00
3. LTA Search Fee	\$ 2.00
TOTAL	\$ 10,794.79

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Tuesday, 5 November 2019 1:40 PM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: LOD REMINDER - SKR406M & SKN2258G ON 07/04/2019 *** LKK REF: CC3/AIG19006564/R1ka3

URGENT REMINDER - Mandate already approved???



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19006564/HA3

16 APRIL 2019

PHUA LAN SHI
12A CANBERRA DRIVE
#02-26
SINGAPORE 768095

Dear Sir/Madam,

**ACCIDENT INVOLVING SKN2258G & SKR406M ALONG/AT YISHUN CENTRAL 1
ON 07/04/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SKR406M against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

KHANCHNA
Case Handler
DID: 6841-2360
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

Khanchna (LKK Auto)

From: Rasul (LKKAuto)
Sent: Friday, 24 May 2019 2:44 PM
To: PBSP
Cc: Joy Irene (LKKAuto)
Subject: RE: FINAL REPORT SLQ8452U

Hi Caroline,

Finalised amount confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Wednesday, 22 May, 2019 6:20 PM
To: Rasul (LKKAuto); SUR; Joy Irene (LKKAuto)
Subject: FINAL REPORT SLQ8452U

Dear Sirs,

We refer to the above and attached Final Report .

Please confirm COR as follow :

Total Labour : 2,014.00
Total Parts : 1,137.90
Total Labour & Parts : 3,151.90

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named-addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

This mail is associated with :

MANOKARAN S/O MOOKKAYYAH
Apr 7 2019 2:00PM
[PHUA LAN SHI]
Performance Motors Limited

Send

Sender LKK_HQ

Urgent Mail

(Case Directory) AIG Asia Pacific Insurance Pte. Ltd. <AIG_SG>

(External E-mail Directory) Foo, Chit Yan <Chityan.Foo@aig.com>

CC

Add Ext

Add Ext

Subject: Fw: Alert - Adj Mandate Approved (S\$10794.79) - SKR406M - Claim Handler: Foo, Chit Yan

Previous Attachments :

There are no attached documents.

<-- Original Message -->

From: AIG SG EXPRESS

To: LKK HQ

Sent On: 03/11/2019 06:30 PM

Subject: Alert - Adj Mandate Approved (SS10794.79) - SKR406M - Claim Handler: Foo, Chit Yan

Approved: 10794.79: above mandate subject to Final Repair Bill, GIA/LTA Search Bill in order and solely for amicable settlement

body div br

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2003
(PAYMENT BREAKDOWN)**

Vehicle No:	SR406 M	Model:	BMW
Date of Accident:	7.4.2019		

Global Sum Settlement:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	: \$	11107.95	
Final Repair Cost	: \$	10242.79	
Loss of Use	: \$	600.00	5 days at \$ 120 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$	2.00	
Others	: \$		
	: \$		
Final Settlement Sum	: \$	10844.79	

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Application: Yes / No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown			
1)	Performance Motor Limited	: \$	10242.79
2)	Performance Motors Ltd	: \$	2.00
3)	Manokaran S/o Mookkayyah	: \$	600.00



Signed by appointed surveyor

6/4/19

Date

Please attach all the supporting documents to the form.

Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report / Bill (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19006564/HA3

16 APRIL 2019

PHUA LAN SHI
12A CANBERRA DRIVE
#02-26
SINGAPORE 768095

Dear Sir/Madam,

**ACCIDENT INVOLVING SKN2258G & SKR406M ALONG/AT YISHUN CENTRAL 1
ON 07/04/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SKR406M against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


KHANCHNA
Case Handler
DID: 6841-2360
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Manokaran s/o Mookkayyah ("the third party claimant")
of 290G Rt Batuk Street 24 #05-91 SC 656290 (address),
owner of SKR 406 M (vehicle no.) hereby authorize
Performance Motors Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKR 406 M that was
damaged pursuant to the accident which occurred on 7.4.2019 (date) along
Yishun Central 1 (location)
involving vehicle no/s SKN 2258G ("the accident").


I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.


Date this 16 day of 5 (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"





LETTER OF AUTHORISATION

ACCIDENT INVOLVING SKR 406M & SKN 2258G ON 7-04-2019.

I, Manokaran S/O Mookkayyah owner of Vehicle Registration No. SKR 406M hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.


I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:

Name : M. Manokaran (Date) 8/4/19
NRIC No.: S140638012

In the presence of:

Name : _____ (Date) 8/4/19
NRIC No.: _____



RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 10242.79 (repair costs), S\$ 550.00 (loss of use/rental) S\$ 2.00 (search fees) for vehicle no. SKR406M that was damaged pursuant to the accident which occurred on 7-2-2019 (date) along Vishnu Central 1 (location) involving vehicle no/s SKN22586.

This is pursuant to the inspection conducted on 16-5-2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Manokaran S/o Mookkayath ("third party claimant") of vehicle no. SKR 406M to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKR 406M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 06 day of 11 (month) 20 19 (year)



MPB

Signed by AIG appointed surveyor

[Signature]

Chopped & Signed by "the workshop"

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Serpong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449777313, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/310 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1362881

Date IN : 16/05/2019

Cust. Svc. Advisor: Inthiran A/L Thurasamy

Page No. : 1 of 2

Invoice Number : 2122116 / WSB

Invoice Date : 10/07/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Manokaran S/O Mookkayyah
290G Bukit Batok Street 24
#05-91

Singapore 656290

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120REGN. NO
SKR406MCHASSIS NO.
0V44791REGN. DATE
03/07/2017MODEL
X4 XDRIVE20IMILEAGE
43680

- - - - LABOUR 1 - - - -

To replace front bumper, front right fender and front right
wheel arch cover etc including to remove and install body
parts in order to carry out painting job.

To respray front bumper and front right fender.

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

To carry out body cavity preservation.

To replace right B1-Xenon headlight.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 7.4.2019. 3RD PARTY CAR : SKN2258G.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RUSAL FROM LKK AUTO
CONSULTANTS PTE LTD ON 16.5.2019 AT 2.10 PM.
AUTHORISED REPAIR BY KHANCHNA FROM LKK ON 25.4.2019
VIA E-MAIL.PROPOSE LOSS OF USE = \$120X5. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

NETT

1,700.00

1,996.00

150.00

100.00

408.00

80.00

0.00

0.00

0.00

Total Labour 1: 4,434.00

- - - - PARTS - - - -

FRT RH WHEEL ARCH COVER

CLIP

RH BI XENON HEADLIGHT

FRT RH FENDER

EXPANDING RIVET

CLADDING BUMPER FRT (PDC/SCHWARZ)

FRT BUMPER PANEL PRIMED

Qty Retail
Price

1 179.75

6 2.00

1 2,437.65

1 804.50

20 1.35

1 315.70

1 1,362.10

NETT

179.75

12.00

2,437.65

804.50

27.00

315.70

1,362.10

Total Parts : 5,138.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020001-x



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438160
Tel: 63190888 (AfterSales)
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64794601 (AfterSales)
64794624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1362881	Page No. : 2 of 2
Date IN : 16/05/2019	Invoice Number : 2122116 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 10/07/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Labour Charges :	4,354.00	Total Labour & Parts Charges :	S\$ 9,572.70
Parts Charges :	5,138.70	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	80.00	Invoice Total Amount Exclude GST :	S\$ 9,572.70
		GST @ 7% :	S\$ 670.09
		Invoice Total Amount Include GST :	S\$ 10,242.79

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 10,242.79**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-057492

Date of Request: 12/04/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 12/04/2019
Enquiry By Melanie Setiawati
TP Vehicle No. SKN2258G
Accident Date 07/04/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKN2258G	AIG Asia Pacific Insurance Pte. Ltd.	04/04/2018-25/05/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-057492

Date of Request: 12/04/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 12/04/2019
Enquiry By Melanie Setiawati
TP Vehicle No. SKN2258G
Accident Date 07/04/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2019 Edit Reg		16 May 2019 00:00 Edit Adj Rpt	\$59,572.70 Edit Estimates	\$59,572.70 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	PHUA LAN SHI, ID: S74013972								
Main Claimant:	MANOKARAN S/O MOOKKAYAH, ID: S1406380C								
Vehicle Reg. No.:	SKR406M	Date of Loss:	07/04/2019 14:00 - :59 [21 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0212775000SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKN2258G	Policy No. (Claimant):	50920404724-01(PREMIUM)						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 24/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (03/11/2019): Alert - Adj Mandate Approved (\$10794.79) - SKR406M - Claim Handler: Foo, Chit Y...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKR406M (0212775000SG)
[SKN2258G]
TP
MANOKARAN S/O MOOKKAYYAH
Apr 7 2019 2:00PM
[PHUA LAN SHI]
Performance Motors Limited

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
2	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
3	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
4	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
5	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
6	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
7	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
8	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
9	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
10	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
11	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
12	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
13	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
14	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
15	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
16	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
17	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
18	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
19	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
20	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
21	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
22	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
23	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
24	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
25	23/09/19 16:41	General View		Load JPG	<input checked="" type="checkbox"/>
26	23/09/19 16:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	23/09/19 16:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	23/09/19 16:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	23/09/19 16:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	23/09/19 16:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	23/09/19 16:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	23/09/19 16:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	23/09/19 16:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	23/09/19 16:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	12/04/19 16:53	TP ESTIMATE + TP GIA REPORT		Load PDF	
2	16/04/19 12:13	LETTER TO OI		Load PDF	
3	22/05/19 07:47	TP ESTIMATE - MARKED		Load PDF	
4	23/09/19 16:28	GIA SEARCH		Load PDF	

Letters/Correspondences					1 per page	<input checked="" type="checkbox"/>
No	Finalized On				Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)						
5	11/11/19 11:23	WORKSHOP INVOICE			 Load PDF	
6	11/11/19 11:23	AUTHORISATION TO ACT FORM			 Load PDF	
7	11/11/19 11:23	Release Voucher			 Load PDF	
8	11/11/19 11:23	LOD			 Load PDF	
AIG Asia Pacific Insurance Pte. Ltd. (SG)						
No	Finalized On				Thumbnail	Print
1	15/04/19 09:50	OI GIA REPORT			 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p> Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> </p>
--

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKN2258G (Insd veh)	Model:	BMW X4 2.0 XDRIVE20i (A)
	SKR406M (TP veh)		
Date of Accident:	07/04/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	11,885.51
Final Repair Cost	:	\$	10,242.79
Loss of Use	:	\$	550.00
			5.00 days at \$110.00 per day
Rental (if any)	:	\$	0.00
			days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	10,794.79
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop : Agreed Liability _____ (%)			
B) For GIA Registered Workshop : BOLA Applicable: Yes/ No- BOLA Scenario No: _____			
BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 10,794.79
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

11 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19006564/R1KA3Q2

Date: 11/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SKR406M

Insured Vehicle No : SKN2258G

Date of Loss: 07/04/2019

Nature of Claim: TP

Claim No: 0212775000SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKR406M

Make & Model: BMW X4, 2.0 xDrive20i (A)

Engine No: A5991657N20B20A

Reg. Date: 03/07/2017 (Man. Year: 2017)

Chassis No: WBAXW120600V44791

Colour: Gold

Odometer: 43680 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R18

Rear Tyre Size:

245/50 R18

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,445.95	5,218.70	227.25	4.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,662.00	4,354.00	1,308.00	23.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,107.95	9,572.70	1,535.25	13.82
+ GST 7.00/7.00% (S\$)	777.56	670.09	107.47	13.82
Nett Amount (S\$)	11,885.51	10,242.79	1,642.72	13.82
+ Loss of Use (5.0 x S\$110.00/day) (S\$)		550.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,794.79		

INSPECTION

Date of Assignment: 16/05/2019

Date Inspected: 16/05/2019 Inspected At:

Performance Motors Limited

(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre

Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	6		*CLIP BEIGE	Not Necessary	6.60 FS	*- FS
3	1		*RH GRILLE SIDE CLOSED	Serviceable	107.75 FS	*- FS
4	1		*GRID LATERAL RH (X LINE)	Serviceable	112.90 FS	*- FS
5	1		*CLADDING BUMPER FRT (PDC/SCHWARZ)	Scratched	315.70 FS	*315.70 FS
6	6		*CLIP	Necessary	12.00 FS	*12.00 FS
7	1		*FRT RH WHEEL ARCH COVER	Scratched	179.75 FS	*179.75 FS
8	1		*RH BI XENON HEADLIGHT	Scratched	2,437.65 FS	*2,437.65 FS
9	1		*FRT RH FENDER	Bent	804.50 FS	*804.50 FS
10	1		*FRT BUMPER PANEL PRIMED	Dented	1,362.10 FS	*1,362.10 FS
11	20		*EXPANDING RIVET	Necessary	27.00 FS	*27.00 FS
Total Parts (S\$)					5,445.95	5,218.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER ,FENDER RIGHT AND ATTACHMENTS	New	2,550.00	1,700.00
2	PAINTING FRONT BUMPER AND FENDER RIGHT	New	2,218.00	1,996.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
5	TO REPLACE RIGHT HEADLIGHT	New	481.00	408.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	0.00
Gross Labour Cost (\$\$)			5,662.00	4,354.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >