

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

Not Authorised
Lkk Marcus
22/5/19
Wheeler. Atkinson
327.
1/5 1350

M/S : CHOO CHEE YONG
BLK 305A ANCHORVALE LINK #11-01
SINGAPORE 541305

Estimate No: EST1504746
Date: 09 Apr 2019
Policy No: MT111943
Veh Reg No: SJM5744S
Make/Model: NISSAN LATIO 1.5L AT
ABS D/AIRBAG 2WD
4DR

ATTN: QBE INSURANCE

Your Ref No: TP 0419-5473
Claim Type: Third Party
Accident Date: 08/04/2019
TP Veh Reg No: PC5400R

Chassis No: JN1BAAC11Z0020658
Engine No: HR15053470B
Reg. Date: 09/01/2009

Estimate Repair Cost to Vehicle No :SJM5744S

Description	U/Price	Quantity	Price SS	Amount SS
Net Price				
1 FRONT BUMPER	de/To.1 ner 456.30	1 PC	456.30	—
2 FRONT BUMPER CLIPS	ner 4.40	10 PC	44.00	—
3 FRONT BUMPER SIDE HOLDER - RH	17 23.00	1 PC	23.00	X
4 FRONT BUMPER SIDE HOLDER - LH	bet 23.00	1 PC	23.00	—
5 FRONT BUMPER FOG LAMP COVER - LH	17 95.90	1 PC	95.90	X
6 FRONT BUMPER TOWING COVER - LH	cut 24.20	1 PC	24.20	—
7 FRONT BUMPER CENTRE GRILLE - NO PRICE	NS 0.00	1 PC	0.00	X
8 FRONT HEAD LAMP - RA LH	Su 372.00	1 PC	372.00	X
9 GRILLE ASSY	cu 388.20	1 PC	388.20	—
10 GRILLE LOGO	ner 65.70	1 PC	65.70	—
11 GRILLE TOP CLIP	ner 4.40	11 PCS	48.40	—
			1,540.70	
		Less 10%	154.07	1,386.63
Special Net				
12 FRONT NUMBER PLATE WITH CASING	Su 35.00	1 SET	35.00	—
			35.00	35.00
Labour				
13 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	500.00	1 JOB	500.00	300
14 TO RESPRAY PAINT ON ACCIDENT PORTIONS	400.00	1 JOB	400.00	✓
15 TO CHECK WIRING	20.00	1 JOB	20.00	20
16 TO TUFF-KOTE	30.00	1 JOB	30.00	X
			950.00	950.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1049.8
102
944.82
1699.82
1359.81

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : CHOO CHEE YONG
BLK 305A ANCHORVALE LINK #11-01
SINGAPORE 541305

ATTN: QBE INSURANCE

Your Ref No: TP 0419-5473
Claim Type: Third Party
Accident Date: 08/04/2019
TP Veh Reg No: PC5400R


Estimate No: EST1504746
Date: 09 Apr 2019
Policy No: MT111943
Veh Reg No: SJM5744S
Make/Model: NISSAN LATIO 1.5L AT
ABS D/AIRBAG 2WD
4DR
Chassis No: JN1BAAC11Z0020658
Engine No: HR15053470B
Reg. Date: 09/01/2009

Estimate Repair Cost to Vehicle No :SJM5744S

Description	U/Price	Quantity	Price SS	Amount SS
Total				SS 2,371.63
Add GST @ 7%				166.01
Total Amount Payable				SS 2,537.64

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FIVE HUNDRED THIRTY SEVEN AND CENTS SIXTY FOUR ONLY

For Progressive Car Care Pte Ltd


AUTHORISED SIGNATURE