

REF: 08/FCI19006679/Kisd3n2
ASSIGNMENT (Office)
Proprietary
CWS
Eileen Lee
of FCI
Date/Time: 3pm @ 15/4/19
Estimated Cost: \$1116

OD/ID WST/TP RES/OF RES/EVA/INV/MY/CS

To Inspect Vehicle No. SLR 7553M Insured SHA 4608X

at Workshop no. Myler Consultant Tel 83300060

of 53 Ubi Ave 1 #01-25

Policy No. Claim No. D19002242MFSH

Sum Insured Excess

Make of Vch. D.O.A. 1/4/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time: 4:50pm @ 15/4/19 Person Contacted: Hui Qin

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	900
-----------	---------------------------------	-----

SLR 7553M - X

SHA 4608X - NS/NC18002275/Klvbn2 DOA: 2/2/18

16/04/19 @ 16:57 p.m. next policy comes from repair to Eileen Lee via email.

60

REF: FCI

ASSIGNMENT

From: Date: 15/4/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 7553M
at Workshop m/s My Car Consultant
of 53 paya ubi Ind. Park #01-33

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Hui Qian @ 83300060

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLR7553M Yr Regn: 28 108/17

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota C-HR c.c. 1798

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 48196 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 8YX102018075

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 215/60 R17
R: 11

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 15-04-19

Survey held at w/s 1pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
15/4 Estimate give later

15/08/19 confirmed 45 \$ 550/- @ 2 days with xhd
(\$ 1585-52 Red - 74%)

RECEIVED 15 AUG 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) 15/08/19 Typ. 4 ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

5 + RS, SI

Photos

Others

TOTAL

110
50
50
32
.
242

Report Format:

Lump Sum / I.B.I. (\$ 550/- 45)

MOTOR SURVEY ASSIGNMENT

Date	02-04-2019	Our Ref No. D19002242MFSH
Accident Date	01-04-2019	Claim Type. Third Party
Insured Vehicle	SHA4608X	Third Party Vehicle. SLR7553M
Survey Location	53 UBI AVE 1 #01-25 PAYA UBI INDUSTRIAL PARK	
Contact Person.	KAI LING	
Contact No.	83300060/ 83300060	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MY CAR CONSULTANT	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: My Car Consultant <admin@mycar.sg>
Sent: Thursday, 15 August 2019 11:43 AM
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: RE: SLR7553M
Attachments: Attachment 1.dat; ESTIMATE MARKED.pdf

WITHOUT PREJUDICE

Dear Shirley,

Pls close at the same.

Best Regards,

Huiqin

Direct line: 88668832 | Fax: 69255219

My Car Consultant Pte Ltd
53 Ubi Avenue 1
Paya Ubi Industrial Park #01-33
Singapore 408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

From: "Shirley Hiew (LKK Auto)" <ShirleyHiew@lkkauto.com>
Sent: Thursday, August 15, 2019 11:41 AM
To: "admin@mycar.sg" <admin@mycar.sg>
Cc: "SUR" <sur@lkkauto.com>
Subject: RE: SLR7553M

Dear Hui Qin,

Please confirm final fig \$ 550.00 (lump sum) @ 2 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: My Car Consultant [mailto:admin@mycar.sg]
Sent: Wednesday, 14 August 2019 5:18 PM
To: sur@lkkauto.com
Subject: SLR7553M

WITHOUT PREJUDICE

Dear Sur,

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 16 April 2019 4:57 PM
To: 'Eileen Lee'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19002242MFSH/2

Dear Eileen,

Please be informed that we have inspected the vehicle SLR 7553M on 15/04/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 15 April 2019 4:53 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002242MFSH/2

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 15 April 2019 3:00 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002242MFSH/2

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	434G
Vehicle Details	
Vehicle No.:	SLR7553M
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S A
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	2ZR8049759
Chassis No.:	ZYX102018075
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$28,008.00
Original Registration Date:	28 Aug 2017
First Registration Date:	28 Aug 2017
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,136.00
COE Rebate Amount:	\$40,964.00
Total Rebate Amount:	\$44,714.00

The information contained herein is correct as at 15 Aug 2019

OK

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #12-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
URN: S66500200 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MSI 319042855 Vehicle Registration No: SLR 7553 M
Name (as shown in NRIC) : JAFFAR BIN AWANG NRIC/FIN/Passport No : 57248834 G
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : APT BLK 758 JURONG WEST STREET 74 104-88 Singapore (640758)
Contact (Tel) : 97543642 Mobile No : 97543642
Email Address : daiyarah@yahoo.com.sg
Date of Accident : 01.04.2019 Time of Accident : 12:30
Place of Accident : AIRPORT BOULEVARD TOWARDS PIE
Insurance Company : NTUC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

- ① - I WOULD LIKE TO AMEND MY REPORT PURPOSE FROM REPORTING ONLY TO CLAIMING THIRD PARTY.
- ② - I WOULD LIKE TO AMEND MY EMAIL ADDRESS TO "daiyarah@yahoo.com.sg"

Policyholder / Driver's Signature
Date: 03/04/2019

IDAC - BOON LAY
STA Inspection Pte Ltd
249 Jalan Boon Lay
Singapore 619523
Tel : 6555 6111
Fax : 6515 5215

Reporting Centre Personnel's Signature
Name: _____

CAR
LANTCAR
LANTCAR
LANT

Estimation

22 Apr 19

SLR7553M

TOYOTA/CHR

398.3
298.73
30
X { MV
X
200
200

20% : 550

2 Days.

Auto Consultants hence notify
repairer of the following:
survey before/after spray painting
spray damaged part(s) during resurvey
prices are subject to confirmation
party survey is on a "Without Prejudice" basis
modification(s) is allowed
elementary item(s) must be resurveyed and
subject to final approval from Insurance Company

edged by Repairer

24



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19006679/Gsd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-08-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4608X	Veh. Inspected	SLR 7553M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002242MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	15/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZYX102018075	Colour	BLUE	
Odometer	48196	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	DUNLOP	6 mm	
L/H Front Tyre	215/60 R17	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R17	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/04/2019	Inspection Date	15/04/2019	
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 7553M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	808.00	398.30
1	REAR REFLECTOR LH	NOT NECESSARY	123.90	-
	LESS 20% DISCOUNT		-186.38	-
	LESS 25% DISCOUNT		-	-99.58
			745.52	298.72
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIP (SN)	NECESSARY	40.00	30.00
			40.00	30.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING.	NOT NECESSARY	50.00	-
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	100.00	-
	SPRAY PAINTING ON AFFECTED AREAS.		600.00	200.00
	PANEL BEATING ON AFFECTED AREAS.		600.00	200.00
			1,350.00	400.00
	GRAND TOTAL		2,135.52	728.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				550.00

Report Ref No. CS/FCI19006679/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.