



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19006700/Kpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: CYNTHIA

Date : 29-06-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 6160E	Veh. Inspected	SLE 5808K
Policy No.	VFX/P1305555	Coverage (\$)	0.00
Claim No.	S9M01K5D	Excess (\$)	0.00
Assign From		Assign Date	15/04/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 5 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6CW1071G0124125	Colour	METALLIC GREY
Odometer	36916	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	TOYO	6 mm
L/H Front Tyre	205/55 R16	TOYO	6 mm
R/H Rear Tyre	205/55 R16	TOYO	5 mm
L/H Rear Tyre	205/55 R16	TOYO	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/04/2019	Inspection Date	25/04/2019
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------