

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

Asiao Tony

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL ST #04-05 IOB BUILDING
049711

Estimate : ES190055

Attention : Motor Claim Department
Contact : 6223 8122

Date : 11/04/2019
Vehicle Num. : SLQ 7273B (LCR)
Make/Model : HONDA VEZEL HYBRID
Chassis/Eng# :
Accident Date : 30/03/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	REAR BUMPER Repair x		865.00
3.	1	REAR SIDE BUMPER - RH Repair x		210.00
3.	1	REAR FENDER WHEEL ARCH MOULDING - RH scf		145.00

List TotalS\$:	1,220.00
20.00% Discount S\$:	244.00
	976.00

1.	1SET	SPECIAL NETT ITEMS :		
2.	1SET	REAR BUMPER CLIP nec		30.00
		REAR FENDER WHEEL ARCH MOULDING CLIPS nec		15 30.00
		Special Nett Total S\$:		60.00

LABOUR :		
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE		400.00 300
REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANELS WHERE		
NECESSARY AND REPLACE ABOVE PARTS		
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS		400.00 /
Labour Total S\$:		800.00

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify
the Repairer for the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total S\$: 1,836.00
=====

Hwei Zie-Lkk
16/4/19
L/S 3days
ms

Total - \$700/-