

Adrian

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \$600  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 120K  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 05 H.S. days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMF1077L Yr Regn: 2018 Oct  
 Type: M.Cam / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Audi A3 Sedan c.c. 1395  
 Colour: White A/C: Insured / Std / Nil / NA  
 Sp. Reading: 7765 T/Radio: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WAUZZZ8V6J1077661  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/55R16  
 R: 205/55R16  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A. _____		D.O.I. <u>16/04/19</u>	

Survey held at Premium  
 Des. of Damages FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>00 ALG.</u>
	<u>SMF 1077L - CC3/A19/19006466 / KHA 3 D.O.A - 9/4/2019</u>
	<u>Part by Part \$4,641.92 (Red: 16,246.03, 77%)</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett: RECEIVED 2 JUL 2019</u>
	<u>Attached DV &amp; Final Bill</u>

Date/Time, File Pass to?	Date/Time, File Return to?
1) <u>IA Typist</u>	2)
3)	4)
5)	6)

Preli. Report: \_\_\_\_\_  
 Final Report: \_\_\_\_\_

Part Prices Check:	
IN	OUT

Survey Fee:	Date:
Basic & Add.	
<u>  </u> S + RS, <u>  </u> SI	
Photos	
Others	
TOTAL	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/04/2019 18:40
Date Of Accident	09/04/2019 11:00
Exact Location Of Accident	JUNCTION OF BEACH ROAD & OPHIR ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF1077L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEONG HOI-YUE, AARON
NRIC No	S8847637I
Email Address	AALL88@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96925511
Alternative Phone No	OTHERS-96925511

### Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.4 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800126371
Cover Note Number	

### Driver

Name of Driver	LEONG HOI-YUE, AARON
NRIC No	S8847637I
Date Of Birth	16/11/1988
Occupation	INDOOR
Date Of Driving Pass	17/11/2014
Driving Experience	4 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96925511
Fax Number	
Contact Number	OTHERS-96925511
EMail Address	AALL88@GMAIL.COM

Address	BLK 842 SIMS AVENUE #16-768
Postcode	400842
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 9 APR 2019, AT AROUND 2:10 PM, I WAS DRIVING ON THE RIGHTMOST LANE ALONG BEACH ROAD HEADING WEST TOWARDS CITY HALL. THERE WAS A RED TRANS CAB TAXI (VEHICLE NO: SHC5396P) TRAVELLING IN FRONT OF MY VEHICLE. AS WE APPROACHED THE JUNCTION OF OPHIR ROAD, THE TRAFFIC LIGHT TURNED AMBER. AT THIS POINT, THE TAXI WAS VERY NEAR THE STOP LINE AND STILL TRAVELLING AT THE SAME SPEED AS BEFORE. JUST MOMENTS BEFORE REACHING THE STOP LINE, THE BRAKE LIGHTS OF THE TAXI CAME ON. HOWEVER, DUE TO THE SPEED AT WHICH IT WAS TRAVELLING, THE TAXI CONTINUED TO MOVE AHEAD PAST THE STOP LINE. IT ONLY CAME TO A COMPLETE HALT WHEN THE TAXI WAS ALREADY PARTIALLY IN THE PEDESTRIAN CROSSING AHEAD, WITH ONLY THE REAR WHEELS STILL ON THE STOP LINE. DUE TO THE SPEED OF WHICH THE TAXI WAS TRAVELLING, IT WAS CLEAR THAT THE VEHICLE COULD NOT HAVE SLOWED DOWN IN TIME TO STOP BEFORE THE STOP LINE, AND I HAD EXPECTED IT TO MAINTAIN ITS SPEED TO CLEAR THE JUNCTION BEFORE THE LIGHT TURNED RED. WHILE DRIVING, I HAD KEPT A SAFE DISTANCE BETWEEN MY VEHICLE AND THE TAXI, BUT AS I DID NOT EXPECT THE TAXI TO BRAKE SO SUDDENLY SO CLOSE TO THE STOP LINE, I WAS UNABLE TO APPLY MY BRAKES IN TIME TO AVOID COLLIDING INTO THE REAR OF THE TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC5396P
Vehicle Make/Model/Colour	RENAULT / RED
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	NG THIAM FOOK
NRIC/Passport Number	S21703101

Contact Number

97537264

Address

BLK 603 YISHUN STREET 61  
#07-344

Postcode

760603

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 4/7/19 11:00

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: WONG ELANNE SPANG, Guy  
NRIC/FIN No: G2927452

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 9 April 2019 at around 2:10 pm, I was driving on the rightmost lane along Beach Road heading West towards City Hall. There was a red Trans Cab taxi (vehicle no. SHC 5396P) travelling in front of my vehicle.

As we approached the junction at Ophir Road, the traffic light turned amber. At this point, the taxi was very near the stop line and still travelling at the same speed or before. Just moments before reaching the stop line the brake lights of the taxi came on. However, due to the speed at which it was travelling, the taxi continued to move ahead past the stop line. It only came to a complete halt when the taxi was already partially in the pedestrian crossing ahead, with only the rear wheels still on the stop line.


Due to the speed at which the taxi was travelling it ~~appeared~~ <sup>was clear</sup> that the vehicle ~~could~~ <sup>could not</sup> have stopped in time to stop before the stop line, and I had expected it to maintain its speed to clear the junction before the light turned red.

While driving, I had kept a safe distance between my vehicle and the taxi, but as I did not expect the taxi to brake so suddenly so close to the stop line, I was

**DECLARATION** unable to apply my brakes in time to avoid colliding into the rear of the taxi.  
 I/We declare the foregoing particulars are true in every respect.

AL  
 Policyholder's Signature  
 Date & Time: 9/4/19 11:00

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name: Linda KENNEDY SMF 1077L  
 NRIC/IN No: G258142x

Accident Photo





License Number **S88476371**

Name

**LEONG HOI-YUE, AARON**

Birth Date **16 Nov 1988**

Issue Date **17 Nov 2014**



**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES**

EFFECTIVE DATE

**Class 3 Motor Cars ≤ 3000kg with ≤ 7 passengers, exclusive of the driver, and other motor vehicles ≤ 2500kg 17 Nov 2014**



NP 428A

## AUDI AUTO PROTECTOR PRIVATE VEHICLE

**Name of Policyholder** : LEONG HOI YUE AARON  
**Period of Insurance** : 29 Oct 2018 To 28 Oct 2020  
**Engine No.** : CZE 693538  
**Chassis No.** : WAUZZZ8V6J1077661

**Vehicle No.** : SMF1077L  
**Policy No.** : 1800126371  
**Endorsement No.** : 00000000240201  
**Issued Date** : 15 Nov 2018

### ABOUT THE COVER

**Make/Model** : AUDI A3 Sedan 1.4 TFSI  
**Engine Capacity/Tonnage** : 1,395.00 CC  
**Driver Restriction** : NA  
**Person or Classes of Persons Entitled to Drive\*** :

**Sum Insured** : Market Value  
**Off Peak Car** : No  
**First Year of Registration** : 2018  
**Insuring with COE/PARF** : Yes

a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission.  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

**Age Condition** : All Age Condition  
**Limitation as to use\*** :

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

**Loss of Use 1800cc - 2000cc Optional**

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

**Section 1**  
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

**Section 2**  
 Property Damage - \$0

**Windscreen** : \$100

**Named Driver and Excess** (where applicable)

LEONG HOI YUE AARON - \$600 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662023

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

### IMPORTANT NOTES

**Hire Purchase Company/Employer's Loan:** DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125259

PREMIUM LEASING -PSHS  
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE  
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**  
 AUTHORISED REPRESENTATIVE

82C986

**What can the 24-hour AIG Auto Emergency Hotline provide for you?**

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

**If no one is injured in the accident:**

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

**If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:**

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

**What should I do in the event of an accident?**

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

**LOSS OF USE CAR REPLACEMENT BENEFIT**

**Applicable only if this benefit is included in your motor insurance.** Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

**Steps to activate Loss of Use Car Replacement Benefit and Important Information**

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

**Rental Car Company: Popular Rent A Car Pte. Ltd.**

**Activation Hotline: 67428888**

**501 Guillemard Road Singapore 399840**

**Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm**

\*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

**IMPORTANT NOTICE**

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0472/2019/DY  
Date : 11-Apr-19

Vehicle NOT IN workshop.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Leong Hoi-Yue, Aaron  
Address : Blk 842 Sims Avenue  
#16-768  
Singapore 400842  
Telephone : HP +65 96925511  
Type of Claim : Own Damage Claims  
Policy No. : 1800126371  
Vehicle No : **SMF 1077 L**  
Model Code : Audi A3 Sedan 1.4 TFSI CO  
Model / Year : Oct-18  
Engine No : CZE 693538  
Chassis No : WAUZZZ8V6J1077661  
Mileage : -  
Date In : -  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 9-Apr-19  
Place of Accident : Junction of Beach Rd & Ophir Rd

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SMF 1077 L

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor headlight washer assy.	s/n \$ 360.00 ✓
2	To dismantle and renew front bumper and both headlights. To repair bonnet. Re-organise crash management components. Reinstall all parts removed.	\$ <del>2,100.00</del> 500 ✓
3	To respray front bumper and bonnet.	\$ <del>1,500.00</del> 1100 ✓
4	To carry out diagnostic check.	s/n \$ 192.00 ✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ <u>4,152.00</u></b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SMF 1077 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER COVER <i>rehab d</i>	\$ 1,667.00 ✓	1333.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00 +	
3	FRONT BUMPER GRILLE <i>new</i>	\$ 134.00 +	
4	CLOSING ELEMENT - LH <i>new</i>	\$ 445.00 +	
5	CLOSING ELEMENT - RH <i>new</i>	\$ 270.00 +	
6	COVER TRIM FOR CLOSING ELEMENT - LH <i>new</i>	\$ 135.00 +	
7	COVER TRIM FOR CLOSING ELEMENT - RH <i>new</i>	\$ 135.00 +	
8	FRONT RADIATOR GRILLE <i>new</i>	\$ 1,176.00 ✓	940.80
9	CLOSING ELEMENT <i>new</i>	\$ 158.00 ?	126.40
10	SIDE REINFORCEMENT <i>new</i>	\$ 660.00 +	
11	FOAM FILLER PIECE <i>new</i>	\$ 157.00 +	
12	COVER FOR FOAM FILLER PIECE <i>new</i>	\$ 111.00 +	
13	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 6.00 +	5.12
14	CAUTION STICKER <i>new</i>	\$ 12.00 +	9.76
15	LED HEADLIGHT - LH <i>new</i>	\$ 5,458.00 +	
16	LED HEADLIGHT - RH <i>new</i>	\$ 5,458.00 +	
17	FRONT NUMBER PLATE <i>new</i>	\$ 40.00 ✓	
18	SUNDRIES <i>Not New</i>	\$ 500.00 ?	X
<b>TOTAL SPARE PARTS</b>		<b>\$ 16,692.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 4,152.00</b>	
<b>GRAND TOTAL</b>		<b>\$ 20,844.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

10838 14

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** : Adrian King.  
**Surveyed Date** : 16/04/19.  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** : Authorised Repairs, OADays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0472/2019/DY

8-May-19

Glory Tan

1 of 1

SMF 1077 L

Audi A3 Sedan 1.4 TFSI CO

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

### Parts

1	Radiator air guide LH } cracked	S 22.00	22.00
2	Radiator air guide RH	S 22.00	22.00

**\$ 44.00**

### LABORS

**TOTAL \$ 44.00**

For Premium Automobiles Pte Ltd

*Adrian Ling*  
*A.S.*



Authorized Signature

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0472/2019/DY  
Date : 11-Apr-19

Vehicle NOT IN workshop.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Hi Adrian

We took 5 days with added parts order

jb 1 Jun 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Leong Hoi-Yue, Aaron  
Address : Blk 842 Sims Avenue  
#16-768  
Singapore 400842  
Telephone : HP +65 96925511  
Type of Claim : Own Damage Claims  
Policy No. : 1800126371  
Vehicle No : **SMF 1077 L**  
Model Code : Audi A3 Sedan 1.4 TFSI CO  
Model / Year : Oct-18  
Engine No : CZE 693538  
Chassis No : WAUZZZ8V6J1077661  
Mileage : -  
Date In : -  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 9-Apr-19  
Place of Accident : Junction of Beach Rd & Ophir Rd

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SMF 1077 L

S/N	Nature of Jobs	Estimated Charges	
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor headlight washer assy.	s/n \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper and both headlights. To repair bonnet. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00	\$ 500.00
3	To respray front bumper and bonnet.	\$ 1,500.00	\$ 1,100.00
4	To carry out diagnostic check.	s/n \$ 192.00	\$ 192.00
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 4,152.00</b>	<b>\$ 2,152.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SMF 1077 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER COVER	\$ 1,667.00	\$ 1,333.60
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GRILLE	\$ 134.00	
4	CLOSING ELEMENT - LH	\$ 445.00	
5	CLOSING ELEMENT - RH	\$ 270.00	
6	COVER TRIM FOR CLOSING ELEMENT - LH	\$ 135.00	
7	COVER TRIM FOR CLOSING ELEMENT - RH	\$ 135.00	
8	FRONT RADIATOR GRILLE	\$ 1,176.00	\$ 940.80
9	CLOSING ELEMENT	\$ 158.00	\$ 126.40
10	SIDE REINFORCEMENT	\$ 660.00	
11	FOAM FILLER PIECE	\$ 157.00	
12	COVER FOR FOAM FILLER PIECE	\$ 111.00	
13	STICKER FOR AIR CONDITIONER	\$ 6.00	\$ 5.12
14	CAUTION' STICKER	\$ 12.00	\$ 9.76
15	LED HAEDLIGHT - LH	\$ 5,458.00	
16	LED HEADLIGHT - RH	\$ 5,458.00	
17	FRONT NUMBER PALTE	\$ 40.00	\$ 40.00
18	Added parts - see attached	\$ 44.00	\$ 34.24
19	SUNDRIES	\$ 500.00	
<b>TOTAL SPARE PARTS</b>		<b>\$ 16,736.00</b>	<b>\$ 2,489.92</b>
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 4,152.00</b>	<b>\$ 2,152.00</b>
<b>GRAND TOTAL</b>		<b>\$ 20,888.00</b>	<b>\$ 4,641.92</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

<b>AIG Asia Pacific Insurance Pte Ltd</b> 78 Shenton Way #07-16 AIG Building Singapore 079120 <b>Attn: Mr. Adrian Ling - Motor Claims Dept</b> <b>Tel: 6841 0055 - Fax: 6256 4315</b>		<b>Estimate No.</b> <b>Date</b> <b>Service Advisor</b> <b>Pages</b> <b>Regn No</b> <b>Model No</b>	PA/OD/0472/2019/DY 8-May-19 Glory Tan 1 of 1 SMF 1077 L Audi A3 Sedan 1.4 TFSI CO
Quantity	Description	Unit Price	Amount
<b>Parts</b>			
1	Radiator air guide LH	\$ 22.00	\$ 17.12
2	Radiator air guide RH	\$ 22.00	\$ 17.12
		<b>\$ 44.00</b>	<b>\$ 34.24</b>
<b>LABORS</b>			
<b>TOTAL</b>		<b>\$ 44.00</b>	

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
Authorised Signature

# Premium Automobiles

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attn: Motor Claims Dept**  
**Yr Ref: SMF 1077 L**

Norah Khai  
6768 9911  
6841 1183  
Nora.khai@premiumauto.com.sg  
Body & Paint Dept  
PA/OD/0472/2019/KS

25 June 2019

from  
Telephone +65-  
Telefax +65-  
EMail  
Our department  
Our Ref  
Your Ref  
Date

Dear Sir,

**RE: INSURANCE CLAIM FOR SMF 1077 L, Audi A3 SEDAN 1.4 TFSI**

With reference to the above-mentioned vehicle, no. **SMF 1077 L**, claimant, **Mr. Leong Hoi-Yue, Aaron**, please find the related document per attached.

1. A copy of the Original invoice no. 85013957 – S\$4,324.85
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai  
Claims Dept

Encl  
AIG – SMF 1077 L

total pages

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Rd 1  
Singapore 408699  
Telephone (65) 6336 2323  
Telefax (65) 684 11183

# Premium Automobiles Pte Ltd



**Audi Centre Singapore**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6836 2223  
Main Telefax 6471 3733

**Alexandra Service Centre**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6388 2223  
Main Telefax 6475 1023

**Ubi Service Centre**  
55 Ubi Road 1  
Singapore 408099  
Main Telephone 6388 2323  
Main Telefax 6641 1183

**Customer Service**  
Service Appointment 6366 2323  
24-hour Breakdown Service 9828 1233  
Email customer.care@premiumauto.com.sg

## INS TAX INVOICE

Page 1 14:29

Company Reg. No. 199902271W  
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013957 Date : 24/06/2019 Order : SMF1077L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SMF1077L (V 39128) Regn Date: 29/10/2018 Mileage: 9606 WIP No.: 49561

Model: A3 SEDAN 1.4 TFSI COD 8VMACG Chassis: WAUZZZ8V6J1077661 Engine: CZE 693538 Dept: U

You have been assisted by :- UB-Tony Foong ( 33 )

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V3853651AA3F2	(A) (SK) GRILLE 17/4/1 Less 020%	1.00	1176.00	940.80
X	A8V5807065R GRU	(A) (GER) COVER 17/4/1 Less 020%	1.00	1667.00	1,333.60
X	A8K0010520A	PLATE Less 020%	1.00	12.20	9.76
X	A8V0010515A	STICKER Less 020%	1.00	6.40	5.12
X	A8V0121284K	AIR DUCT Less 020%	1.00	21.40	17.12
X	A8V0121283K	AIR DUCT Less 020%	1.00	21.40	17.12
X	A8V3853949	(A) (SK) PLATE 17/4/19 Less 020%	1.00	158.00	126.40

Parts 2,449.92  
Labour 0.00  
Sublet 2,192.00  
Menus 0.00  
Lubricant 0.00

Sub-Total 4,041.92

7% GST 282.93

Grand Total 4,324.85



Received by

For & on behalf of  
Premium Automobiles Pte Ltd

# Premium Automobiles

## Telefax

to **AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Motor Claims Dept**  
**Yr Ref: SMF 1077 L**

Norah Khai  
6768 9828  
6841 1183

Body Repair

PA/OD/0472/2019/GW  
10<sup>TH</sup> MAY 2019

from  
Telephone +65-  
Telefax +65-  
Mobile +65-  
Our department  
Your Claim Ref  
Our Ref  
Date

**RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER**

**Make & Model** : Audi A3 SEDAN 1.4 TFSI CO  
**Vehicle Chassis No.** : WAUZZZ8V6J1077661  
**Vehicle Regn No.** : **SMF 1077 L**  
**Vehicle Mileage** : 8859 KM  
**Vehicle Owner** : Mr. Leong Hoi-Yue, Aaron  
**Certificate No** : 1800126371  
**Own Damage Excess** : \$ 642.00 (Inclusive 7% GST)  
**Accident Date** : 9<sup>TH</sup> April 2019  
**Place** : Junction of Beach Rd & Ophir Rd  
**Repair Cost** : \$4,324.85  
**WIP No.** : 49561  
**Repairer's Name** : Premium Automobiles Pte Ltd

total pages

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Road 1  
Singapore 408699  
Telephone (65) 6366 2323  
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

**Owner / Insured Signature** :  \_\_\_\_\_

**Time** : \_\_\_\_\_

**Date** : 10 May 2019

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Apr 2019		16 Apr 2019 14:44 <a href="#">Edit Adj Rpt</a>	<b>S\$4,641.92</b> <a href="#">Edit Estimates</a>	<b>S\$4,641.92</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	LEONG HOI-YUE, AARON, ID: S88476371, Tel: +6596925511, Email: AALLB8@GMAIL.COM	
Vehicle Reg. No.:	SMF1077L	Date of Loss: 09/04/2019 11:00 - :59 [5 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1422149103SG	Policy/Cover Note No.: 1800126371 (Comprehensive) Excess: S\$600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689628/9827/9911	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban] Deeban.nadaraja.nadaraja@aig.com	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/04/2019]	
Driver/Custodian:	LEONG HOI-YUE, AARON (30 / Male), NRIC: S88476371, Tel: +6596925511 Email: AALLB8@GMAIL.COM	

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>• AIG_SG (02/05/2019): SMF1077L / OD / 09/04/2019 / Coverage &amp; Excess update</li> <li>• AIG_SG (30/04/2019): SMF1077L / OD / 09/04/2019 / Coverage &amp; Excess update</li> <li>• AIG_SG (17/04/2019): SMF1077L / OD / 09/04/2019 / Coverage &amp; Excess update</li> </ul>		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

\*SMF1077L (1422149103SG)  
OD  
Apr 9 2019 11:00AM  
[LEONG HOI-YUE, AARON]  
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
<b>Video</b>											1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)						Thumbnail	Print			
1	10/04/19 19:30	<b>Video - Accident</b> [Linked Accident Report Documents]							Load MP4			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	16/04/19 14:57	<b>Video - Accident</b>							Load MP4			
<b>Photos/Images</b>											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
2	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
3	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
4	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
5	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
6	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
7	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
8	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
9	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
10	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
11	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
12	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
13	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
14	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
15	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
16	06/06/19 16:09	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
17	06/06/19 16:10	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
18	06/06/19 16:10	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
19	06/06/19 16:10	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
20	06/06/19 16:10	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
21	06/06/19 16:10	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
22	06/06/19 16:10	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
23	06/06/19 16:10	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
24	06/06/19 16:10	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
25	06/06/19 16:10	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
26	06/06/19 16:10	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>											1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	16/04/19 15:22	<b>ESTIMATE</b>							Load PDF			
2	16/04/19 15:22	<b>Certificate of Insurance</b>							Load PDF			
3	16/04/19 15:22	<b>Driver's Driving License N NIRC</b>							Load PDF			
4	16/04/19 15:23	<b>Singapore Accident Statement</b>							Load PDF			
5	19/07/19 12:28	<b>Workshop Invoice</b>							Load PDF			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
6	19/07/19 12:28	Discharge Voucher		Load PDF
7	19/07/19 12:48	Supplementary		Load PDF

## Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	10/04/19 19:30	Video - Accident		Load MP4

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	10/04/19 19:41	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	10/04/19 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	10/04/19 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	10/04/19 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	10/04/19 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	10/04/19 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	10/04/19 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	10/04/19 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	10/04/19 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	10/04/19 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	10/04/19 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	10/04/19 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	10/04/19 19:28	Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	10/04/19 19:28	Sketch Plan #2		Load JPG <input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co Reg. No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

**Our File No:** CC3/AIG19006753/ATD3E2

**Date:** 19/07/2019

#### REFERENCE

Insured/Claimant:	LEONG HOI-YUE, AARON	Policy No:	1800126371
Date of Loss:	09/04/2019	Nature of Claim:	OD
			Claim No: 1422149103SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF1077L	Engine No:	CZE693538
Make & Model:	AUDI A3, 1.4 TFSI (A)	Chassis No:	WAUZZZ8V6J1077661
Reg. Date:	29/10/2018 (Man. Year: 2018)	Odometer:	7765 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,726.24	2,489.92	14,236.32	85.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,152.00	2,152.00	2,000.00	48.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,878.24</b>	<b>4,641.92</b>	<b>16,236.32</b>	<b>77.77</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	20,278.24	4,041.92	16,236.32	80.07
<b>+ GST 7.00/7.00% (S\$)</b>	1,419.48	282.93	1,136.55	80.07
<b>Nett Amount (S\$)</b>	<b>21,697.72</b>	<b>4,324.85</b>	<b>17,372.87</b>	<b>80.07</b>

#### INSPECTION

Date of Assignment:	16/04/2019		
Date Inspected:	16/04/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	1,667.00 FS	*1,333.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE	Not Necessary	134.00 FS	*- FS
4	1		*CLOSING ELEMENT - LH	Not Necessary	445.00 FS	*- FS
5	1		*CLOSING ELEMENT - RH	Not Necessary	270.00 FS	*- FS
6	1		*COVER TRIM FOR CLOSING ELEMENT - LH	Not Necessary	135.00 FS	*- FS
7	1		*COVER TRIM FOR CLOSING ELEMENT - RH	Not Necessary	135.00 FS	*- FS
8	1		*FRONT RADIATOR GRILLE	Cracked	1,176.00 FS	*940.80 FS
9	1		*CLOSING ELEMENT	Cracked	158.00 FS	*126.40 FS
10	1		*SIDE REINFORCEMENT	Not Necessary	660.00 FS	*- FS
11	1		*FOAM FILLER PIECE	Not Necessary	157.00 FS	*- FS
12	1		*COVER FOR FOAM FILLER PIECE	Not Necessary	111.00 FS	*- FS
13	1		*STICKER FOR AIR CONDITIONER	Necessary	6.00 FS	*5.12 FS
14	1		*CAUTION STICKER	Necessary	12.00 FS	*9.76 FS
15	1		*LED HEADLIGHT - LH	Not Necessary	5,458.00 FS	*- FS
16	1		*LED HEADLIGHT - RH	Not Necessary	5,458.00 FS	*- FS
17	1		*FRONT NUMBER PLATE	Necessary	40.00 FS	*40.00 FS
18	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
19	1		*RADIATOR AIR GUIDE LH	Cracked	17.12 FS	*17.12 FS
20	1		*RADIATOR AIR GUIDE RH	Cracked	17.12 FS	*17.12 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 16,726.24 2,489.92**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. TO REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>4,152.00</b>	<b>2,152.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >