

ASS. REC. BY:

REF: CS/CT119006756 | A993 | 02

Special Instruction:

Conveyor: Adnan

ASSIGNMENT (Office)

From (Person): Elaine Cheong

of CT1

Date/Time: 16.4.19 11.57 A.M

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 97627

Insured: SJV 719B

at Workshop m/s Dynamic Autowork

Tel: 63416789

of 8 Kaki Bukit Ave 4 #08-09

Policy No:

Claim No: SVM1910201638C02-9

Sum Insured:

Excess:

Make of Veh:

D.O.A. 12.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 16.4.2019

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)

WP \$4350, 6 days (red \$16381.40, 70%)

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKE9762T Yr Regn: 2012 AprilType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit ASX c.c. 1998Colour: Black A/C: Insured / Std / NI / NASp. Reading: 102136 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYXTGA2WC2000572Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Right / STD A/Rim orTyre Size: F: 235/50R18R: 235/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 16/04/19Survey held at DynamicDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP China.SKE 9762T-XSJV 719B-XMV: 41K. Depreciation 10K. 3yr x 10K + Mn Perf = 30+1K = 41K.PV: 36K.Nett: 5K.

RECEIVED 28 MAY 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 28/5 Adrian

2) _____

3) _____

4) _____

5) _____

6) _____

Prel. Report: _____

Final Report: _____

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

220

Catherine Chong (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Tuesday, 16 April, 2019 11:51 AM
To: Dynamic Autowork; 'assignments'
Cc: Claims Dept of CTI
Subject: RE: SKE9762T (Pre-inspection) / Your vehicle : SJV719B (CLAIM REF: SNM19D201638C02-9)

Without Prejudice

Your Ref: SJV719B
Our Ref: SNM19D201638C02/2 (SKE9762T)

Dear Michelle,

We refer to the above matter.

Liability clear.

In view of the above, we agree to go for Direct Settlement, subject to consistency of damages, based on M/s LKK Auto Consultant's findings, with supporting documents.

Aside to M/s LKK,

Please assist to arrange for the survey.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Dynamic Autowork [mailto:dynamicautowork@gmail.com]
Sent: Tuesday, 16 April, 2019 9:56 AM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: SKE9762T (Pre-inspection) / Your vehicle : SJV719B (CLAIM REF: SNM19D201638C02-9)

Dear All,

Thanks for reply.
Please arrange **ADRIAN LING** to survey the above vehicle.

**** Please advise liability ****

--

Thank You.

Yours Sincerely,

Michelle
HP : 9856 4815

8 Kaki Bukit Avenue 4
#08-09Premier @ Kaki Bukit
Singapore (415875)
Tel : 6341 6789
Fax : 6341 6778

On Tue, Apr 16, 2019 at 9:52 AM Elaine Cheong <elaine.cheong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Michelle,

We refer to your email of 15.04.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Elaine Cheong

Executive (Motor Claims)

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com

From: Claims Dept of CTI

Sent: Monday, 15 April, 2019 3:57 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>

Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: FW: SKE9762T (Pre-inspection) / Your vehicle : SJV719B

Dear Elaine,

Please conduct PRS – TP: SKE9762T soonest possible.

The file is with you.

From: Dynamic Autowork [<mailto:dynamicautowork@gmail.com>]

Sent: Monday, 15 April 2019 3:18 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: SKE9762T (Pre-inspection) / Your vehicle : SJV719B

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert

**** PLEASE ADVISE LIABILITY****

--

Thank You.

Yours Sincerely,

Michelle

HP : 9856 4815

8 Kaki Bukit Avenue 4

#08-09Premier @ Kaki Bukit

Singapore (415875)

Tel : 6341 6789

Fax : 6341 6778

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Price Range ▼ Depreciation ▼ Year Reg ▼ Vehicle Type ▼

Advanced Search

Home » Used Cars » Direct Owners » Mitsubishi ASX 2.0A

Mitsubishi ASX 2.0A

Overview Financial Insurance Accessories Similar Research Photos Map **DIRECT OWNER**

Price	\$45,800		
Depreciation ⓘ	\$11,200 /yr <small>View models with similar depre</small>	Reg Date	23-Apr-2012 <small>(3yrs 7days COE left)</small>
Mileage	N.A.	Manufactured ⓘ	2011
Road Tax ⓘ	\$1,210 /yr	Transmission	Auto
Dereg Value ⓘ	\$36,043 as of today (change)	OMV ⓘ	\$23,888
COE ⓘ	\$67,889	ARF ⓘ	\$23,888
Engine Cap	1,998 cc	Power	110.0 kW (147 bhp)
Curb Weight ⓘ	1,438 kg	No. of Owners ⓘ	2
Type of Vehicle	SUV		



100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER

Shortlist Compare Add note
Report Error More Actions

Features

View specs of the Mitsubishi ASX (2010-2014)

Description

Low Maintenance Cost, Very Well Maintained, Like Brand New.

Category

PARF Car, Direct Owner Sale

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Seller Information

Contact Person(s) Fablan

Enquiry Contact Seller

ESSENTIAL TRANSACTION FORMS

- » Indemnity form
- » Receipt
- » Sales agreement
- » Hand-over form
- » Ownership Transfer



GET HELP WITH PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with **Car Loans, Insurance, Payments & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

[Upload your Sales Agreement](#)

[Read our 8 Step Guide for Direct Buyers & Sellers](#)

Posted on: 15-Apr-2019 | Last Updated on: 15-Apr-2019

Upfront Payment

[» more Financial info](#)

Transfer Fee ⓘ	\$25	
Down Payment ⓘ	\$13,740 (change)	Maximum 70% Loan
1st Instalment ⓘ	\$970	Based on 2.98% interest rate
Insurance	\$1,140 onwards <small>Not at fault? No upfront payment required! (Get a quote) Quote assumes a standard profile. *Get a quote* for exact figure.</small>	
Total Upfront Payment ⓘ	\$15,875	Check with seller for exact figure

Powered by

[Compare](#)

» [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5192J
Vehicle Details	
Vehicle No.:	SKE9762T
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Apr 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	ASX 2.0 6-CVT (M) ABS D/AIRBAG SR 2WD
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	4B11HY5148
Chassis No.:	JMYXTGA2WCZ000572
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$23,888.00
Original Registration Date:	23 Apr 2012
First Registration Date:	23 Apr 2012
Transfer Count:	1
Actual ARF Paid:	\$23,888.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Apr 2022
PARF Rebate Amount:	\$15,527.00
Intended COE Rebate Details	
COE Expiry Date:	22 Apr 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$67,889.00
COE Rebate Amount:	\$20,536.00
Total Rebate Amount:	\$36,063.00

23/04/2012

\$ 9737.00

The information contained herein is correct as at 13 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/04/2019 14:57
Date Of Accident	12/04/2019 13:05
Exact Location Of Accident	CTE TWDS CITY (AFTER ANG MO KIO AVE 1 EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE9762T
Insured/Policyholder	
Name Of Registered Owner	BEVIE WEE SHI YI
NRIC No	S9305192J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87882720
Alternative Phone No	OFFICE-60000000

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ASX-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA093171/1
Cover Note Number	

Driver

Name of Driver	WEE SHI KAI KEELY
NRIC No	S9045338F
Date Of Birth	13/11/1990
Occupation	INDOOR
Date Of Driving Pass	02/07/2018
Driving Experience	0 YEAR AND 9 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-88337207
Fax Number	
Contact Number	
EMail Address	KEELYWEE27@GMAIL.COM

Address	2 SANDY LANE
Postcode	437323
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Report please refer to sketch plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	GET FROM WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV719B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: ADAMIC
57131307C

Sketch Plan #2

SKETCH PLAN



A = JKE 9762J

B = SJV 719B

CTE towards City

(After Ang Mo Kio

Avenue 1 Exit)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No: 37151309G

Sketch Plan #3

On 12.04.19 at about 13:05 hours along CTE towards City (After Ang Mo Kio Avenue 1 Exit). I was travelling straight on the lane 4, when my front vehicle slowed down and stopped hence I follow suit.

Suddenly I heard a loud bang from behind. When I alighted I realised it was vehicle (B) had hit onto rear portion of my vehicle (A).

Vehicle (A): SKE 9762T

Vehicle (B): SJV 719B



Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 15.04.19

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKE9762T**
MODEL : MIT-ASX *Xiao Chen .*
DATE OF ACCIDENT : 12.04.19
TIME OF ACCIDENT : 13:05HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	TAILGATE BUZZLE <i>3 Dented</i>	1	\$ 110.00	\$ 110.00	-
2	TAILGATE DETECTOR	1	\$ 184.00	\$ 184.00	✓
3	TAILGATE WEATHERSTRIP <i>New</i>	1	\$ 175.00	\$ 175.00	+
4	REAR BUMPER <i>Rehd</i>	1	\$ 730.00	\$ 730.00	✓
5	REAR BUMPER REFLECTOR <i>Crushed</i>	2	\$ 42.00	\$ 84.00	✓
6	REAR BUMPER TOWING COVER <i>Rehd</i>	1	\$ 28.00	\$ 28.00	✓
7	REAR BUMPER CENTRE COVER <i>Rehd</i>	1	\$ 28.00	\$ 28.00	✓
8	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 32.00	\$ 64.00	✓
9	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 270.00	\$ 270.00	✓
10	TAILLAMP <i>New</i>	2	\$ 588.00	\$ 1,176.00	+
11	REAR FENDER INNER TRIM <i>New</i>	2	\$ 510.00	\$ 1,020.00	+
12	REAR END PANEL <i>Dented</i>	1	\$ 342.00	\$ 342.00	✓
13	REAR END PANEL TOP GARNISH <i>Rehd</i>	1	\$ 155.00	\$ 155.00	✓
14	REAR FLOOR PANEL TOP BOARD <i>Rehd</i>	1	\$ 250.00	\$ 250.00	✓
15	REAR FLOOR SIDE TOOL BOX <i>Crushed</i>	2	\$ 160.00	\$ 320.00	✓
16	REAR SPARE TYRE BOLT <i>New</i>	1	\$ 25.00	\$ 25.00	+
17	CENTER EXHAUST <i>New</i>	1	\$ 1,500.00	\$ 1,500.00	+
18	CENTER EXHAUST MOUNTING <i>New</i>	4	\$ 35.00	\$ 140.00	+
19	CENTER EXHAUST GASKET (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	+
20	REAR EXHAUST PIPE <i>Dented</i>	1	\$ 769.00	\$ 769.00	✓
21	REAR EXHAUST INSULATOR <i>New</i>	1	\$ 84.00	\$ 84.00	+
22	REAR EXHAUST GASKET (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	✓
23	REAR EXHAUST MOUNTING <i>New</i>	2	\$ 36.00	\$ 72.00	+
24	REAR CROSS MEMBER <i>New</i>	1	\$ 1,400.00	\$ 1,400.00	+

3394
3054.60

TOTAL PRICE \$ 9,046.00
LESS 10% \$ 904.60
SUB TOTAL PRICE \$ 8,141.40

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SKE9762T
 MODEL : MIT-ASX
 DATE OF ACCIDENT : 12.04.19
 TIME OF ACCIDENT : 13:05HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE (SPECIAL TYPE) <i>Ne</i>	1	\$ 150.00	\$ 150.00 <i>x</i>
2	REAR BUMPER CLIP (SET) <i>Ne</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
3	REAR FENDER INNER COWLING CLIP (SET) <i>Ne</i>	1	\$ 60.00	\$ 60.00 <i>x</i>
4	REAR FENDER INNER TRIM CLIP (SET) <i>Ne</i>	1	\$ 60.00	\$ 60.00 <i>x</i>
5	TAIL LAMP CLIP (SET)	1	\$ 40.00	\$ 40.00 <i>x</i>
6	REAR END PANEL TOP GARNISH CLIP (SET) <i>Ne</i>	1	\$ 30.00	\$ 30.00 <i>10</i>
7	REAR END PANEL INSULATION SEAL <i>Ne</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
8	REAR EXHAUST CHROME (SPECIAL TYPE) <i>Ne</i>	1	\$ 350.00	\$ 350.00 <i>x</i>
9	REVERSE SENSOR <i>Damp</i>	1	\$ 220.00	\$ 220.00 <i>200</i>

300 TOTAL \$1,140.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	<i>600</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING AND BULB CHECK	\$ 80.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 150.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX UNDERCARRIAGE	\$ 650.00	<i>x</i>
8	FOUR WHEELS ALIGNMENT	\$ 120.00	<i>x</i>
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>x</i>
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	<i>x</i>
11	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>x</i>
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	<i>80</i>

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SKE9762T
 MODEL : MIT-ASX
 DATE OF ACCIDENT : 12.04.19
 TIME OF ACCIDENT : 13:05HRS

13	WRAPPING PAPER	\$ 680.00	400
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$5,450.00 2080

ESTIMATE REPORT

TOTAL PARTS COST : \$9,281.40
 TOTAL LABOUR COST : \$5,450.00
 TOTAL REPAIR COST : \$14,731.40

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY
 SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Adrian Lj
L/S 15/04/19.
060hrs.

total: 5434.60.
L/S: 4350.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119006756/AQD3N2

Date: 30/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1800361901
Claimant Vehicle No :	SKE9762T	Insured Vehicle No :	SJV719B
Date of Loss:	12/04/2019	Nature of Claim:	TP
		Claim No:	SNM19D201638C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE9762T	Engine No:	4B11HY5148
Make & Model:	MITSUBISHI ASX, 2.0 (A)	Chassis No:	JMYXTGA2WCZ000572
Reg. Date:	23/04/2012 (Man. Year: 2011)	Odometer:	102136 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,281.40	3,354.60	5,926.80	63.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,450.00	2,080.00	3,370.00	61.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,731.40	5,434.60	9,296.80	63.11
Approved Total (Overridden) (S\$)		4,350.00		
(S\$)	14,731.40	4,350.00	10,381.40	70.47
+ GST 7.00/7.00% (S\$)	1,031.20	304.50	726.70	70.47
Nett Amount (S\$)	15,762.60	4,654.50	11,108.10	70.47

INSPECTION

Date of Assignment:	16/04/2019	
Date Inspected:	16/04/2019 Inspected At:	Dynamic Autowork Pte. Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2019)
Parts: M1-SUV	mitsubishi ASX 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKE9762T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE BUZZLE	Damaged	110.00 FL	*110.00 FL
2	1		*TAILGATE DETECTOR	Damaged	184.00 FL	*184.00 FL
3	1		*TAILGATE WEATHERSTRIP	Not Necessary	175.00 FL	*- FL
4	1		*REAR BUMPER	Deformed	730.00 FL	*730.00 FL
5	2		*REAR BUMPER REFLECTOR	Cracked	84.00 FL	*84.00 FL
6	1		*REAR BUMPER TOWING COVER	Deformed	28.00 FL	*28.00 FL
7	1		*REAR BUMPER CENTRE COVER	Deformed	28.00 FL	*28.00 FL
8	2		*REAR BUMPER SIDE RETAINER	Necessary	64.00 FL	*64.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Dented	270.00 FL	*270.00 FL
10	2		*TAILLAMP	Not Necessary	1,176.00 FL	*- FL
11	2		*REAR FENDER INNER TRIM	Not Necessary	1,020.00 FL	*- FL
12	1		*REAR END PANEL	Dented	342.00 FL	*342.00 FL
13	1		*REAR END PANEL TOP GARNISH	Deformed	155.00 FL	*155.00 FL
14	1		*REAR FLOOR PANEL TOP BOARD	Deformed	250.00 FL	*250.00 FL
15	2		*REAR FLOOR SIDE TOOL BOX	Cracked	320.00 FL	*320.00 FL
16	1		*REAR SPARE TYRE BOLT	Not Necessary	25.00 FL	*- FL
17	1		*CENTER EXHAUST	Not Necessary	1,500.00 FL	*- FL
18	4		*CENTER EXHAUST MOUNTING	Not Necessary	140.00 FL	*- FL
19	1		*SET CENTER EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
20	1		*REAR EXHAUST PIPE	Dented	769.00 FL	*769.00 FL
21	1		*REAR EXHAUST INSULATOR	Not Necessary	84.00 FL	*- FL
22	1		*SET REAR EXHAUST GASKET	Necessary	60.00 FL	*60.00 FL
23	2		*REAR EXHAUST MOUNTING	Not Necessary	72.00 FL	*- FL
24	1		*REAR CROSS MEMBER	Not Necessary	1,400.00 FL	*- FL
25	1		*REAR NUMBER PLATE (SPECIAL TYPE)	Not Necessary	150.00 FS	*- FS
26	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
27	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
28	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
29	1		*SET TAIL LAMP CLIP	Not Necessary	40.00 FS	*- FS
30	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
31	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
32	1		*REAR EXHAUST CHROME (SPECIAL TYPE)	Not Necessary	350.00 FS	*- FS
33	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,186.00	3,694.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	904.60	339.40
Total Parts (\$\$)	9,281.40	3,354.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS.	New	1,400.00	600.00
2	TO SPRAY PAINT AFFECTED AREA.	New	1,400.00	800.00
3	TUFF COAT.	New	250.00	60.00
4	WIRING AND BULB CHECK.	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.	New	150.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	New	80.00	50.00
7	REMOVE AND REFIX UNDERCARRIAGE.	New	650.00	0.00
8	FOUR WHEELS ALIGNMENT.	New	120.00	0.00
9	TRANSFER TAILGATE MECHANISM.	New	80.00	0.00
10	CONDUCT WATER LEAKAGE TEST.	New	80.00	0.00
11	REMOVE AND REFIX TAILGATE WINDSCREEN.	New	120.00	0.00
12	REMOVE AND REFIX REAR EXHAUST PIPE.	New	180.00	80.00
13	WRAPPING PAPER.	New	680.00	400.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	180.00	0.00
Gross Labour Cost (\$\$)			5,450.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >