

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to Survey this
Vehicle thanks

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	: SQT19001700	Page	1
	8 SHENTON WAY	Date	: 15. Apr 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: LIM CHOU SIONG		
Registration No	: SLV9226Z	Engine No	: L15B4533674		
Chassis No	: JHMRU1830GX203674	Date Time	: 15. Apr 2019 8:00:45 PM		
Model	: HRV LX-SIN CVT YM 2016	Surveyor Name	:		
Owner's Name	: LIM SHAN SHAN, ALICE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 13/4/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: LIM SHAN SHAN, ALICE						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 13/4/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SLN4579E						
75722-T7W-A01	EMBLEMRR.	11	1	13.30	25 X	9.97	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	11	1	14.50	25 X	10.87	11.63
75701-T5A-000	EMBLEMH	11	1	10.70	25 X	8.02	8.58
90301-ST0-003	NUTPUSH 3MM	11	2	2.10	25 X	3.15	3.37
04715-T7A-900ZZ	FACE,RR.BUMPER	DD/22	1	463.70	25	347.77	372.11
71593-T7A-J00	SPACER R,RR.BPR S	11	1	16.90	25 X	12.67	13.56
71598-T7A-J00	SPACER,L,RR.BPR S	CPA	1	16.90	25	12.67	13.56
91505-TM8-003	CLIP,BUMPER	11	84	2.30	25	13.60	14.77
					Sum Item	418.92	448.25
BOSUN	SUNDRIES	11	1	50.00	20	50.00	53.50
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	130.00			130.00	139.10
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00			350.00	374.50
BKBU02R	REPLACE RR BUMPER; REPAIR TAILGATE, RR PANEL & 1		1200.00			1200.00	1284.00
BP03R	SPRAY PAINTING ON TAILGATE, RR BUMPER & RR PANEL	1	1500.00			1500.00	1605.00
					Sum Labor	3230.00	3456.10

Survey By

Marcus Loh

Printed on 16/4/2019 10:20:16 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.