1	marcus Solun we		ENT (Office)	Date/Time: 17.4.19 5.36p.n
Estimated Co			Bill to:	pace Time.
To Inspect V	chicle No: P	es/eva/inv/mv/c N GBB	CS Insur	ed: SHA 12585
	m/s Erofia i Bulcit Ne 6	# 02-62	Т	'el: 67527740
Policy No:_			Claim No: D19	102479MFSH
Sum Insured:			Excess:	
Make of Veh				D.O.A. 10.4.247
(Client's Recor	1)   REP.   REV 24   8-4-19   8-579		Lo Lu	H.O.D. Endorsement: Vehicle IN OUT
(Client's Recor CA / REV Date/Time;	/ REP. / REV 24 8-4-19 8-5-4 Action/Instruction	LALENIO		H.O.D. Endorsement:  Vehicle (IN) OUT
(Client's Recor CA / REV Date/Time;	Action/Instruction	Person Contacted:		Vehicle (IN) OUT
(Client's Recor	Action/Instruction	Person Contacted:		Vehicle (IN) OUT

1) : Final Report

Date/Fine, File Return to?

2) >6/4 - typist

Report Format : (ws

Lump Sum / I.B.J.: (\$ 4000 b.

Add Fee: : Site Insp (\$

Weekend (\$

Site Insp (\$ ) \_\_S+RS,\_\_Si
Interview (\$ ) Photos
Tech. Invs (\$ ) Others

Photos 24
Others
TOTAL 304

1

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

D19002479MFSH

Our ref:

CS/FCI19006884/Uvd3

DATE: 22/4/2019

The Motor Claims Department

MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

### INITIAL INSPECTION REPORT OF VEHICLE NO FW 98B

We thank for your instruction on 17/4/2019


Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 18/4/2019 at the premises of M/s EROFIA MOTOR TRADING PTE LTD

Workshop Estimate Amount	: S\$9,312.80	-
Revised Estimate Amount	: S\$5,836.85	
"Check" Items Amount	:S\$	
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the n/s front portion and o/s body

rear



nearside

front


Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA

Licensed Appraiser



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

#### MOTOR SURVEY ASSIGNMENT

Date

11-04-2019

Our Ref No. D19002479MFSH

**Accident Date** 

10-04-2019

Claim Type. Third Party

Insured Vehicle

SHA1258S

Third Party Vehicle. FW98B

Survey Location

1 KAKI BUKIT AVE 6 #02-62

Contact Person.

LEELEE TAN

Contact No.

67527740/0

Fax No. 67528669

Survey Type

WITHOUT PREJUDICE:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

#### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

#### THIRD PARTY SURVEY REQUEST

Cc: Workshop

EROFIA MOTOR TRADING PTE LTD

Attention, NIL

Cc : TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

EILEEN LEE

#### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

### Veron Chen (LKKAuto)

From:

Erofia Motor - LeeLee Tan <erofia@singnet.com.sg>

Sent:

Thursday, 25 April 2019 1:32 PM

To:

Marcus Chua (LKKAuto)

Subject:

finalize for FW98B

Dear Marcus

We confirm accept your finalized amount of S\$4,000.00 cost of repair and 04 repair days for FW98B

Thank you

Regards LeeLee Tan Erofia Motor Trading Pte Ltd

Tel: 67527740 Fax: 67528669

### Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 22 April 2019 2:33 PM

To:

'CWS Motor Claims'; SUR

Cc:

'Eileen Lee'

Subject:

RE: SURVEY ASSESSMENT - D19002479MFSH/1, FW 98B

Attachments:

FW 98B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle FW 98B

Date of survey: 18/4/2019 Number of days: 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 18 April 2019 9:00 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR

<sur@lkkauto.com>

Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg> Subject: RE: SURVEY ASSESSMENT - D19002479MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Wednesday, 17 April, 2019 5:36 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg >; Eileen Lee < EileenLee@msfirstcapital.com.sg >

Subject: PRI: SURVEY ASSESSMENT - D19002479MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards, Admin Team Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

### > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	C' NDIC
Owner ID Type:	Singapore NRIC
Owner ID:	1866E
ehicle Details	T. 4 (0.0 P.
ehicle No.:	FW98B
ehicle to be Exported:	No
ntended Deregistration Date:	18 Apr 2019
/ehicle Make:	HONDA
/ehicle Model:	CB400
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	NC42E1124883
Chassis No.:	JH2NC4295BK300521
Maximum Power Output:	).~
Open Market Value:	\$6,726.00
Original Registration Date:	13 Dec 2013
First Registration Date:	13 Dec 2013
Transfer Count:	1
Actual ARF Paid:	\$1,009.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	*
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,610.00
COE Rebate Amount:	\$748.00
Total Rebate Amount:	\$748.00

The information contained herein is correct as at 18 Apr 2019

OK

REPORT ERROR > (/LISTING/LISTING/ERROR/USEDBIKE/8897/)

+ ADD TO SHORTLIST

Like 0 Share

© SHARE (WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-CB400-SUPER-4-REVO/8897/)

## Honda CB400 Super 4 Revo

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB400 Super 4 Revo (/listing/usedbike/model/honda-cb400-super-4-revo/)
Engine Capacity	399cc
Classification	Class 2A (/listing/usedbike/model/motorcycle-for-sale/class/class-2a/)
Registration Date	11/03/2013
COE Expiry Date	10/03/2023 (3 years 10 months left)
Mileage	80950km
No. of owners	1
Type of Vehicle	Street Bikes (/listing/usedbike/model/motorcycle-for- sale/street-bikes/)

Price: SGD \$13500

#### **DETAILS**

Honda CB400 Revo For Sale. Stock condition. Flawless original paintwork. Viewing at Soon Hin Motors Pte Ltd. Address: Yishun Industrial Park A Block 1018 S768760. Tel 67524893. We accept Trade in and many other brands new and used models available for sale. Installment plans available. No early settlement penalty.

SIMILAR BIKES

VIEW ALL (/LISTING/USEDBIKES/LISTING/)



	Certificate of Insurance
MOTOR VEHICLES (THIRD PARTY RISKS AND MOTOR VEHICLES (THIRD PARTY RISKS AND ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD PARTY RISKS) RUI	COMPENSATION) RULES, 1960 LES, 1959 (MALAYSIA)
Certificate Number : 5068664787-04	Cover : Third Party, Fire & Theft
Index mark and Registration Number of	Vehicle : FW98B
Chassis Number	; JH2NC4295BK300521
Name of Policyholder	: LEE CHEE KEE
Effective Date of Insurance	: 13 Dec 2018
Expiry Date of Insurance	: 12 Dec 2019
5. Persons or Classes of Persons entitled t	o drive#
(a) Named Driver(s) Only.	S. 92 (2.08) \$40V\$233
Provided that the person driving is	permitted in accordance with the licensing or other laws or regulations to drive permitted and is not disqualified by order of a Court of Law or by reason of any half from driving the Motor Vehicle.
6. Limitations as to Use#	
(a) Use for social domestic and pleasu	re purposes and in connection with the Policyholder's business or profession.
This Policy does not cover	
(a) Use for hire or reward.	
(b) Use for racing, pace-making, reliab	ility trial or speed-testing.
<ul><li>(c) Use for the carriage of goods (other</li></ul>	er than samples) in connection with any trade or business.
(d) Use for any purpose in connection	with the Motor Hade.
headings.	e Road Transport Act, 1987 (Malaysia), are not to be included under these
EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A : PLEASE REFER OVERLEAF
EXCESS (THEFT OUTSIDE SINGAPORE)	
INSURE WITH COE	: YES : LEE CHEE KEE
NAMED DRIVER (1)	: NG KIM CHIANG
NAMED DRIVER (2) HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS
Vehicles (Third Party Risks and Compensat	
Countersigned By:	rised Officer Chief Executive

### REPUBLIC OF SINGAPORE

IDENTITY CARD NO. \$1381866E



Name



LEE CHEE KEE

李志基


CHINESE
Date of Brith S
11-05-1959 N
Country of Brith

SINGAPORE









NP 428A

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel: 67527740 Fax: 67528669

Co. Reg No. 201202259N

Owner:

Lee Chee Kee

Vehicle No: FW 98 B

NOF Allul

Accident Date:

10-Apr-19

Vehicle Model:

Honda CB400

**Estimated Repair Costs** 

		Estimated	Kepan Costs	Amount S(\$)
<u>Oty</u>	Description	Telan )	he Attery	Amount S(5)
	<u>List Items</u>	0000	, 1	\$ 600 196.00
1	Front fender		Hdi.	\$ 2 of /tag 620.00
2	Fork inner tubes			\$ 11 640.00 ×
2	Fork outer tubes			\$ del 335.00?
1	Fork under bracket			s 6/5 1/1,120.00 (1)
2	Front brake discs	257.		5 der 68.00
1	Front rim shaft			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
1	Front sport rim	22		
1	Meter	985		1,000.00
1	Handle bar			0/(\$ 2/8 145.00
2	Handle bar ends	30		\$ 5 CAC 60.00 (20
1	Hand grip (1 set)			\$ 11 60.00 ×
1	Side mirror	Oz: F4		#\$ CUT 95.00 12
1	Brake lever			\$ 54 65.00
2	Front signals			\$ 11 370.00 ×
1	Front footrest -R/H	Ĭ.		\$ 647 75.00
1	Front footrest brack	ket -R/H		\$ 245.00
1	Brake pedal			\$ 98.00 X
1	Rear footrest -R/H			\$ 647 70.00 -
1	Exhaust pipe	1000		\$ 70 1,100.00
1	Exhaust pipe prote	* 1		\$ 3/ 70.00
1	Rear signal -R/H			\$ 17 185.00 \
1	Rear tailboard			\$ 335.00
				\$ 8,932.00
			Less 10%	\$ 893.20
				\$ 8,038.80

45265

	Special Nett Items		37
1	Number plate (1 set)	\$ 17	28.00 ×
2	Fork oils	\$ re	30.00
2	Fork oil seals	s ru	56.00
1	Steering cone (1 set)	\$ 20	80.00
1	Side slider (1 set)	\$ 647	120.00
1	Rear box	\$ 577	250.00 200
1	Rear box bracket	\$ 54	100.00
		\$	664.00

S/No.	Labour	30
1	To provide towing service.	\$ 50.00
2	To check wiring and reset headlamp focusing	\$ 1 1 80.00 ×
3	To provide labour.	\$ 480.00 ] 20
900		\$ 610.00

Grand Total

\$

**EROFIA MOTOR TRADING PTE LTD** 

LKKALI's Consentative hence notify the Research this followings • To recurre take water some painting To display demaged parties flusting resurvey
 Participles also in read to confirmation

Third proxy survey or on a "Webo it Prejudice" basis

to darge improposition is moved.

But presentary demiss much be neurologed and is sufficial to final upproved from insurance Company.



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

A DESCRIPTION	Affiliated to Federation Intern	ationale Des Experts En Auton	nobile
AS FIRST CAPITAL II	NSURANCE LTD	Ref : CS/FCI190068	84/Uvd3n2
6 ROBINSON ROAD 16-01 CITY HOUSES	SINGAPORE 068877	Date: 06-05-2019 Code: FCI2	
	Policy Particul	ars :- THIRD PARTY CLA	IM
Insured Veh.	SHA 1258S	Veh. Inspected	FW 98B
Policy No.		Coverage (\$)	0.00
Claim No.	D19002479MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	17/04/2019
2.	Vehicle P	articulars & Condition	
Make & Model	HONDA CB400	c.c	399
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JH2NC4295BK300521	Colour	BLACK
Odometer	26079	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3.	Cor	nditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	120-60 ZR17	BRIDGESTONE	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	160-60 ZR17	BRIDGESTONE	7 mm
L/H Rear Tyre			mm
4.		ription of Damages	
THE VEHICLE S	SUSTAINED DAMAGES AT TH	E O/S BODY AND N/S FROM	IT PORTION.
DAMAGES SEE	DETAILS.		
5.		neral Information	
Accident Date	10/04/2019	Inspection Date	18/04/2019
Survey held a	t EROFIA MOTOR TRADIN	G PTE LTD	
( and	1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a.		Remarks	
A)DAMAGES C	ONSISTENT TO ACCIDENT R TION WAS CONDUCTED ON ANCE TO YOUR INSTRUCTIO	A"WITHOUT PREJUDICE" B	ASIS. RISED REPAIRS.
5b.		mate Days of Repair	
ESTIMATED NO	ORMAL PERIOD FOR REPAIR	4 Working D	ays



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FW 98B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
- 4	FRONT FENDER	CRACKED	196.00	196.00
200	FORK INNER TUBES	BENT / TWISTED	620.00	620.00
350	FORK OUTER TUBES	NOT NECESSARY	640.00	
	FORK UNDER BRACKET	BENT	335.00	335.00
2		O/S BENT	1,120.00	525.00
_	FRONT RIM SHAFT	BENT	68.00	68.00
1	FRONT SPORT RIM	TO REPAIR SEE LABOUR	1,100.00	
1	METER	CUT	1,880.00	985.00
4	HANDLE BAR	BENT	145.00	145.00
2		O/S SCRATCHED	60.00	30.00
1		NOT NECESSARY	60.00	1.0
4		CUT	95.00	47.50
- 1	BRAKE LEVER	BENT	65.00	65.00
2	FRONT SIGNALS	NOT NECESSARY	370.00	)
	FRONT FOOTREST-R/H	сит	75.00	75.00
	FRONT FOOTREST BRACKET-R/H	BENT	245.00	245.00
	BRAKE PEDAL	TO REPAIR SEE LABOUR	98.00	
-	REAR FOOTREST-R/H	CUT	70.00	70.00
	EXHAUST PIPE	DENTED	1,100.00	1,050.00
	1 EXHAUST PIPE PROTECTOR	BENT	70.00	70.00
	1 REAR SIGNAL-R/H	NOT NECESSARY	185.0	0
	1 REAR TAILBOARD	TO REPAIR SEE LABOUR	335.0	
	LESS 10% DISCOUNT	(	-893.2	
	The state of the s		8,038.8	0 4,073.8
	SPECIAL NETT ITEMS			
. 3	1 SET NUMBER PLATE (SN)	NOT NECESSARY	28.0	
	2 FORK OILS (SN)	NECESSARY	30.0	
	2 FORK OIL SEALS (SN)	NECESSARY	56.0	56.0

Report Ref No. CS/FCI19006884/Uvd3n2



(TO ITS PRE-ACCIDENT CONDITION)

### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET STEERING CONE (SN) SET SIDE SLIDER (SN) REAR BOX (SN) REAR BOX BRACKET (SN)	NECESSARY CUT CUT BENT	80.00 120.00 250.00 100.00	100.00
	LABOUR  TO PROVIDE TOWING SERVICE.  TO CHECK WIRING AND RESET HEADLAMP FOCUSING.  TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF FRONT SPORT RIM, BRAKE PEDAL AND REAR	NOT NECESSARY	50.00 80.00 480.00	35.00
	TAILBOARD.		610.00	355.00
	GRAND TOTAL		9,312.80	5,014.85
	RECOMMENDED COST OF LUMP SUM REPAIRS			4,000.00

Report Ref No. CS/FCI19006884/Uvd3n2

CHUA KANG SENG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part, Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.