



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: SP0000001 / SINGAPORE
Chassis No: MRHFC5650GT001116
License No: SLL5229U
Mileage: 37806
Engine No: R16B21601420

Document No: SVO19046857
Printed By: ANIKKALAI
Order Date: 22. July 2019
Order Time: 10:26:22 AM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TOH GUO WEI OWNER INSURER : FWD ACC DATE: 03/04/2019 SURVEYED BY: HWEE JIE DATE: 21/05/2019 REF NO: TP INSURER: SPF TP VEH: QX701H						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	1	2.30	25	1.72	0.12	1.84
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	0	164.70	25	0.00	0.00	0.00
	SUM PARTS:				509.16	35.63	544.79
BKBU02R	1466 REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON ATTACHMENT ITEMS	1	560.00		560.00	39.20	599.20
BP01R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(1P)	1	450.00		450.00	31.50	481.50
BOSUN	1718 SUNDRIES	1	20.00		20.00	1.40	21.40
BA02R	1466 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	80.00		80.00	5.60	85.60
	SUM LABOUR:				1,110.00	77.70	1,187.70
	TOTAL SGD				1,619.16	113.33	1,732.49
	Total Payable (SGD)						1,732.49

GST Amount is calculated from individual line(s)