

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT
 SINGAPORE 638129
 Tel No. : 6863-9595 Fax No. : 6863-6477
 E-Mail : sinsheng1981@gmail.com
 Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
 59 SENOKO ROAD
 SINGAPORE 758123

Attention : Motor Claim Department
 Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002825

Date : 23/04/2019
 Vehicle Num. : GBH7027L
 Make/Model : TOYOTA KDY 231-2018
 Chassis/Eng# : KDY2318033649/1KD2796373
 Accident Date : 15/04/2019
 Claim No. :
 Reference : SHA1363X
 Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount SS
		LIST ITEMS :		
1.	1	REAR LAMP, LHS		293.50
2.	1	REAR LAMP BRACKET		145.20
3.	1	REFLECTOR		45.20
		List TotalSS :		483.90
		25.00% Discount SS :		120.98
				362.92
		LABOUR :		
		TO PANEL BEAT/REPAIR REAR BODY		250.00
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		SPRAY PAINTING		200.00
		LOSS OF USE : 2 DAYS @ \$ 120/DAY		
		Labour Total SS :		450.00



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:
Date:

Total SS : 812.92

Tanpin 97495749
 - wp' 23/4/19 e4pm
 2 days
 Resurvey new parts
 sure lkkauto.com.

SIN SHENG ENGINEERING SERVICES