

INS. CASE OWNER:

CC 6 / QBE 1900 6932 / A

LEK:

IDAC:

Surveyor:

Adrian.

DOI:

ASSIGNMENT

17/04/2019

Date / Time:

17/4/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

SJS 4470 G

Claim No.

UC012610

Name of Insured

UTIMAX LEASING PTE LTD

Policy No.

Insured Tel No.

HP:

Make / Model

Excess Sec II :SS

D.O.A:

14/04/2019

Place of Accident

Is driver the owner?

(YES / NO)

Nature of Accident

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO

YES

NO

TP GIA REPORT: YES / NO

YES

NO

Insured Liability:

%

Final ? Yes / No

SLT 28354



INSRS:

WSP: MG Solution

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SLT 28354 - X

SJS 4470G - X

STAGE

DATE / PIC

*TP video in.
*Liability down against Insured;
*e-mailed video to ABE (Yenny)

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 17/4/19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PER:

Mandate / Reject Instruction:

LOD

Payment Breakdowns Form:

Post-Repair Photos:

Others:

20/6/19
C. Chua

File pass to type mandate

17/2/2020
C. Chua

File pass to mk to close.

- OV - 2 "anti"

RELIMINARY ADVICE Date/Time:

Sent By:

INITIALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 45 \$S 2,550 (5 days) Reduction: 55%

Email ☐ Call ☐

INITIAL SETTLEMENT

Date/Time:

Confirm with Su Wong

Email ☒ Call ☐

Initial Liability: % 100 (Agreed / Assessed) BOLA S/N No.: N/A

If NO or B 28, Ass. Lia:

Repair Cost: (445T) \$S 2,728.50

COI IN BETWEEN TWO LINES
AND COLLIDED INTO TRUCK

Loss of Rental (LOR): \$S - (- days)

Loss of Use (LOU): \$S 1,600 (\$200 x 8 days)

Loss of Income (LOI): \$S - (\$ - x - days)

OR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

LTA Search \$S 7.45

Medical: \$S -

Insurance: \$S - (e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

Repair Cost \$S -

2) Report Format:

Total: \$S 4,335.95 Global Sum \$S:

3) Survey fee: \$400

INITIAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Copy 1: \$S 4,335.95

Name 1: MG SOLUTION PTE LTD

Copy 2: (Stikes if N.A.)

Name 2:

Copy 3: (Stikes if N.A.)

Name 3:

COPY SENT

- OV 2 "anti"

ASS. REC. BY:

REF:
226Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
Person Contacted: _____Veh No: SLT 283SY Yr Regn: 2017, OctType: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda City c.c. 1497Colour: Grey A/C: Insured / Std / Nil / NASp. Reading: 27470 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MRH6M6660JT000124Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 185/55R16R: 185/55R16B3 / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.L. 17/04/19Survey held at MG SolutionDes. of Damages: Frt / Rear / O/S (N/S) / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP QBE.C L/S \$ 2,550 / Red \$ 3,151.60 / 55%.

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1) _____ 2) _____

3) _____ 4) _____

5) _____ 6) _____

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, \$

Photos

Others

TOTAL

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: QBE INSURANCE	DATE	: 16-Apr-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLT 2835 Y		
MODEL	: HONDA CITY 1.5		MRH6M660J7000124
CHASSIS NO			Ashes
<u>ACCIDENT DETAILS</u>		DATE	: 14-Apr-19
		TIME	: 20:50HRS
THIRD PARTY REQUESTOR / CONTACT : DEON			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT CENTRE PILLAR <i>Painted</i>	1	\$ 850.00	\$ 850.00
2	REAR DOOR LH <i>Painted</i>	1	\$ 1,050.00	\$ 1,050.00
3	REAR DOOR STICKER LH <i>new</i>	1	\$ 90.00	\$ 90.00
4	REAR DOOR HANDLE CHROME GARNISH LH <i>new</i>	1	\$ 170.00	\$ 170.00
5	REAR DOOR HINGE(UPPER) <i>Painted</i>	1	\$ 72.00	\$ 72.00
6	REAR DOOR HINGE(LOWER)	1	\$ 72.00	\$ 72.00
7	REAR DOOR OUT PROTECTOR <i>new</i>	1	\$ 92.00	\$ 92.00
8	REAR DOOR LOCK <i>new</i>	1	\$ 250.00	\$ 250.00
9	REAR DOOR WEATHERSTRIP <i>new</i>	1	\$ 211.00	\$ 211.00
10	REAR DOOR INNER BOARD <i>Painted</i>	1	\$ 380.00	\$ 380.00
11	REAR DOOR POWER WINDOW MOTOR <i>new</i>	1	\$ 310.00	\$ 310.00
12	REAR DOOR POWER WINDOW REGULATION <i>Painted</i>	1	\$ 230.00	\$ 230.00

2365

1892

TOTAL PRICE \$ 3,777.00

LESS 20% \$ 755.40

SUB TOTAL PRICE \$ 3,021.60

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

1	REAR DOOR INNER TRIM BOARD CLIP (SET) <i>Alm</i>	1	\$ 30.00	\$ 30.00
			<i>30</i> TOTAL	\$ 30.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	<i>260.600</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>260.600</i>	
3	TUFF COAT	\$ 250.00	<i>X</i>	
4	WIRING CHECK	\$ 80.00	<i>30</i>	
5	REMOVE AND REFIX REAR DOOR MECHANISM	\$ 120.00	<i>80</i>	

TOTAL

\$2,650.00

1310

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,051.60

TOTAL LABOUR COST : \$ 2,650.00

TOTAL REPAIR COST : \$ 5,701.60

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lim Total: 3232
4/5 17/04/19 4/5: 2550
0.5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Shu Pei (LKKAUTO)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Monday, 15 July 2019 2:49 PM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SJS4470G (OI : QBE - TBA) AND SLT2835Y (TP : LKK REF - CC6/QBE19006932/Aeb3) on 14.04.2019
Attachments: SAS.PDF

Our ref: VC012610

Dear Shu Pei

Please find attached as per requested.

regards

Jenny Toh

Senior Assistant

Claims / Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6224 6633 | +65 6477 1225

[Website](#) [LinkedIn](#) [Twitter](#)



From: Jenny Toh

Sent: Monday, 15 July 2019 9:17 AM

To: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SJS4470G (OI : QBE - TBA) AND SLT2835Y (TP : LKK REF - CC6/QBE19006932/Aeb3) on 14.04.2019

Hi Shu Pei

Till date our insured had yet to report the accident, we have sent another chaser.

regards

Jenny Toh

Senior Assistant

Claims / Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6224 6633 | +65 6477 1225

[Website](#) [LinkedIn](#) [Twitter](#)



From: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>

Sent: Monday, 15 July 2019 8:49 AM

To: Jenny Toh <jenny.toh@qbe.com>

Subject: RE: Direct Settlement - Accident Involving SJS4470G (OI : QBE - TBA) AND SLT2835Y (TP : LKK REF - CC6/QBE19006932/Aeb3) on 14.04.2019

Dear Jenny,

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)

Sent: Thursday, 4 July 2019 9:45 AM

To: Jenny Toh <jenny.toh@qbe.com>

Subject: RE: Direct Settlement - Accident Involving SJS4470G (OI : QBE - TBA) AND SLT2835Y (TP : LKK REF - CC6/QBE19006932/Aeb3) on 14.04.2019

Dear Jenny,

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)

Sent: Friday, 28 June 2019 9:00 AM

To: Jenny Toh <jenny.toh@qbe.com>

Subject: RE: Direct Settlement - Accident Involving SJS4470G (OI : QBE - TBA) AND SLT2835Y (TP : LKK REF - CC6/QBE19006932/Aeb3) on 14.04.2019

Dear Jenny,

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Friday, 21 June 2019 9:29 AM

To: 'Jenny Toh' <jenny.toh@qbe.com>

Subject: RE: Direct Settlement - Accident Involving SJS4470G (OI : QBE - TBA) AND SLT2835Y (TP : LKK REF - CC6/QBE19006932/Aeb3) on 14.04.2019

Dear Jenny,

Noted with thanks.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Toh <jenny.toh@qbe.com>

Sent: Friday, 21 June 2019 9:22 AM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SJS4470G (OI : QBE - TBA) AND SLT2835Y (TP : LKK REF - CC6/QBE19006932/Aeb3) on 14.04.2019

Hi Shu Pei

Our insured had yet to report, once we got it will forward to you.

regards

Jenny Toh

Senior Assistant

Claims / Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6224 6633 | +65 6477 1225

[Website](#) [LinkedIn](#) [Twitter](#)



From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Thursday, 13 June 2019 11:52 AM
To: Jenny Toh <jenny.toh@qbe.com>
Subject: RE: Direct Settlement - Accident Involving SJS4470G (OI : QBE - TBA) AND SLT2835Y (TP : LKK REF - CC6/QBE19006932/Aeb3) on 14.04.2019

Dear Jenny,

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Thursday, 13 June 2019 10:27 AM
To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving SJS4470G (OI : QBE - TBA) AND SLT2835Y (TP : LKK REF - CC6/QBE19006932/Aeb3) on 14.04.2019

Our ref: VC012610

Dear Shu Pei

We refer to this matter.

Our insured informed us that their driver was not involved in this accident. you may request third party for the evidence of claim.

regards

Jenny Toh

Senior Assistant

Claims / Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6224 6633 | +65 6477 1225

[Website](#) [LinkedIn](#) [Twitter](#)



From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 14 May 2019 9:44 AM
To: Jenny Toh <jenny.toh@qbe.com>

Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SJS4470G (OI : QBE - TBA) AND SLT2835Y (TP : LKK REF - CC6/QBE19006932/Aeb3) on 14.04.2019

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Monday, 22 April 2019 6:47 PM

To: 'Jenny Toh' <jenny.toh@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: Direct Settlement - Accident Involving SJS4470G (OI : QBE - TBA) AND SLT2835Y (TP : LKK REF - CC6/QBE19006932/Aeb3) on 14.04.2019

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SLT 2835Y at M/s MG Solution Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupej@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

PROFORMA BILL

Bill To:

QBE INSURANCE (INTERNATIONAL) LTD

NO.60 ANSON ROAD

#11-01 MAPLETREE ANSON

SINGAPORE 079914

Bill No : 198183

Date : 30-May-2019

Vehicle Number : SLT 2835Y

ATTN : MOTOR CLAIMS DEPARTMENT

QTY	CLAIM	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 2,550.00
BEFORE GST		2,550.00
7% GST		178.50
TOTAL		\$ 2,728.50

Tax Invoice will be issue upon amount finalised.

Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis with sole intention of resolving the matter amicably without parties resorting to legal proceeding. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.



Co's stamp & Authorised Signature

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 4 December 2019 9:36 AM
To: MG Solution
Cc: Admin A
Subject: RE: Accident involving SLT 2835Y (TP) & SJS 4470G (QBE) on 14/04/2019
Attachments: QBE DV.pdf

Without Prejudice

Dear Sir/Madam,

We refer to the above matter and your e-mail below.

We confirm settlement as per your LOD on this matter.

We attach herewith a copy of the DV for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: MG Solution <mg3solution@gmail.com>

Sent: Thursday, 12 September 2019 11:52 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: Accident involving SLT 2835Y (TP) & SJS 4470G (QBE) on 14/04/2019

Your Ref: **SJS4470G**

Our Ref: **SLT2835Y**

Dear Khanchna,

We refer to below email, we already sent the cctv footage to your Admin-Ms Shu Pei on 19/06/2019. Please find attached cctv footage and photo for your reference.

Best Regards,

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

MOTOR CLAIM DISCHARGE

INSURED: ANG LYE BENH
CAR/LORRY/CYCLE: REG NO: SLT 2835Y POLICY NO: _____
ACCIDENT CLAIM NO: _____

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle

Registered No. SLT 2835Y from the repairers,
Messrs MG SOLUTION PTE LTD

And that all repairs necessary as a result of an accident in which the said vehicle was involved on or
about the 14 day of 04 2019 have been completed to my / our satisfaction, and that
I / we have no further claim on the above company in Respect thereof.

Date: _____ Signature: X

Co's Stamp: _____ NRIC No: _____

16/04/2019. 11:11

19/04/2019. 11:11 (Completed)

19/04/2019. 11:11

16/04/2019. 11:11

19/04/2019. 11:11

19/04/2019. 11:11

19/04/2019. 11:11

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC6/QBE19006932/Aka3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 19-02-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 4470G	Veh. Inspected	SLT 2835Y
Policy No.	8-V0018019-MVA	Coverage (\$)	0.00
Claim No.	VC012610	Excess (\$)	0.00
Assign From		Assign Date	17/04/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CITY	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MRHGM6660JT000124	Colour	GREY
Odometer	27470	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/04/2019	Inspection Date	17/04/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 2835Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT CENTRE PILLAR	DENTED	850.00	615.00
1	REAR DOOR LH	DENTED	1,050.00	906.00
1	REAR DOOR STICKER LH	NECESSARY	90.00	90.00
1	REAR DOOR HANDLE CHROME GARNISH LH	NOT NECESSARY	170.00	-
1	REAR DOOR HINGE (UPPER)	BENT	72.00	72.00
1	REAR DOOR HINGE (LOWER)	BENT	72.00	72.00
1	REAR DOOR OUT PROTECTOR	NOT NECESSARY	92.00	-
1	REAR DOOR LOCK	NOT NECESSARY	250.00	-
1	REAR DOOR WEATHERSTRIP	NOT NECESSARY	211.00	-
1	REAR DOOR INNER BOARD	CRACKED	380.00	380.00
1	REAR DOOR POWER WINDOW MOTOR	NOT NECESSARY	310.00	-
1	REAR DOOR POWER WINDOW REGULATION	DAMAGED	230.00	230.00
	LESS 20% DISCOUNT		-755.40	-473.00
			3,021.60	1,892.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR DOOR INNER TRIM BOARD CLIP (SN)	NECESSARY	30.00	30.00
			30.00	30.00
	<u>LABOUR</u>			
	PANEL BEATING .REMOVING AND REPLACING PARTS.		1,200.00	600.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	600.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK .		80.00	30.00
	REMOVE AND REFIX REAR DOOR MECHANISM .		120.00	80.00
			-	-
			-	-
			-	-
			2,650.00	1,310.00
	GRAND TOTAL		5,701.60	3,232.00

Report Ref No. CC6/QBE19006932/Aka3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00
---	--	--	----------

Report Ref No. CC6/QBE19006932/Aka3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.