



After Sales Liability Check.

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH	L1	GRL10R	21/06/2013	SFZ8778D	0	17077 :4TP/SFZ8778D/16041!
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019	4.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN:16.04.19 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 80.00
2	Z	BP-SUNDRY TOWING IN CHARGE.				380.00
3	B	BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT)				216.50
4	B	BP-LAB3 REMOVE/REFIX FRONT PARKING SENSORS. (NETT)				216.50
5	B	BP-MECH3 REMOVE/REFIX AIR-CON CONDENSER, RECEIVER DRYER, GAS PIPES TO ENABLE REPAIRING, REFIT AND REGAS.				? 866.00
6	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS AND FIT NEW PARTS.				2598 3464.00
7	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1855 2597.00
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2019
TIME 10:55

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR 8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETON L1	GRL10R	21/06/2013	SFZ8778D	0	17077	4TP/SFZ8778D/16041

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019	4.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
8	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
9	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)				216.50
10	L	BP-LPO SUPPLY REGN PLATE (PO#)				ms 96.00
		FRONT (NETT)				
11	1	L53301-30491 HOOD SUB-ASSY <i>sch</i>	1.00	2754.60		2754.60
12	2	T90467-09050 CLIP <i>sch</i>	11.00	2.40		26.40
13	3	L11293-31120 LABEL, ENGINE <i>sch</i>	1.00	4.20		4.20
14	4	T88723-42070 LABEL, COOLER <i>sch</i>	1.00	3.60		3.60
15	5	L53805-30203 SHIELD SUB-ASSY, ?	1.00	336.80		336.80
16	6	L53806-30203 SHIELD SUB-ASSY, LH	1.00	349.50		349.50
17	7	L53879-50010 RETAINER, FR FENDER X	12.00	2.90		34.80
18	8	T90467-07214 CLIP X	10.00	2.20		22.00
19	9	L81145-30F60 UNIT, HEADLAMP RH <i>sch</i>	1.00	3735.30		3735.30
20	0	L81185-30F60 UNIT, HEADLAMP LH <i>sch</i>	1.00	3735.30		3735.30
21	1	L53119-30260 PROTECTOR RADIATOR	1.00	66.10		66.10
22	2	L53111-30D90 GRILLE, RADIATOR <i>sch</i>	1.00	981.30		981.30
23	3	L53115-30070 BRACKET, GRILLE <i>sch</i>	1.00	24.70		24.70
24	4	T53149-46010 PROTECTOR, RADIATOR	1.00	3.10		3.10
25	5	L90975-02125 EMBLEM, SYMBOL <i>sch</i>	1.00	472.10		472.10
26	6	L52711-30270 MOULDING, RADIATOR GR <i>sch</i>	1.00	379.20		379.20

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2019
TIME 10:55

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH	L1	GRL10R	21/06/2013	SFZ8778D	0	17077 :4TP/SFZ8778D/16041'

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019 4.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
27	7	S52161-OK040 BUMPER CLIPS <i>new</i>	9.00	4.00		36.00
28	8	L52535-30230 RETAINER, FR BUMPER <i>new</i>	1.00	74.20		74.20
29	9	L52536-30220 RETAINER, FR BUMPER <i>new</i>	1.00	74.20		74.20
30	0	L52115-30150 SUPPORT, FR BUMPER <i>new</i>	1.00	63.80		63.80
31	1	L52116-30100 SUPPORT, FR BUMPER <i>new</i>	1.00	63.80		63.80
32	2	L52115-30140 SUPPORT, FR BUMPER <i>new</i>	1.00	35.50		35.50
33	3	L52116-30090 SUPPORT, FR BUMPER <i>new</i>	1.00	35.50		35.50
34	4	L52611-30420 ABSORBER, FR BUMPER <i>new</i>	1.00	126.00		126.00
35	5	L52119-3A932 COVER, FR BUMPER <i>new</i>	1.00	965.40		965.40
36	6	L52421-30110 PAD, FR BUMPER <i>new</i>	1.00	5.90		5.90
37	7	L52129-30907 COVER, FR BUMPER <i>new</i>	1.00	20.90		20.90
38	8	L53112-30240 GRILLE, RADIATOR LWR <i>new</i>	1.00	183.50		183.50
39	9	L52114-30230 BRACKET, EXTENTION <i>new</i>	1.00	159.20		159.20
40	0	L53141-30160 GARNISH, RADIATOR <i>new</i>	1.00	69.60		69.60
41	1	L53142-30060 GARNISH, RADIATOR <i>new</i>	1.00	79.60		79.60
42	2	L81481-30110 COVER, FOG LAMP RH <i>new</i>	1.00	90.80		90.80
43	3	L81482-30150 COVER, FOG LAMP LH <i>new</i>	1.00	90.80		90.80
44	4	L52535-50060 FRT BUMPER RETAINER, <i>new</i>	2.00	8.70		17.40
45	5	L53879-30050 RETAINER, FR FENDER <i>new</i>	4.00	16.80		67.20
46	6	L47749-50090 CLIP <i>new</i>	4.00	1.50		6.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2019
TIME 10:55

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : MR 8500000-9www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH	L1	21/06/2013	SFZ8778D	0	17077	4TP/SFZ8778D/16041

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019	4.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
47	7	T81210-0D042 R/FRT FOG LAMP ASSY	1.00	306.30		306.30
48	8	T81220-0D042 L/FRT FOG LAMP ASSY	1.00	306.30		306.30
49	9	L85353-30090 B1 COVER, HEADLAMP	1.00	14.10		14.10
50	0	L85207-30060 ACTUATOR SUB-ASSY	1.00	586.00		586.00
51	1	L89341-76010 B3 SENSOR, ULTRASONIC	2.00	490.80		981.60
52	2	L89348-30030 B1 RETAINER, ULTRASONIC	4.00	21.70		86.80
53	3	L89348-35030 CLIP, ULTRASONIC	2.00	3.70		7.40
54	4	L82114-30200 WIRE, ENGINE ROOM	1.00	122.80		122.80
55	5	L53217-30903 BRACE, HOOD LOCK	1.00	79.60		79.60
56	6	L53153-30200 GUIDE RADIATOR	1.00	106.40		106.40
57	7	L53154-30190 GUIDE RADIATOR	1.00	99.70		99.70
58	8	L53289-30180 COVER RADIATOR	1.00	586.70		586.70
59	9	T90467-07217 CLIP	11.00	2.10		23.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

No illegal modification(s) is allowed.

is subject to final approval from Insurance Company.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	26,733.60
Acknowledged by Repairer Signature:	Please acknowledge receipt of vehicle	Parts 18,501.10	GST 7.00%	1,871.35
Date:		Labour 8,136.50	Less	0.00
		Materials 96.00		
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	28,604.95

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 17/04/2019

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

TIME 10:56

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motors