

Surveyor:

KSL

DOI:

ASSIGNMENT

2314/19

Date / Time:

21/4/19

Registered in Merimen:

21/4/19

Pre-assign / CCU / FTE

SMD 7470



Insured Vehicle No.:

Name of Insured:

YMP YIP HAN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

21/4/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SME 928 T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Rally Pitstop



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

4/2/19 - FILE PASS TO HMR TO CLOSE

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

> 19/6/19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

26/6/19

Confirm with:

Terrence Lim

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

3849.03

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

300.00

(\$

60

x

5

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

4149.03

Global Sum S\$:

1) Claim status: Not/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$320

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4149.03

Name 1:

Rally Pitstop

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

21/7/19

Surveyor

REF:

A19

ASSIGNMENT

From: Date: 23/4/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SME 928T

at Workshop m/s

of 176 Sin Ming Drive # 04-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

temme @ 91005500

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SME 928T

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Ty Pion

cc

1496

Colour:

M. Pink

A/C: Insured / Std / NI / NA

Sp. Reading

4857

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MHF 228H3100056483

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

R:

195/50R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

1/19

D.O.I.

23/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

GIA not ready

P/P - \$3849.03 (Reo \$2681.71 / 41%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Returns to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

RALLY PITSTOP

176 Sin Ming Drive
#04-17 Sin Ming Autocare
Singapore 575721
Tel: 64516985
Email: tar6985@hotmail.com

Date: 22-04-20189

To: Motor Claims Department

RE: Estimate repair cost of SME928T

Your insured: SMD747D

Dear Sir/Madam,
Vehicle No: SME928T
Make Model: Toyota Sienta 1.5
Date of accident: 21-04-2019

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Qty	Description	Unit Price	TOTAL
1	Rear bumper <i>495-90</i>	<i>Buy</i> 953.20	
2	Rear bumper retainer <i>also 11</i>	96.2	196.40
1	Rear bumper top garnish	<i>Ref</i>	425.80
1	Rear bumper side garnish LH <i>269.</i>	<i>CR</i>	389.10
5	Rear bumper clips	3 <i>Ref</i>	15.00
1	Boot lid <i>1180</i>	<i>By</i>	1358.50
1	Boot lid upper lock		<i>R</i> 121.30
1	Boot lid Toyota logo		<i>Ref</i> 38.30
2	Rear windscreen moulding	95.3	<i>Ref</i> 190.60
1	Rear end panel <i>590</i>		<i>R</i> 658.30
1	Rear end panel inner garnish		<i>Ref</i> 225.80
1	Weather stripe	<i>Ref</i>	221.30
1	Reverse sensor LH		<i>Ref</i> 234.80
1	SIENTA' emblem		<i>Ref</i> 89.80
1	Rear end panel key sensor <i>180</i>	<i>Ref</i>	232.80
	Sub-total before discount		5351.00
	Parts percentage discount 20% <i>259</i>		1070.20
	PARTS TOTAL		4280.80
	LABOUR CHARGES & MISC		
1	Labour to dismantle, panel beat, repair & replace rear bumper, boot lid, rear end panel & all the necessary parts		1200.00
2	To remove and refit rear windscreen		150.00
3	To putty and spray paint		800.00
4	To check wiring		50.00
5	To provide undercoating		50.00
	LABOUR TOTAL		2250.00
	LABOUR & PARTS TOTAL		6530.80

Regards,
Terrence Lim

- To receive additional spray painting
- To display additional artwork during recovery
- Part person is subject to confirmation
- Third party agency is a "Without Prejudice" basis
- No direct payment is allowed
- Customer may be advised by recovery and
- It is not a requirement from Insurance Company

176 Sin Ming Drive
#04-17 Sin Ming Autocare
Singapore 575721
Tel: 64516985
Email: tar6985@hotmail.com

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Qty	Description	Unit Price	TOTAL
1	Rear bumper		953.20
2	Rear bumper retainer	98.2	196.40
1	Rear bumper top garnish		425.80
1	Rear bumper side garnish LH		389.10
5	Rear bumper clips	3	15.00
1	Boot lid		1358.50
1	Boot lid upper lock		121.30
1	Boot lid Toyota logo		38.30
2	Rear windscreen moulding	95.3	190.60
1	Rear end panel		658.30
1	Rear end panel inner garnish		225.80
1	Weather stripe		221.30
1	Reverse sensor LH		234.80
1	SIENTA' emblem		89.80
1	Rear end panel key sensor		232.80
	Sub-total before discount		5351.00
	Parts percentage discount 20%		1070.20
	PARTS TOTAL		4280.80
	LABOUR CHARGES & MISC		
1	Labour to dismantle, panel beat, repair & replace rear bumper, boot lid, rear end panel & all the necessary parts		1200.00
2	To remove and refit rear windscreen		150.00
3	To putty and spray paint		800.00
4	To check wiring		50.00
5	To provide undercoating		50.00
	LABOUR TOTAL		2250.00
	LABOUR & PARTS TOTAL		6530.80

Regards,
Terrence Lim

[illegible]

Jia Le (LKK Auto)

From: Terrence Lim <tar6985@hotmail.com>
Sent: Wednesday, 26 June 2019 11:22 AM
To: Jia Le (LKK Auto)
Subject: Re: SME928T after repair photos
Attachments: SME928T aut.letter 001.jpg

Thanks & Regards,
Terrence Lim
91005500

From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Sent: Wednesday, June 26, 2019 11:15 AM
To: Terrence Lim
Subject: RE: SME928T after repair photos

WITHOUT PREJUDICE

Dear Terrence,

Please let us have the Authorization to Act sign by your client.

Thank you.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Terrence Lim [mailto:tar6985@hotmail.com]
Sent: Wednesday, 26 June 2019 11:10 AM
To: Jia Le (LKK Auto)
Subject: Re: SME928T after repair photos

hi
DV attached.

Thanks & Regards,
Terrence Lim
91005500

From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Sent: Tuesday, June 25, 2019 5:48 PM

To: Terrence Lim
Subject: RE: SME928T after repair photos

Without Prejudice

Dear Sir/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 3,849.03
2. Loss of Use (5days x \$60)	\$ 300.00
TOTAL	\$ 4,149.03

Please duly sign the DV enclosed and return with Authorization to Act together to us.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jia Le (LKK Auto)
Sent: Tuesday, 25 June 2019 2:10 PM
To: Terrence Lim
Subject: RE: SME928T after repair photos

WITHOUT PREJUDICE

Dear Sirs/Mdm,

ACCIDENT INVOLVING SMD 747D & SME 928T ON 28/04/2019

We refer to the above matter.

We propose settlement at a global sum of **\$4,100.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Terrence Lim [<mailto:tar6985@hotmail.com>]

Sent: Tuesday, 25 June 2019 9:02 AM

To: Jia Le (LKK Auto)

Subject: Re: SME928T after repair photos

Hello

1 month pass since we sent you the LOD, if we never heard from your side by today regarding the DV we'll pass this case to lawyer.

Regards

Terrence Lim

----- Original message -----

From: "Jia Le (LKK Auto)" <JiaLe@lkkauto.com>

Date: 24/06/2019 12:55 (GMT+08:00)

To: Terrence Lim <tar6985@hotmail.com>, "Asher Sng (LKKAuto)" <AsherSng@lkkauto.com>

Subject: RE: SME928T after repair photos

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SMD 747D(AIG) AND SME 928T ON 24/06/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Terrence Lim [<mailto:tar6985@hotmail.com>]

Sent: Monday, 24 June 2019 12:38 PM

To: Jia Le (LKK Auto); Asher Sng (LKKAuto)

Subject: Re: SME928T after repair photos

Hi Jia Le,

Please let us hear from you by today.
Our last email to you was 24/5/19.

Thank you.

Regards,
Angela Tang
90494578

On 21 Jun 2019, at 1:54 PM, Asher Sng (LKKAuto) <AsherSng@lkkauto.com> wrote:

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Angela,

We refer to the email below.

The current case handler for this case is Jia Le.

She will look into the matter and settle with you soon.

Hi Jia le,

Kindly assist.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

From: Terrence Lim <tar6985@hotmail.com>
Sent: Friday, 21 June 2019 11:35 AM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: Re: SME928T after repair photos

Dear Asher,

We have yet to hear from you since our last email to you dated 24/05/2019.

Please advise if you are doing direct settlement with us or shall we pass to our lawyer to settle with AIG with the settlement?

Please let us hear from you by today.

Thanks & Regards,
Angela Tang
90494578

From: Terrence Lim <tar6985@hotmail.com>
Sent: Friday, May 24, 2019 12:15 PM
To: Asher Sng (LKKAuto)
Subject: Fw: SME928T after repair photos

Dear Asher,

Attached herewith our LOD & Repair Invoice.
Please assist.

Thanks & Regards,
Terrence Lim
91005500

From: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Sent: Tuesday, May 21, 2019 9:24 AM
To: Terrence Lim
Subject: RE: SME928T after repair photos

Attach finalised for SME 928T.

From: Terrence Lim [<mailto:tar6985@hotmail.com>]
Sent: Thursday, 2 May, 2019 10:39 AM
To: Kenneth Kong (LKKAuto)
Subject: SME928T after repair photos

Regards
Terrence Lim

RALLY PITSTOP

176 Sin Ming Drive,
#04-17 Sin Ming Autocare
Singapore 575721
Tel: 6451 6985
Email: tar6985@hotmail.com

Your ref: MT/1038510-002

Our ref: SME928T

90494578 (Rally Pitstop)

Date: 23 May 2019
AIG
Motor Claims Division

Dear Sir/Madam,

Accident involving SMD747D (AIG) and SME928T on 28-04-2019

We are the authorized repair workshop for the owner of motor vehicle: **SME928T** which was involved in the captioned accident with your insured vehicle: **SMD747D**. The vehicle owner has requested and authorized us to assist him in presenting his claim against the party responsible for the damage to the vehicle. As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

Cost of Repair	\$	3,849.03
LOU 6days @ \$60/day <i>5 days x \$60</i>	\$	360.00
TOTAL	\$	4,209.03

4,209.03

We enclosed herewith the following documents to support the claims: -

Repair Invoice
LOD

Kindly look into the matter and let us hear from you on the settlement of our client's claims as soon as possible.

Thank you.

Yours Sincerely,
Terrence Lim

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Wednesday, 19 June 2019 3:23 PM
To: JIMMYAP48@GMAIL.COM
Subject: ACCIDENT INVOLVING SMD 747D & SME 928T ALONG/AT BISHAN RD NEAR TRAFFIC LIGHT ANG MO KIO AVE 8 ON 21/04/2019

Our Ref: CC4/AIG19007079/Kda3

19 JUNE 2019

YAP YIAN HUAT
161 KILLINEY RD
#10-05
SINGAPORE 239569

Dear Sir/Madam,

ACCIDENT INVOLVING SMD 747D & SME 928T ALONG/AT BISHAN RD NEAR TRAFFIC LIGHT ANG MO KIO AVE 8 ON 21/04/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SME 928T against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head to rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Authorization Letter

To: RALLY PITSTOP

RE: ACCIDENT INVOLVING VEHICLE SME 948T & SMD 787D

ALONG/AT Ang Mo Kio Ave 8

ON 21/04/2019

Please act for me/us in respect of the abovementioned matter. I/We hereby authorize you:-

- a. To apply for the Accident Report from GIARMC and all other relevant documents on my behalf.
- b. To commence repair of my vehicle forthwith.
- c. To claim, settle, receive whatever amount payable by the insurance company and/or third party and to commence legal proceedings, in my/our name, for the costs of repairs, loss of use, etc and to you appoint a Solicitor to act for me/us in respect of the accident.
- d. To sign all discharge vouchers/indemnity forms and all necessary papers in connection with the above claim for and on my/our behalf.
- e. To appoint such a firm of Solicitors on my/our behalf as you shall deem fit for the purpose of the third party insurer's claim.
- f. To inform you and/or the Solicitor appointed by you on my behalf in the event the third party's insurance company communicate with me/us orally or in writing and I further undertake not to accept any monies or offer of settlement from the third party's insurers without first communicating with you and obtaining your consent.
- g. To co-operate fully with you and the Solicitor appointed to see the claim to a successful conclusion.

Dated this 22 day of 04 2019

 TAN HEC CHONG
Owner's Signature / Name / NRIC S2104178E
Company Stamp

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, RALLY PITSTOP ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,849.03 (Repair Cost), S\$300.00 (Loss of Use/Rental), S\$ - (Disbursement) for vehicle no. SME 928T that was damaged pursuant to the accident which occurred on 11/04/2019 (date) along ANG MO KIO AVENUE 8 (location) involving vehicle no/s SMD 747D. This is pursuant to the inspection conducted on 23/04/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN HEE CHONG ("the third party claimant") of vehicle no. SME 928T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SME 928T (vehicle no.) as a result of the accident. excludes bodily injury

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 26 (day) of 06 (month) 2019 (year)



ksc

Signed by appointed surveyor



Signed by "the workshop" (with chop)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane







CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Apr 2019 Edit Reg		22 Apr 2019 00:00 Edit Adj Rpt	S\$3,849.02 Edit Estimates	S\$3,849.02 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	YAP YIAN HUAT, ID: S0158118Z								
Main Claimant:	TAN HEE CHONG, ID: S2104178E								
Vehicle Reg. No.:	SME928T	Date of Loss:	21/04/2019 00:00 - :59 [7 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6256564912SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SMD747D	Policy No. (Claimant):	CN013969						
		Excess:							
Repairer:	Rally Pitstop (HQ) 176 SIN MING DRIVE #04-17 SINMING AUTO CARE, 787525 Sin Ming - Tel: 64516985								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 02/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SME928T (6256564912SG)
[SMD747D]
TP
TAN HEE CHONG
Apr 21 2019 12:00AM
[YAP YIAN HUAT]
Rally Pitstop

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
2	02/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
3	02/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
4	02/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
5	02/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
6	02/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
7	02/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
8	02/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
9	02/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
10	02/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
11	02/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/04/19 19:57	ACKNOWLEDGEMENT EMAIL TO AIG DD 22.4.19	 Load PDF	
2	22/04/19 19:57	EMAIL FROM AIG DD 22.4.19	 Load PDF	
3	22/04/19 19:57	NOTIFICATION FROM WORKSHOP	 Load TIF	
4	25/04/19 14:37	TP GIA REPORT	 Load PDF	
5	02/05/19 11:32	TP ESTIMATE - MARKED	 Load PDF	
6	12/07/19 10:15	WORKSHOP INVOICE	 Load PDF	
7	12/07/19 10:15	AUTHORISATION TO ACT FORM	 Load PDF	
8	12/07/19 10:15	Release Voucher	 Load PDF	
9	12/07/19 10:15	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/04/19 10:46	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMD747D (Insd veh)	Model:	TOYOTA SIENIA 1.5 (A)
	SME928T (TP veh)		
Date of Accident:	21/04/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	6,530.80	
Final Repair Cost	: \$	3,849.03	
Loss of Use	: \$	300.00	5days at \$60.00 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$	0.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	4,149.03	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____100____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Rally Pitstop	: \$	4,149.03
2)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

12 Jul
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19007079/KDA3Q2

Date: 12/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SME928T

Insured Vehicle No : SMD747D

Date of Loss: 21/04/2019

Nature of Claim: TP

Claim No: 6256564912SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME928T**

Make & Model: TOYOTA SIENTA, 1.5 (A)

Engine No: 2NRX360718

Reg. Date: 18/09/2018 (Man. Year: 2018)

Chassis No: MHFZ28H3100056483

Colour: Metallic Silver

Odometer: 4857 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16

Rear Tyre Size: 195/50 R16

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,280.80	2,579.02	1,701.78	39.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,270.00	980.00	43.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,530.80	3,849.02	2,681.78	41.06
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
Nett Liability (S\$)		4,149.02		

INSPECTION

Date of Assignment: 22/04/2019

Date Inspected: 23/04/2019 Inspected At:

Rally Pitstop (HQ)
176 SIN MING DRIVE #04-17 SINMING
AUTO CARE
Singapore 787525

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	953.20 FL	*495.90 FL
2	1		*REAR BUMPER RETAINER	N/S Distorted	196.40 FL	*98.20 FL
3	1		*REAR BUMPER TOP GARNISH	Dented	425.80 FL	*425.80 FL
4	1		*REAR BUMPER SIDE GARNISH LH	Cracked	389.10 FL	*269.00 FL
5	5		*REAR BUMPER CLIPS	Necessary	15.00 FL	*15.00 FL
6	1		*BOOT LID	Bent	1,358.50 FL	*1,180.00 FL
7	1		*BOOT LID UPPER LOCK	Repair	121.30 FL	*- FL
8	1		*BOOT LID TOYOTA LOGO	Necessary	38.30 FL	*38.30 FL
9	2		*REAR WINDSCREEN MOULDING	Necessary	190.60 FL	*190.60 FL
10	1		*REAR END PANEL	Repair	658.30 FL	*- FL
11	1		*REAR END PANEL INNER GARNISH	Serviceable	225.80 FL	*- FL
12	1		*WEATHER STRIPE	Dented	221.30 FL	*221.30 FL
13	1		*REVERSE SENSOR LH	Dented	234.80 FL	*234.80 FL
14	1		*SIENTA EMBLEM	Necessary	89.80 FL	*89.80 FL
15	1		*REAR END PANEL KEY SENSOR	Dented	232.80 FL	*180.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,351.00	3,438.70
- List Item Discount on L Items 20.00/25.00% (\$\$)	1,070.20	859.68
Total Parts (\$\$)	4,280.80	2,579.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO DISMANTLE ,PANEL BEAT ,REPAIR & REPLACE REAR BUMPER ,BOOT LID ,REAR END PANEL & ALL THE NECESSARY PARTS	New	1,200.00	500.00
2	TO REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
3	TO PUTTY AND SPRAY PAINT	New	800.00	600.00
4	TO CHECK WIRING	New	50.00	20.00
5	TO PROVIDE UNDERCOATING	New	50.00	30.00
Gross Labour Cost (S\$)			2,250.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >