

F/Sian Tony



WEARNES

SERVICE ESTIMATE

Q - A00005
AXA INSURANCE PTE LTD
8 SHENTON WAY,
#27-01 AXA TOWER,
SINGAPORE 068811

SL: AXA INSURANCE PTE LTD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
Inv.date : 17/05/2019
WIP No. : 14445
Veh.In/Out: 12/05/2019 15/05/2019
*Tel.No. : 6338 7288
Reg.No. : SLB1173A
Reg.date : 29/03/2016
Mileage : 44,525
Chassis No: YV1AS40CDG1198988

Closed by : Richmond Ho
Svc Consultant : ACC
Remarks : Mr Chan Wai Kuan Lio

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPAIR FRONT BUMPER,ETC	0	1200.00	0		1,200.00	S ✓
800	TO PUTTY SPRAY PAINT ON FRT	0	700.00	0		700.00	S ✓
BUMPER,ETC							
280	TO CHECK WIRING INCLUDE	0	450.00	0		450.00	S ✓
RESETTING OF ALL ELECTRICAL							
MODULES							

Gross Total. 2,350.00 ✓

Labour Total 2,350.00
Parts Total 0.00
Package Total 0.00

Net..... 2,350.00
GST @ 7.0% 164.50
Total..... 2,514.50
Paid..... 0.00
Please Pay.. 2,514.50

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

Steve Wt- 23/4/19 10.30am
3 days
By AL Shy

SERVICE ESTIMATE

75275 - C00001 SL: SERVICE SALES - PC
Mr Chan Wai Kuan Lionel Eric
Blk 316A Ang Mo Kio Street 31
#02-311

Singapore 562316

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Chan Wai Kuan Lio

GST Reg.No: M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 20/04/2017
WIP No. . : 49408
Veh.In/Out: 18/04/2017
*Tel.No. . : Mobile: 97767904
Reg.No. . : SLB1173A
Reg.date . : 29/03/2016
Mileage .. : 0
Chassis No: 124 198988 16

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount G
-------	-------------	----------	-------	-------	-----	----------

802	TO REPLACE FRONT BUMPER, FRT BRACKET, ETC	0	1600.00	0	1,600.00	S 1200
800	TO PUTTY SPRAY PAINT ON FRT BUMPER, ETC	0	1000.00	0	1,000.00	S 700
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0	450.00	S ✓
	BUMPER COVER FRT D2	1.0 EA	1698.00		1,698.00	S X
	BUMPER GRILLE CHROME	1.0 EA	283.30		283.30	S X
	WASHER COVER FRT LH	1.0 EA	60.50		60.50	S X
	WASHER COVER FRT RH	1.0 EA	60.50		60.50	S X
	EXTERIOR ADHESIVE GL	1.0 EA	142.20		142.20	S X
	STYLING PLASTIC PRIM	1.0 EA	123.00		123.00	S X
	BUMPER BRACKET FRT L	1.0 EA	37.00		37.00	S X
	BUMPER BRACKET FRT R	1.0 EA	37.00		37.00	S X
	BUMPER BRACKET FRT L	1.0 EA	49.00		49.00	S X
	BUMPER BRACKET FRT R	1.0 EA	49.00		49.00	S X

} NMI

SERVICE ESTIMATE

75275 - C00001 SL: SERVICE SALES - PC

Mr Chan Wai Kuan Lionel Eric
Blk 316A Ang Mo Kio Street 31
#02-311

Singapore 562316

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Chan Wai Kuan Lio

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 20/04/2017
WIP No. . : 49408
Veh.In/Out: 18/04/2017
*Tel.No. . : Mobile: 97767904
Reg.No. . : SLB1173A
Reg.date. : 29/03/2016
Mileage . : 0
Chassis No: 124 198988 16

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER CLIP S80 07-	10.0 EA	4.80			48.00 S	X
	BLIND RIVET 4.0*21MM	10.0 EA	3.00			30.00 S	X
	BUMPER EXPANSION PLU	10.0 EA	3.30			33.00 S	X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Total 3,050.00
Parts Total 2,650.50
Package Total 0.00

Gross Total. 5,700.50

Net..... 5,700.50
GST @ 7.0% 399.04
Total..... 6,099.55
Paid..... 0.00
Please Pay.. 6,099.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated