

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 07 May 2019

## **Preliminary Advice**

|                    |                                                                                             |                         |              |
|--------------------|---------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLP7972Y                                                                                  |                         |              |
| TP Vehicle No      | : SLX3953L                                                                                  | Accident Date           | : 20/04/2019 |
| Make               | : BMW 520I                                                                                  | Assignment Date         | : 07/05/2019 |
| Date of Inspection | : 22/04/2019                                                                                | Est. Duration of Repair | : 2 days     |
| Inspection At      | : Fastech Auto Pte Ltd (HQ)<br>1 Kaki Bukit Ave 6, #01-46/48/50 Autobay<br>Singapore 417883 |                         |              |

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 6,322.40 |
| Revised Amount              | :S\$ | 3,199.54 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 3,199.54 |
| Lump Sum Repair             | :S\$ | 2,500.00 |

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.