# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd

To: Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

51 Ubi Ave 1 #01-25 #05-01/06, Singapore Land Tower Paya Ubi Industrial Park Singapore 048623 Singapore 408933

Attn: Ruth Chua Gek Tiang Date: 16 Jul 2019

## **Preliminary Advice**

Vehicle No : SLD855L **Accident Date** : 18/04/2019

Make : TOYOTA COROLLA ALTIS Policy No. : D18MTPV01008413

**Assignment Date** : 24/04/2019 **Excess** : S\$0.00 Date of Inspection : 24/04/2019 Est. Duration of Repair : 9 days

Inspection At : Ah Lim Motor Company (AMK)

10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint

Singapore 568047

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,106.90 (Inclusive Supp)
Revised Amount	:S\$	5,343.10 (Inclusive Supp)
Check Items (Estimated)	:S\$	3.846.80

Total :S\$ 9,189.90

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 73,000.00 COE / PARF Rebate :S\$ 46,930.00

Salvage Value :S\$

:S\$ 26,070.00 Margin for Repair

### Remarks

( X )	The vehicle is repairable at our adjusted amount.	We have also confirmed	l excess and policy coverage.
	Kindly let us have your authorisation.		

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments: Supplementary amount is \$ 524.00. ( X )