

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 25 Apr 2019

Preliminary Advice

Insured Vehicle No	: GY4721L	Accident Date	: 09/04/2019
TP Vehicle No	: FBH6234L	Assignment Date	: 24/04/2019
Make	: YAMAHA FZ16	Est. Duration of Repair	: 4
Date of Inspection	: 24/4/2019		
Inspection At	: BAN HOCK HIN CO PTE LTD		

The vehicle sustained impact / damages rear portion and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,681.00
Revised Amount	:S\$	1,301.00
Check Items (Estimated)	:S\$	152.00
Total	:S\$	1,453.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.