

FASTEC AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
LKK
2/5 = 3000 / 4dy.
24/4/19

VEHICLE NO: SJB 3654P

QTY	PARTICULAR			
1 PCS	FRONT DOOR LH	788.50	11	\$985.20 X
1 PCS	REAR DOOR LH		body 20	\$966.50 X
2 PCS	REAR DOOR HINGES @\$115.00		11	\$230.00 X
1 PCS	REAR DOOR GLASS OUTER MOULDING		body	\$129.30 X
1 PCS	REAR DOOR GLASS REGULATOR		body/shell	\$184.60 X
1 PCS	REAR DOOR GLASS MOTOR	414.20		\$450.00 X
1 PCS	REAR DOOR INNER TRIM BOARD	366.50	re/trim	\$766.50 X
1 SET	REAR DOOR INNER TRIM BOARD CLIPS		re	\$50.00 X
1 PCS	REAR DOOR INNER RUBBER		re	\$166.30 X
1 PCS	REAR DOOR INNER LOCK		11	\$345.50 X
1 SET	REAR DOOR FRAME BLACK STICKER		re	\$120.00 X
1 PCS	ROCKER PANEL GARNISH N/S	745.20	re/trim	\$820.00 X
1 SET	ROCKER PANEL GARNISH CLIPS N/S		re	\$50.00 X
1 PCS	REAR FENDER		11	\$911.30 X
1 PCS	REAR SPORT RIM O/S		cut	\$480.00 X 3505.2
1 PCS	REAR SHOCK ABSORBER O/S		11	\$215.00 X
1 PCS	REAR WHEEL BEARING O/S		11	\$266.00 X
1 PCS	REAR AXLE		11	\$799.00 X
1 PCS	REAR DOOR OUTER HANDLE		11	\$125.30 X
				\$8,060.50
	LABOUR CHARGES:			
	TO CHECK WIRING			\$80.00 -20
	TO CONDUCT WHEEL ALIGNMENT			\$120.00 -80
	TO DISMANTLE & REFIX REAR UNDERCARRIAGE		11	\$350.00 X
	TO SPRAY RUST PROOFING			\$100.00 40
	TO TRANSFER REAR DOOR MECHANISM			\$100.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$800.00 1400
	TO PUTTY & SPRAY PAINTING			\$1,080.00 600
			TOTAL	\$10,690.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9-2830
2170
226420
3754