

Steve - LKIC

Poh Kin

AUTOLUTION INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0060/19
DATE : 22-JAN-2019

AUTOLUTION INDUSTRIAL PTE. LTD.
100 ROBINSON ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6346 7483

ERGO INSURANCE PTE. LTD.
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9246
ATTN : CLAIM MANAGER

OWNER'S NAME : LOH YEEN YING
ADDRESS : BLK 3 MARINE TERRACE
#06-284
S(440003)
TELEPHONE NO : 97342763

4 days.

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SBH2810A
MODEL CODE : B0RUREWJ32EYAD---A
MODEL/YEAR : NISSAN TEANA 200XL
ENGINE NO : MR20333941A
CHASSIS NO : JN1BXXJ32Z0001252
MILEAGE : 103319 KM
DATE IN : 22/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HANZAH — 96450079
ACCIDENT DATE : 22/01/2019

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SBH2810A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION	
1	ZZ/001	LABOUR CHARGES TO RENEW FRONT BUMPER AND LH FRONT FENDER.	700.00	585.00	✓
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	650.00	500.00	✓
3	ZZ/003	RENEW DAMAGED HEADLAMP AND FOCUS.	48.00	48.00	✓
TOTAL LABOUR CHARGES			1398.00	1133.00	✓

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SBH2810A

DAMAGED PARTS & PRICES						
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN			20.00	OK ✓
2	HEADLAMP LH	26060-JN25A	595.20	✓		OK
3	L/F FENDER STAY	63181-JN20A	42.00			X
4	L/F FENDER PROTECTOR COVER	63841-JN20A	99.40			X
5	FENDER-FRONT LH	F3101-JN2MA	706.60	✓		OK
6	FRT BUMPER SIDE MLDG LH	62075-JN00B	121.20	✓		OK
7	FRT BUMPER STD RETAINER LH	62241-JN00A	25.20			X
8	FRT BUMPER SIDE BRACKET LH	62221-JN20A	55.50	✓		OK
9	CLIP FRT BUMPER # 1.30 EACH	01553-09321	7.80	✓		OK
10	FRONT BUMPER FACIA	62022-JN20H	720.00	✓		OK
SUB TOTAL			2206.30	✓	0.00	20.00 ✓
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			441.26		0.00	
GRAND TOTAL			1765.04	✓	0.00	20.00 ✓
OVERALL TOTAL			1785.04	✓		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO 5842810A

NETT ITEM	2206.30
LESS 20.00%	-441.26
NETT AMOUNT	1765.04

LIST ITEM	0.00
LESS 20.00%	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	20.00
LESS 20.00%	0.00
SPECIAL NETT AMOUNT	20.00

TOTAL LABOUR CHARGES	1133.00
TOTAL SPARE PARTS CHARGES	1765.04

TOTAL CHARGES	2918.04
ADD 7% GST	204.26

GRAND TOTAL	3122.30
-------------	---------

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE. LTD.
12 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6546 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0060/19
DATE : 22-JAN-2019

ERGO INSURANCE PTE. LTD.
5 TOMASEK BOULEVARD
#04-03 SUNEED TOWER/PIRE
S(039985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : LEE YEEN YING
ADDRESS : BLK 13 MARINE TERRACE
#06-284
S(440003)
TELEPHONE NO : 97542763

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY / ATN
POLICY NO :
VEHICLE NO : JB 97810A
MODEL CODE : B0F0REWJ32EYAD---A
MODEL/YEAR : NISSAN TEANA 200XL
ENGINE NO : MR20833941A
CHASSIS NO : JNTH0UJ32Z0001252
MILEAGE : 100546 KM
DATE IN : 22/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HANZAH - 96450079
ACCIDENT DATE : 22/01/2019

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SBH2810A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO RENEW FRONT BUMPER AND LH FRONT FENDER. 890	700.00	585
2	ZZ/002	CHARGE TO SPRAY PAINTING SAME. 350	650.00	500
3	ZZ/003	REPAIR DAMAGED HEADLAMP AND FOCUS.	48.00	✓
TOTAL LABOUR CHARGES			1398.00	

MATERIAL LIST FOR A-10000 VEHICLE (REQ. NO. 5042)

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN			60.00	20
2	HEADLAMP LH / CUT	26060-JN25A	595.20			
3	L/F FENDER STAY ?	63181-JN20A	42.00			
4	L/F FENDER PROTECTOR COVER ?	63841-JN20A	99.40			
5	FENDER FRONT LH / DO	F3101-JN2MA	706.00			
6	FRT BUMPER SIDE MOLD LH / CUT	62075-JN00B	121.20			
7	FRT BUMPER SIDE RETAINER LH in the ?	62241-JN00A	25.20			
8	FRT BUMPER SIDE BRACKET LH / OR	62271-JN20A	55.50			
9	L/R FR BUMPER W/100 EACH / 14C	01553-09321	7.00			
10	FRONT BUMPER FASCIA / TN	E2022-JN20H	720.00			
SUB TOTAL			2372.90	0.00	60.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-100%)			474.58	0.00	0.00	
GRAND TOTAL			1898.32	0.00	60.00	
OVERALL TOTAL			1958.32			

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

Steve (LKK) wil Per/4 die
 83228813 26/4/19, 10.15 am
 P/P
 R-y bef spy
 4 Days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

