



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBF9753X YAMAHA YBR125 (51P3) REPAIR ESTIMATE

ITEM	DESCRIPTION
1	FRONT MUDGUARD <i>scr</i>
2	FRONT FORK ASSY RH & LH @ \$185 <i>repair</i>
3	STEM STEERING <i>X</i> NN
4	CONE BEARING SET <i>X</i> NN
5	WINDSHIELD <i>CRA</i>
6	FRONT COWLING <i>? X NN</i>
7	STAY, FRONT COWLING <i>? X NN</i>
8	HEADLAMP COMP <i>scr</i>
9	METER ASSY <i>scr</i>
10	FRONT SIGNAL RH & LH @ \$58 <i>RH-scr (ipc)</i>
11	FRONT LICENCE PLATE <i>na</i>
12	BRAKE LEVER <i>scr</i>
13	HANDLEBAR <i>? X NN</i>
14	BALANCER <i>mis</i>
15	HANDLE GRIP <i>X NN</i>
16	SIDE MIRROR <i>scr</i>
17	IU UNIT <i>scr</i>
18	FUEL TANK COMP <i>X NN</i>
19	FUEL TANK COVER <i>X NN</i>
20	STAY, FRONT MUDGUARD <i>X NN</i>
21	FRONT FOOTRESTBAR <i>bt</i>
22	FOOTREST RUBBER X2 @ \$8 <i>scr cut (ipc)</i>
23	BRAKE PEDAL <i>X NN</i>
24	MUFFLER <i>repair scr</i>
25	HEAT PROTECTION, CHROME <i>scr</i>
26	HEAT PROTECTION, RUBBER <i>scr</i>
27	REAR SIGNAL <i>scr</i>
28	TOP BOX BRACKET <i>X NN</i>
29	REAR FOOTREST RH <i>scr</i>
30	REAR FOOTREST BRACKET RH <i>X NN</i>
31	REAR TOP BOX <i>scr</i>
32	WORKMANSHIP
33	TRANSPORTATION TP-IDAC- SHOP @ \$50
34	BODY CHASSIS REPAIR <i>X NN</i>
35	TRANSPORTATION 2 WAY TO REPAIR CHASSIS @ \$50 <i>X NN</i>

AMOUNT SGD

3042
10%
2737.80

150 s/n
250
40
440

2737.80
440.00
3177.80
20%
2542.24
45-2550

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul

Hp 90010068

4 days

4/5

16/05/19 @ 1720

Reay after repair

TOTAL

\$5,946.00

2737.80

440.00

3177.80

20%

2542.24

45-2550