

Qty

LKK Auto Consultants Pte Ltd

Condition

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

Our Adjusted

4,184.78

Estimate By

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 2508Z

Description of Parts

Qty	Description of Parts	Condition	Workshop (\$))	(\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR (RH) (CONSISTENT)	DENTED	1,168.30	1,168.30
1	FRONT DOOR TAPE (RH) (CONSISTENT)	NECESSARY	172.40	172.40
1	FRONT DOOR GARNISH (RH) (CONSISTENT)	CUT	380.00	380.00
1	FRONT DOOR WEATHERSTRIP (RH) (CONSISTENT)	NOT NECESSARY	158.95	-
1	REAR DOOR (RH) (CONSISTENT)	DENTED	1,084.90	1,084.90
1	REAR DOOR GARNISH (RH) (CONSISTENT)	сит	331.50	331.50
1	REAR DOOR TAPE (RH) (CONSISTENT)	NECESSARY	159.40	159.40
1	REAR DOOR WEATHERSTRIP (RH) (CONSISTENT)	NOT NECESSARY	166.50	-
1	REAR FENDER ARCH GARNISH (RH) (CONSISTENT)	сит	142.00	142.00
1	SIDE SKIRT (RH) (CONSISTENT)	CUT	541.20	541.20
	LESS 20% DISCOUNT		-861.03	-
	LESS 25% DISCOUNT		-	-994.92
			3,444.12	2,984.78
	LABOUR			
	TO DISMANTLE & CHARGE FRONT RH DOOR ,REAR RH DOOR ,REAR RH DOOR GARNISH ,RH SIDE SKIRT ,DISMANTLE & REFIT REAR BUMPER TO KNOCK & PULL STRAIGHT REAR RH FENDER .		800.00	500.00
	TO PERFORM WIRE CHECKING .		20.00	20.00
	TO DISMANTLE & TRANSFER FRONT RH DOOR ,REAR RH DOOR FITTING AND MECHANISM TO NEW DOOR .		120.00	80.00
	TO SPRAY FRONT RH DOOR ,REAR RH DOOR ,REAR RH FENDER AND TOUCH UP REAR BUMPER .		800.00	600.00
			1,740.00	1,200.00
	GRAND TOTAL		5,184.12	4,184.78

Report Ref No. CC4/ASM19007271/Epa3q2

OUEN TOUE VE

CHEN TSUE YEE
Automotive Assessor

RECOMMENDED COST OF REPAIRS

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.