

11/13/2019

ASS. REC. BY:

REF:

03/CTI19007279/ETd3e2

Special Instruction:

Surveyor

Shave

ASSIGNMENT (Office)

From (Person): Chang Boon Sen

of

CTI

Date/Time: 24/4/2019

Estimated Cost:

Bill to:

OD/TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDK 861 B

Insured: SLG 6606X

at Workshop in/s Premium Automobiles

Tel: 6762 9828 Sheila

of 55 Ubi Rd 1

Policy No:

Claim No: SNM1900201779

Sum Insured:

Excess:

D.O.A.

19/4/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

24/4

Person Contacted:

Sheila

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SDK 861 B - X
	SLG 6606X - X
	Part by part \$19,046.20 Cred: 8903; 31%

ASSIGNMENT

From: 29/4/19 Date: 29/4/19 Veh No: SOK 861 B Yr Regn: 30/6/15

Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

To Inspect Vehicle No: Truck / Trailer or Make: Audi A7 C.C: 2773

at Workshop m/s: Premium Colour: White A/C: Insured / Std / NI / NA

of: 55 ubi Road 1 Sp. Reading: 53388 T/Radio: Insured / Std / NI / NA

Insured: Eng/No: WAV 222 46 7 EN 080459

Policy No: C/No: WAV 222 46 7 EN 080459

Claims No: Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess: Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record) Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: Look for George Modi: Nil / 5/Rim / STD A/Rim or

(Policy Condition) Tyre Size: F: 265/35 ZR20

Remark: The veh had commenced its repair at the time of inspection. R: "

Bal. or Market Value: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

IDAC Accident Rpt: Consistent? : Yes or No TOYO / YOKO or Pirelli

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.



RECEIVED 22 AUG 2019

Date / Time	Action / Instruction
	MV - 150,980
	PV - 98,546
	AV - 5,454

Date/Time, File Pass to? ☐ : Prel. Report Days Of Repair: 12

1) ☐ : Final Report Resurvey No. of Trip: 1

Date/Time, File Return to? Add Fee: ☐ Site Inap (\$)

2) ☐ Interview (\$)

Report Format: ☐ Tech. Invs (\$)

Lump Sum / L.S. (\$ 19,096.20) ☐ Weekend (\$)

Survey Fee: 220

Transportation: \$ + R.S. \$

Photos: 0

Others: 0

TOTAL: 220

Nivitha (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Wednesday, 24 April 2019 1:13 PM
To: 'Chong Boon Sen'
Cc: 'assignments'
Subject: RE: ACCIDENT INVOLVING SDK 0861 B AND YOUR INSURED SLS6606X DATED ON 19/04/2019 / OUR REF: SNM19D201779

Dear Sir,

Thank you will make arrangements with the appointed consultant.

Best Regards,
Sheila M Ismail
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902211W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]
Sent: Wednesday, 24 April 2019 9:54 AM
To: Claims Dept
Cc: assignments
Subject: RE: ACCIDENT INVOLVING SDK 0861 B AND YOUR INSURED SLS6606X DATED ON 19/04/2019 / OUR REF: SNM19D201779

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3
Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Tuesday, 23 April, 2019 4:30 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: ACCIDENT INVOLVING SDK 0861 B AND YOUR INSURED SLS6606X DATED ON 19/04/2019 / OUR REF: SNM19D201779

Dear Sir,

We will choose Adrian Ling for this case.

Thank You.

Best Regards,
Sheila M Ismail
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/04/2019 13:10
Date Of Accident	19/04/2019 21:20
Exact Location Of Accident	ENTRANCE OF MEYER RISE 97 MEYER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDK861B
Insured/Policyholder	
Name Of Registered Owner	MUKUND S/O HARKISHANDAS R DOSHI
NRIC No	S0143166H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96555052
Alternative Phone No	OFFICE-63444245

Vehicle Particulars

Manufacturer	AUDI
Model	A7 SB 2.8 FSI QU 4GA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA048772/1
Cover Note Number	

Driver

Name of Driver	MUKUND S/O HARKISHANDAS R DOSHI
NRIC No	S0143166H
Date Of Birth	28/10/1948
Occupation	INDOOR
Date Of Driving Pass	07/10/1966
Driving Experience	52 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96555052
Fax Number	
Contact Number	OFFICE-63444245
Email Address	NOEMAIL

Address	93 MEYER ROAD #15-02
Postcode	437986
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING DOWN MEYER ROAD TOWARDS TANJONG KATONG, I STOPPED AND MADE A RIGHT TURN INTO MY CONDOMINIUM, THE MEYERISE. I HAD MADE 3 POINT TURN INTO THE ENTRANCE OF THE CONDOMINIUM WHEN THE OTHER VEHICLE SLS6606X WAS REVERSING STRAIGHT INTO THE RIGHT SIDE OF MY CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS6606X
Vehicle Make/Model/Colour	BMW 523.I/METALIC BEIGE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ZHENG YAN CHAO
NRIC/Passport Number	S8777688C
Contact Number	97761876
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Person's Signature
Name: 
NRIC/IN No: 

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling down Meyer Road towards Tanjong Katong Road. I stopped and made a Right Turn to my Condo in the Meyer Rd. I had made 3/4 turn into the entrance of the Condo when the other vehicle SLS 6606X was reversing a straight in to the right side of my car.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

[Signature]

Police Officer's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the partyholder)
Date & Time:

[Signature]



Reporting Centre Personnel's Signature
Name: *Sgt Mesallie*
NRIC/IDN No: *S8412102*

Accident Photo





redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

account number
 03926

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	MUKUND S/O HARKISHANDAS R DOSHI	Certificate number	GA048772 / 1
Cover	Comprehensive	Chassis number	WAUZZZ4G7EN080459
Plan name	Flexi*	Engine number	CHV022898
NCD applicable	40%		
Vehicle registration number	SDK861B		
Period of Insurance	from 30/06/2018 to 29/06/2019 (both dates inclusive)		
Finance loan company	DBS BANK LTD		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any Named Driver as stated in the Policy:
 1. BHANUMATI MUKUND DOSHI 2. DOSHI DHRIJ MUKUND
 (c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 900.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

- \$5500 for unnamed Authorised Driver
- \$5500 for declared Young and Inexperienced Driver
- \$15,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to \$52,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.


 License Number: **S0143166H**
 Name: **MUKUND S/O HARKISHANDAS R DOSHI**
 Birth Date: **28 Oct 1948**
 Issue Date: **14 Aug 2003**


REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. **S0143166H**



Name:

MUKUND S/O HARKISHANDAS R DOSHI

Race:

INDIAN

Date of birth:

28-10-1948

Country/Place of birth:

INDIA

Sex:

M

S0143166H

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

PASS DATE

Class 2 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

07 Oct 1968

NP 438A



Licence No: **S0143166H**



NRIC No: **S0143166H**



Date of issue:

02-05-2018

Address:

93 MEYER ROAD
#15-02
SINGAPORE 437986

5927597



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Promo! Brand New Borneo Toyota Dyna 150 @ \$72,600!



GST Inclusive! No Hidden Cost!
No Goods! Immediate Stock!
See To Believe!
Net Link Partners StarHub

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category ▾

Sort by Date Posted ▾ 20 results/page ▾

2 vehicles

Audi A7 sportback

Advanced Search 🔍

Model	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Audi A7 sportback	Any	Any	2016	Any	Any	Any	Available
	Audi A7 Sportback 2.0A TFSI S-tronic	\$175,800	\$20,880 /yr	27-Jan-2016	1,984 cc	45,000 km	Luxury	Available
5 Years Extended Warranty From 1st Date Of Registration For Selected Unit, White On Black! 20" BBS Rims! Fully Serviced And Maintained By Premium Automobiles. Flexible Financing/Trade In Can Be Arrang...								
Posted: 26-Mar-2019 Tags: 2016 Audi A7, 2016 audi a7, Audi A7, audi a7, Audi, A7, a7, Used Audi								
	Audi A7 Sportback 2.0A TFSI S-tronic	\$167,000	\$19,350 /yr	25-Feb-2016	1,984 cc	40,500 km	Luxury	Available
Handsome Car With Huge Boot Space With Rear Knock Down Seats, Fully Maintained By Premium Automotive With Genuine Mileage, Driven By Careful Driver With No Accident Record, Guarantee No Chassis Or Str...								
Posted: 19-Mar-2019 Tags: 2016 Audi A7, 2016 audi a7, Audi A7, audi a7, Audi, A7, a7, Used Audi								

Save this search criteria, to get email alerts whenever a match is found.

Model Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

20 ▾ results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Audi A7 sportback, Audi A7 sportback Singapore, used Audi A7 sportback Singapore, used Audi A7 sportback, used vehicles Singapore or even buy used Audi A7 sportback Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)
©2004-2019 sgCarMart. All rights reserved.

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3166H
Vehicle Details	
Vehicle No.:	SDK861B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 May 2019
Vehicle Make:	AUDI
Vehicle Model:	A7 SB 2.8 FSI QU (MY'14)
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	CHV022898
Chassis No.:	WAUZZZ4G7EN080459
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$54,772.00
Original Registration Date:	30 Jun 2015
First Registration Date:	30 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$70,590.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2025
PARF Rebate Amount:	\$52,942.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$75,801.00
COE Rebate Amount:	\$45,604.00
Total Rebate Amount:	\$98,546.00

The information contained herein is correct as at 26 Apr 2019

OK

[➤ Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details	
Vehicle No.:	SDK861B
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	AUDI
Vehicle Model:	A7 SB 2.8 FSI QU (MY'14)
Chassis No.:	WAUZZZ4G7EN080459
Propellant:	Petrol
Engine No.:	CHV022B9B
Engine Capacity:	2773 cc
Maximum Power Output:	150.0 kW (201 bhp)
Maximum Laden Weight:	2280 kg
Unladen Weight:	1730 kg
Year Of Manufacture:	2013
Original Registration Date:	30 Jun 2015
Lifespan Expiry Date:	-
COE Category:	E - Open Category
Quota Premium:	\$75,801.00
COE Expiry Date:	29 Jun 2025
Road Tax Expiry Date:	29 Jun 2019
PARF Eligibility Expiry Date:	29 Jun 2025
Inspection Due Date:	29 Jun 2020
Intended Transfer Date:	29 Apr 2019
CO2 Emission:	187.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 29 Jun 2019. You may renew the road tax from 30 Mar 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 29 Jun 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 30 Jun 2019 to 29 Dec 2019)

	Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	1,060.00	-	1,060.00
Total Amount Payable:			1,085.00

Total Amount Payable:

Amount Payable (From 30 Jun 2019 to 29 Jun 2020)

	Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	2,120.00	-	2,120.00
Total Amount Payable :			2,145.00

You may print this page for reference.

OK

Print

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0526/2019/DY
Date	:	23-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : **SLS 6606 X**

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Motor Claims Dept

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name	:	Dr. Mukund S/o Harkishandas R Doshi
Address	:	93 Meyer Road #15-02 Singapore 437986
Telephone	:	96555052
Type of Claim	:	Third Party Claims
Policy No.	:	GA048772/1
Vehicle No	:	SDK 0861 B
Model Code	:	Audi A7 SB 2.8 FSI QU
Model / Year	:	Jun-15
Engine No	:	CHV 022898
Chassis No	:	WAUZZZ4G7EN080459
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Apr-19
Place of Accident	:	Entrance of Meyer Rise 97-

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDK 0861 B

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	s/n	\$ 360.00 ✓	✓
2	To renew rhs 1/4 glass to facilitate fender renewal.	s/n	\$ 300.00 ✓	✓
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.		\$ 1,400.00 ✓	✓
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	s/n	\$ 1,400.00 ✓	✓
5	To remove and transfer rhs rear door's multi-lock systems and power window devices. Inspect for damages and renew if necessary.	s/n	\$ 280.00	no photo ? +
SUB-TOTAL LABOUR CHARGES			: \$ 3,460.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDK 0861 B

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To dismantle rear bumper, rear lid, rhs rear door and rhs sill panel trim. Cut out and weld rhs rear fender. To renew rhs rear door. Re-organise crash management components. Reinstall all parts removed. <i>7000</i>	s/n \$ 7000.00 <i>7000</i>	<i>4900</i> ✓
7	To respray rear bumper, rhs rear fender, rhs sill panel trim, rhs sill panel, rhs rear door, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works. <i>800</i>	\$ 6,000.00	<i>4300</i> ✓
8	To renew rhs rear rim. To carry out wheel alignment.	s/n \$ 280.00	✓
9	To carry out diagnostic check.	s/n \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>10,632.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDK 0861 B

		<u>Damage Parts & Prices</u>	
S/N	Parts Description	S/NETT	REMARKS
1	REAR FENDER - RH / DO	\$ 2,891.00	✓
2	REAR 1/4 GLASS - RH / N/A	\$ 622.00	621.50
3	REAR FENDER CLIP SET / N/A	\$ 118.00	117.50
4	REAR FENDER ADHESIVE TAPE / N/A	\$ 15.00	X N/A
5	REAR DOOR - RH x R	\$ 3,855.00	
6	REAR DOOR OUTER SEAL - RH / N/A	\$ 157.00	✓
7	BONDING AGENT x N/A	\$ 45.00	
8	CLEANING SOLUTION x N/A	\$ 65.00	
9	APPLICATOR x N/A	\$ 7.00	
10	REAR DOOR ATTACHMENT PARTS ? x N/A	\$ 119.00	X
11	REAR DOOR CATCH - RH x R	\$ 117.00	
12	REAR TYRE RIM - RH ? / CAT	TBC	1223 ✓
13	RUBBER VALVE x N/A	\$ 13.00	X N/A
14	ACRYLIC SEALANT / N/A	S/N \$ 180.00	✓
15	CAVITY WAX / N/A	S/N \$ 140.00	✓
16	STONE CHIP TREATMENT ? / N/A	S/N \$ 180.00	✓
17	METAL FILLER POWDER / N/A	S/N \$ 280.00	✓
18	1/4 GLASS SEALANT / N/A	S/N \$ 100.00	✓
19	SUNDRIES ? / N/A	\$ 600.00	1420
TOTAL SPARE PARTS		\$ 9,504.00	
TOTAL LABOUR CHARGES		\$ 10,632.00	
GRAND TOTAL		\$ 20,136.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

27699

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

[Signature]
2/5/19

Telefax

Name

: Steve (LKK) 83228813

Surveyed Date

: 29/4/19 2.30 pm

Authorised Date

: LHL Moped

Excess Cost

: P/P

Liability

: Rj bel spg

Remarks

: 12 - 13 Days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0526/2019/DY
Date	:	23-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : **SLS 6606 X**

China Taiping Insurance (SG) Pte Ltd
105 Cecil Street
#19-00 The Octagon
Singapore 069534

Hi Steve
12 days exclude 1 Sunday -
Johnny Boo 15 Aug 19

Motor Claims Dept
Tel: 6389 6541 - Fax: 6224 7175

Owner's Name	:	Dr. Mukund S/o Harkishandas R Doshi
Address	:	93 Meyer Road #15-02 Singapore 437986
Telephone	:	96555052
Type of Claim	:	Third Party Claims
Policy No.	:	GA048772/1
Vehicle No	:	SDK 0861 B
Model Code	:	Audi A7 SB 2.8 FSI QU
Model / Year	:	Jun-15
Engine No	:	CHV 022898
Chassis No	:	WAUZZZ4G7EN080459
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Apr-19
Place of Accident	:	Entrance of Meyer Rise 97-

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDK 0861 B

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	s/n	\$ 360.00	\$ 360.00
2	To renew rhs 1/4 glass to facilitate fender renewal.	s/n	\$ 300.00	\$ 300.00
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.		\$ 1,400.00	\$ 1,400.00
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	s/n	\$ 1,400.00	\$ 1,400.00
5	To remove and transfer rhs rear door's multi-lock systems and power window devices. Inspect for damages and renew if necessary.	s/n	\$ 280.00	na
SUB-TOTAL LABOUR CHARGES		:	<u>\$ 3,740.00</u>	\$ 3,460.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDK 0861 B

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
			\$ 3,460.00
6	To dismantle rear bumper, rear lid, rhs rear door and rhs sill panel trim. Cut out and weld rhs rear fender. To renew rhs rear door. Re-organise crash management components. Reinstall all parts removed.	s/n \$ 7,000.00	\$ 4,900.00
7	To respray rear bumper, rhs rear fender, rhs sill panel trim, rhs sill panel, rhs rear door, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 6,000.00	\$ 4,300.00
8	To renew rhs rear rim. To carry out wheel alignment.	s/n \$ 280.00	\$ 280.00
9	To carry out diagnostic check.	s/n \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 17,212.00	\$ 13,132.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDK 0861 B

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR FENDER - RH	\$ 2,891.00	\$ 2,891.00
2	REAR 1/4 GLASS - RH	\$ 622.00	\$ 621.50
3	REAR FENDER CLIP SET	\$ 118.00	\$ 117.50
4	REAR FENDER ADHESIVE TAPE	\$ 15.00	
5	REAR DOOR - RH	\$ 3,855.00	
6	REAR DOOR OUTER SEAL - RH	\$ 157.00	\$ 157.00
7	BONDING AGENT	\$ 45.00	
8	CLEANING SOLUTION	\$ 65.00	
9	APPLICATOR	\$ 7.00	
10	REAR DOOR ATTACHMENT PARTS	\$ 119.00	
11	REAR DOOR CATCH - RH	\$ 117.00	
12	REAR TYRE RIM - RH	\$ 1,283.00	\$ 1,283.00
13	RUBBER VALVE	\$ 13.00	
14	ACRYLIC SEALANT	S/N \$ 180.00	\$ 180.00
15	CAVITY WAX	S/N \$ 140.00	\$ 140.00
16	STONE CHIP TREATMENT	S/N \$ 180.00	\$ 180.00
17	METAL FILLER POWDER	S/N \$ 280.00	\$ 280.00
18	1/4 GLASS SEALANT	S/N \$ 100.00	\$ 100.00
19	SUNDRIES	\$ 600.00	\$ 14.20
TOTAL SPARE PARTS		\$ 10,787.00	\$ 5,964.20
TOTAL LABOUR CHARGES		\$ 17,212.00	\$ 13,132.00
GRAND TOTAL		\$ 27,999.00	\$ 19,096.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Sep 2019		05 Sep 2019 11:32 Edit Adj Rpt	S\$19,096.20 Edit Estimates	S\$19,096.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	MUKUND S/O HARKISHANDAS R DOSHI , ID: S0143166H								
Vehicle Reg. No.:	SDK861B	Date of Loss:	19/04/2019 21:00 - :59 [45 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201779C02	Policy/Cover Note No.:	DMPCSN30542518000						
Vehicle Reg. No. (Insured):	SLS6606X	Policy No. (Claimant):	GA048772/1						
		Excess:	S\$0.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 16/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDK861B (SNM19D201779C02)
[SLS6606X]

TP

MUKUND S/O HARKISHANDAS R DOSHI

Apr 19 2019 9:00PM

[-]

Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Video				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	25/04/19 16:53	Video - Accident [Linked Accident Report Documents]		Load MP4	
Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	25/04/19 16:53	Addendum Sheet		Load JPG	☒
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
11	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
12	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
13	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
14	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
15	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
16	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
17	22/04/19 13:27	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/09/19 09:22	General View		Load JPG	☒
2	06/09/19 09:22	General View		Load JPG	☒
3	06/09/19 09:22	General View		Load JPG	☒
4	06/09/19 09:22	General View		Load JPG	☒
5	06/09/19 09:22	General View		Load JPG	☒
6	06/09/19 09:22	General View		Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
7	06/09/19 09:22	General View	 Load JPG	☒
8	06/09/19 09:22	General View	 Load JPG	☒
9	06/09/19 09:22	General View	 Load JPG	☒
10	06/09/19 09:22	General View	 Load JPG	☒
11	06/09/19 09:22	General View	 Load JPG	☒
12	06/09/19 09:22	General View	 Load JPG	☒
13	06/09/19 09:22	General View	 Load JPG	☒
14	06/09/19 09:22	General View	 Load JPG	☒
15	06/09/19 09:22	General View	 Load JPG	☒
16	06/09/19 09:22	General View	 Load JPG	☒
17	06/09/19 09:22	General View	 Load JPG	☒
18	06/09/19 09:22	General View	 Load JPG	☒
19	06/09/19 09:22	General View	 Load JPG	☒
20	06/09/19 09:22	General View	 Load JPG	☒
21	06/09/19 09:22	General View	 Load JPG	☒
22	06/09/19 09:22	General View	 Load JPG	☒
23	06/09/19 09:22	General View	 Load JPG	☒
24	06/09/19 09:22	General View	 Load JPG	☒
25	06/09/19 09:22	General View	 Load JPG	☒
26	06/09/19 09:22	General View	 Load JPG	☒
27	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
28	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
29	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
30	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
31	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
32	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
33	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
34	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
35	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/04/19 13:21	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	22/04/19 13:21	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	25/04/19 16:53	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	25/04/19 16:53	Addendum Sheet	 Load JPG	☒
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/04/19 13:27	Accident Photo	 Load JPG	☒
2	22/04/19 13:27	Accident Photo	 Load JPG	☒
3	22/04/19 13:27	Accident Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
4	22/04/19 13:27	Accident Photo	 Load JPG	☒
5	22/04/19 13:27	Accident Photo	 Load JPG	☒
6	22/04/19 13:27	Accident Photo	 Load JPG	☒
7	22/04/19 13:27	Accident Photo	 Load JPG	☒
8	22/04/19 13:27	Accident Photo	 Load JPG	☒
9	22/04/19 13:27	Accident Photo	 Load JPG	☒
10	22/04/19 13:27	Accident Photo	 Load JPG	☒
11	22/04/19 13:27	Accident Photo	 Load JPG	☒
12	22/04/19 13:27	Accident Photo	 Load JPG	☒
13	22/04/19 13:27	Accident Photo	 Load JPG	☒
14	22/04/19 13:27	Accident Photo	 Load JPG	☒
15	22/04/19 13:27	Accident Photo	 Load JPG	☒
16	22/04/19 13:27	Accident Photo	 Load JPG	☒
17	22/04/19 13:27	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/04/19 13:21	Sketch Plan	 Load JPG	☒
2	22/04/19 13:21	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119007279/ETD3E2

Date: 06/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30542518000

Claimant Vehicle
No: SDK861BInsured Vehicle
No: SLS6606X

Date of Loss: 19/04/2019

Nature of Claim: TP

Claim
No: SNM19D201779C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDK861B

Make & Model: AUDI A7 SPORTBACK, 2.8 FSI QUATTRO (A)

Engine No: CHV022898

Reg. Date: 30/06/2015 (Man. Year: 2013)

Chassis No: WAUZZZ4G7EN080459

Colour: White

Odometer: 53388 km

Engine Capacity: 2773 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35Z R20

Rear Tyre Size: 265/35Z R20

Front Left Side: Pirelli 7 mm

Rear Left Side: Pirelli 7 mm

Front Right Side: Pirelli 7 mm

Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,787.00	5,964.20	4,822.80	44.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,212.00	13,132.00	4,080.00	23.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,999.00	19,096.20	8,902.80	31.80
+ GST 7.00/7.00% (S\$)	1,959.93	1,336.73	623.20	31.80
Nett Amount (S\$)	29,958.93	20,432.93	9,526.00	31.80

INSPECTION

Date of Assignment: 05/09/2019

Date Inspected: 29/04/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2019)
Parts: 143	AUDI A7 SPORTBACK 2.8 FSI QUATTRO (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDK861B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER - RH	Dented	2,891.00 FS	*2,891.00 FS
2	1		*REAR 1/4 GLASS - RH	Necessary	622.00 FS	*621.50 FS
3	1		*SET REAR FENDER CLIP	Necessary	118.00 FS	*117.50 FS
4	1		*REAR FENDER ADHESIVE TAPE	Not Necessary	15.00 FS	*- FS
5	1		*REAR DOOR - RH	Repair	3,855.00 FS	*- FS
6	1		*REAR DOOR OUTER SEAL - RH	Necessary	157.00 FS	*157.00 FS
7	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
8	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
9	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
10	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	119.00 FS	*- FS
11	1		*REAR DOOR CATCH - RH	Repair	117.00 FS	*- FS
12	1		*REAR TYRE RIM - RH	Cut	1,283.00 FS	*1,283.00 FS
13	1		*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
14	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
15	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
16	1		*STONE CHIP TREATMENT	Necessary	180.00 FS	*180.00 FS
17	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
18	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
19	1		*SUNDRIES	Necessary	600.00 FS	*14.20 FS
Total Parts (S\$)					10,787.00	5,964.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO RENEW RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	300.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
5	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEMS AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	280.00	0.00
6	TO DISMANTLE REAR BUMPER, REAR LID, RHS REAR DOOR AND RHS SILL PANEL TRIM. CUT OUT AND WELD RHS REAR FENDER. TO RENEW RHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,000.00	4,900.00
7	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL TRIM, RHS SILL PANEL, RHS REAR DOOR, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	6,000.00	4,300.00
8	TO RENEW RHS REAR RIM. TO CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			17,212.00	13,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >