



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19007357/Epa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:JAS

Date : 09-10-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 5139R	Veh. Inspected	SLZ 5868B
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01L95	Excess (\$)	0.00
Assign From		Assign Date	25/04/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ GLC250	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDC2533462F379065	Colour	GREY
Odometer	26598	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/50 R19	HANKOOK	7 mm
L/H Front Tyre	255/50 R19	HANKOOK	7 mm
R/H Rear Tyre	255/50 R19	HANKOOK	7 mm
L/H Rear Tyre	255/50 R19	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/04/2019	Inspection Date	28/05/2019
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------