

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SDE8832P
Accident Date : 23-Apr-2019

No. : 05965

Date : 25-Apr-2019

Our Ref : 219064 (AIG) / CHAN

PAGE : 1

TAN ENG CHING
BLK 124 BEDOK NORTH ROAD
#09-129
Singapore 460124

*Not Withain
Resurvey B4 paint*

ESTIMATED COST OF REPAIR FOR NISSAN NOTE 1.2DIG 2WD LED SGY8166M

1 pc	Rear bumper fascia		976.60	n	—
4 pcs	Rear bumper clip	@ S\$ 4.50	18.00	n	—
2 pcs	Rear bumper side retainer	@ S\$ 45.40	90.80	n	4
2 pcs	Rear bumper sponge	@ S\$119.90	239.80	n	?
2 pcs	Rear bumper bracket	@ S\$ 86.60	173.20	n	?
1 pc	Rear end panel		500.20	n	X
1 pc	End panel top garnish		63.50	n	X
1 pc	Tail gate		976.40	n	X
1 pc	Tail gate glass moulding		50.00	n	X
1 pc	Tail gate "NOTE" emblem		73.60	n	—
1 pc	Tail gate logo		59.70	n	—
1 pc	Tail gate "DIG" plate		59.20	n	—
			3,281.00		
Less 10% :			328.10		

1 pc Rear bumper reverse sensor
1 pc Rear w/s glass sealant

2,952.90
300.00 sn ?
na 60.00 sn X

To remove & refix rear windscreen
glass and conduct water leak test.

na 150.00 X

To remove roof lining, front and
rear seats, trim board and carpet

120.00 ?

To apply undersealing

na 60.00 X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SDE8832P

Page : 2

To putty and spray replaced parts

800.00 *400*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

900.00 *600*

Total : S\$ 5,342.90

=====

Singapore Dollars Five Thousand Three Hundred
and Forty Two and Cents Ninety Only