

ASS. REC. BY:

REF: CS/INC 19007385 / Bsd 301 Special Instruction:

Surveyor:

Mr Jim

ASSIGNMENT (Office)

From (Person):

Annie Koh

of

INC

Date/Time:

11/14/19 @ 6:36pm

Estimated Cost:

Bill to:

OD / ① / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLK 4933 G

Insured:

G2 52742

at Workshop m/s

JKS Motor

Tel:

88119996

of

8 kaki Bkt Ave 4 #03-46

Policy No:

Claim No:

MT/1039614-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9/14/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:43am @ 26/1/19

Person Contacted:

Lefie

Vehicle ① IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 4933G -X

G2 52742 - NALING 09027347/p1

RON-63/12/2009

REF:

NTUC

ASSIGNMENT

From:

Date:

17/4/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLK 4933G

at Workshop m/s

JCS Motor Works

of

8 Kaki Bukit Ave 4 #03-45

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6.8

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLK 4933G

Yr Regn:

18/1/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 2 1.5

C.C

1426

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

110991

T/Radio:

Insured / Std / NI / NA

Eng/No:

P520344101

C/No:

MM6DL2AA-GW186313

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50/16

R:

205/50/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kapsen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

7/4/19

D.O.I.

17/4/19 1257pm

Survey held at

JCS Motor Works

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Lim

Pls check parts prices

07/05/19 Confirmed P/P \$ 7,653.60 @ 8 days with LTG
(\$ 7284.40 Red-49 %)

MV 56,000/2

PV 48,692/2

NV 7,308/2

RECEIVED 17 MAY 2019

26/4/19

Date/Time, File Pass to?

17/05/19

1)

Typ: 4

Date/Time, File Return to?

2)



Prel. Report



Final Report

Days Of Repair:

8

Resurvey No. of Trip:

2

Survey Fee:

250

Transportation

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

) S + RS SI

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I: (\$ 7,653.60 P/P)

TOTAL

250

Niyithia (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Thursday, 11 April 2019 6:36 PM
To: Admin-D (LKKAuto); assignments
Subject: RE: TP CASES FARMED OUT TO LKK ON 12/04/2019

Re-send

Please take note of the OIC and claim number as stated below.

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Thursday, 11 April 2019 5:47 PM
To: 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 12/04/2019

Dear LKK,

Please survey the vehicle for SKQ2698D.
Total vehicle to survey should be 3.

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 11 April 2019 5:44 PM
To: Annie Koh <annie.koh@income.com.sg>; assignments <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 12/04/2019

Dear Annie,

Noted with thanks.

Best Regards,

G.Nivitha| Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annie Koh [<mailto:annie.koh@income.com.sg>]

Sent: Thursday, 11 April 2019 5:42 PM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 12/04/2019

Dear LKK,

Please cancel SKQ2698D**

					KAKI BUKIT AUTOHUB @ BLK 2 KAKI BUKIT AVE 2 #01-17/18		
2	To ignore	MT/1039603- 002	SKQ2698D	N-51 AUTOMOTIVE PTE LTD	Zi Ting / 6842 0051	To cancel	

Warmest Regards

Annie Koh

Senior Admin,

Motor Insurance

T +65 64307899

www.income.com.sg



From: Annie Koh

Sent: Thursday, 11 April 2019 5:30 PM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 12/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	David Phua	MT/1039614-002	SLK4933G	JKS MOTOR WORKS PTE LTD	8 KAKI BUKIT AVENUE 4 #03-46 PREMIER @ KAKI BUKIT	Leslie Enriquez / 88119996		GZ5274Z	9/4/19	
2	Helena Tan	MT/1039603-002	SKQ2698D	N-51 AUTOMOTIVE PTE LTD	KAKI BUKIT AUTOHUB @ BLK 2 KAKI BUKIT AVE 2 #01-17/18	Zi Ting / 6842 0051		PC7272E	9/4/19	
3	Quek Swee Keng	MT/1039741-002	SHC6426E	PREMIER AUTOMOTIVE SERVICES PTE LTD	23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443	MR LIEW / 65446689	10:00-12:00	SJS1004P	10/4/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 6692D

Vehicle Details

Vehicle No.: SLK4933G
Vehicle to be Exported: No
Intended Deregistration Date: 25 Apr 2019
Vehicle Make: MAZDA
Vehicle Model: MAZDA2 SEDAN 1.5L SP.6EAT (LED)
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: P520344101
Chassis No.: MM6DL2SAAGW186313
Maximum Power Output: 85.0 kW (113 bhp)
Open Market Value: \$18,657.00
Original Registration Date: 18 Jan 2017
First Registration Date: 18 Jan 2017
Transfer Count: 0
Actual ARF Paid: \$13,657.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Jan 2027
PARF Rebate Amount: \$10,242.00

Intended COE Rebate Details

COE Expiry Date: 17 Jan 2027
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$50,389.00
COE Rebate Amount: \$38,450.00
Total Rebate Amount: \$48,692.00

The information contained herein is correct as at 25 Apr 2019

OK

Avg dep 6900/yr
575/mth

MV 56,000 / 2
PV 48,692 / 2
NV 7,308 / 2

Nil
26/4/19



ANNOUNCING Speedo Motoring as sgCarMart Premium Dealer for the 8th Consecutive Year


**Speedo
Motoring**

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Mercedes Benz E200 CGI 2010 Model Black Color












Very Well Maintained, Regularly
Serviced, Low Mileage: 115206
Km New Battery!
Direct Owner [Starline](#)


[Browse by Category](#)
[Back \(1 2 3 4 \) Next »](#)
[Sort by Date Posted](#)
[20 results/page](#)

63 vehicles

Mazda 2

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mazda 2		Any	Any	2017	Any	Any	Any	All
	Mazda 6 2.0A Executive		\$89,800	\$9,900 /yr	20-Feb-2017	1,998 cc	27,000 km	Luxury	Available
1 Owner, Well Maintained, Low Mileage With High PARF Rebate. Regularly Servicing At Agent, Under Agent Warranty. Free Road Tax Till 19 Aug 2019. Looking For Sincere Buyer, Please Whatsapp Or SMS For V...									
Posted: 15-Mar-2019 Tags: 2017 Mazda 6, 2017 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda									
	Mazda 2 HB 1.5A		\$59,800	\$7,040 /yr	13-Jun-2017	1,496 cc	21,000 km	Hatchback	Available
Selling On Behalf Of Direct Owner To Private Buyer. Full Agent Serviced. Under Full Agent Warranty. Excellent Condition! Attractive Loan Package Interest From 2.28% And Competitive Trade In Price! Cal...									
Posted: 15-Mar-2019 Tags: 2017 Mazda 2, 2017 mazda 2, Mazda 2, mazda 2, Mazda, 2, Used Mazda									
	Mazda 6 Wagon 2.5A R-Grade Luxury		\$128,888	\$13,560 /yr	25-Sep-2017	2,488 cc	13,150 km	Stationwagon	Available
Lowest Depre In Market! Brand New Selling At \$141,800, Look No Further, Immaculate Condition Inside Out, Pristine And As Good As New! Will Be Handing Over To The Next Buyer In Showroom Condition. Stil...									
Posted: 09-Mar-2019 Tags: 2017 Mazda 6, 2017 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda									
	Mazda 5 2.0A Sunroof		-	N.A	26-May-2017	1,998 cc	-	MPV	SOLD
Graded A by 									
Graded A! Purchase From An Award Winning Dealership! 1 Owner! STA Certified Accident-Free Quality Pre-Owned With Low Mileage Done And Agent Warranty For Peace Of Mind, 100% Loan Approval With Our Flex...									
Cosmo Automobiles									
Posted: 09-Mar-2019 Tags: 2017 Mazda 5, 2017 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda									
	Toyota Camry takes on Volkswagen's Passat								
The Toyota Camry offers more legroom for rear passengers, is sportier around corners and has more safety systems but the Volkswagen Passat is more affordable and feels more premium overall.									
Find out more!									
	Mazda CX-9 2.5A Turbo		-	N.A	09-Oct-2017	2,488 cc	-	SUV	SOLD
7 Full Leather Seats CX-9 Will Drive You An Extraordinary Path Of Exceptional Space And Surprising Luxury. BOSE Sound System, Sunroof, Heads Up Display, Navigation, Lane Departure Warning, Bluetooth I...									
Eurokars Pre Owned									
Posted: 08-Mar-2019 Tags: 2017 Mazda CX-9, 2017 mazda cx-9, Mazda CX-9, mazda cx-9, Mazda, CX-9, cx-9, Used Mazda									
	Mazda MX-5 2.0A		\$130,000	\$13,300 /yr	18-May-2017	1,998 cc	12,700 km	Sports	Available
Agent Unit With Warranty And Full Service Record, Enjoy Loan Interest Rate At 2.28% Financing Possible. Trade In Welcome, 100% Accident Free. Well Maintained, View To Believe. Don't Miss This Beauty, ...									
Posted: 08-Mar-2019 Tags: 2017 Mazda MX-5, 2017 mazda MX5, Mazda MX-5, mazda MX5, Mazda, MX-5, MX5, Used Mazda									
	Mazda CX-5 2.5A Luxury		\$126,000	\$12,670 /yr	14-Dec-2017	2,488 cc	20,000 km	SUV	Available
Immaculate Condition With Body Paint Ceramic Coating, Personal Use Only And Well Taken Care Of. Tyre Changed To Michelin. Serious Seller Looking For Serious Buyer Only, No Dealers Please!									
Posted: 08-Mar-2019 Tags: 2017 Mazda CX-5, 2017 mazda CX5, Mazda CX-5, mazda CX5, Mazda, CX-5, CX5, Used Mazda									

[Compare](#)

Shirley Hiew (LKK Auto)

From: JKS Accident Claims <accidentclaims@jksmotorworks.com.sg>
Sent: Wednesday, 15 May 2019 10:17 AM
To: Shirley Hiew (LKK Auto)
Cc: SUR; JKS Motor Works
Subject: Re: SLK 4933G FINALIZE DOA 09/04/2019 NTUC

Without Prejudice

Dear Sir / Madam :

Strictly for the sake of amicable settlement, JKS would accept the COR finalization @ \$7,653.60 before 7% GST and 8 days of repair.

We will submit our reports/documents to NTUC.

Thanks.

Best Regards,

Leslie Enriquez
JKS Motor Works Pte Ltd
HP : 88119996

8 Kaki Bukit Avenue 4
Premier @ Kaki Bukit
#03-45, Singapore 415875

On Mon, May 13, 2019 at 9:03 AM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Leslie,

Please re - confirm final fig \$7,653.60 @ 8 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Thursday, 9 May 2019 10:22 AM

To: accidentclaims@jksmotorworks.com.sg

Cc: SUR <sur@lkkauto.com>

Subject: SLK 4933G FINALIZE DOA 09/04/2019 NTUC

Dear Leslie,

Please confirm final fig \$7,537.60 @ 6 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: JKS Accident Claims <accidentclaims@jksmotorworks.com.sg>
Sent: Monday, 13 May 2019 5:31 PM
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: Re: SLK 4933G FINALIZE DOA 09/04/2019 NTUC
Attachments: 2ND.pdf; 1ST.pdf

Without Prejudice

Thank you for your email however, apologized we are not able to accept your offer.

Your price for the item nos 30 and 32 changed base on the first finalization. Please refer to your sent finalization. We are not able to accept the changes for the price of both items as the cost price is not even the amount you have put on your 2nd finalization.

Thank you.

Best Regards,

Leslie Enriquez
JKS Motor Works Pte Ltd
HP : 88119996

8 Kaki Bukit Avenue 4
Premier @ Kaki Bukit
#03-45, Singapore 415875

458K

On Mon, May 13, 2019 at 9:03 AM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Leslie,

Please re - confirm final fig \$7,653.60 @ 8 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/04/2019 11:01
Date Of Accident	09/04/2019 18:30
Exact Location Of Accident	SLIP RD OF CTE TO ANG MO KIO AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK4933G
Insured/Policyholder	
Name Of Registered Owner	BLUE STAR CONCIERGE PTE LTD
Co Reg No	- 201506692D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93258498

Vehicle Particulars

Manufacturer	MAZDA
Model	2
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	

Driver

Name of Driver	LIM KIM SENG ANTHONY
NRIC No	S1431378H
Date Of Birth	19/05/1960
Occupation	OUTDOOR
Date Of Driving Pass	12/07/1982
Driving Experience	36 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81113526
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	105 ELLINGTON SQUARE S568986
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHIN SHIUK KIU GENDER: : FEMALE
Passenger 2	NAME: : THERESA LIM GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ5274Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR CHIO
NRIC/Passport Number	
Contact Number	96660864
Address	NA NA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 LTD * BLUE STAR
Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

10/4/19

11.20am

Accident Sketch Plan Pg. 1

SKETCH PLAN



A: SLK 4933G

B: GZ5274Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

After I exited CTE onto the slip to Amy Mokia vehicle in front stop, and I follow to stop. Suddenly I felt an impact from behind + realised vehicle B has hit onto my vehicle

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR ACCIDENT INTERVIEW FORM

NAME (DRIVER) : Lim Kim Seng
 VEHICLE NUMBER : SLK4933G
 DATE/TIME OF ACCIDENT : 9/4/19. 18.30.
 PLACE OF ACCIDENT : Sip Rd from CTE to Ang Mo Kio Ave 1
 THIRD PARTY VEHICLE (IF ANY) : GZ5274Z

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

Tg. Pagar - Ellington Sg -

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT IS THE RESULT?

NO

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

Front & Rear Collision

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

NO

Lim Kim SENG ANTHONY
 Name:

I Affirmed The Above Information Is Given To My Best Knowledge.

**JKS MOTOR WORKS PTE LTD**

8 KAKI BUKIT AVENUE 4, #03-45, Premier @ Kaki Bukit, Singapore, 415875

Company Reg & GST No. : 201407714K

TEL: 67026828 FAX: 6702 6829

EMAIL: accidentclaims@jksmotorworks.com.sg

Motor Claims Department
 NTUC INCOME CO-OPERATIVE LIMITED
 75 Bras Basah Road, NTUC INCOME Centre
 Singapore 189557

REF NO : MT/1039614-002

VEH NO : YJ6366G ON 2 MARCH 2019 @ 18:00 AT CENTRAL
 EXPRESSWAY CTE EXIT NO 11 TOWARDS AMK AVENUE 1

ESTIMATE FOR : SLX4933G MAZDA 2

QUOTATION NO. : JKSQUOTE083

DATE : 10-Apr-19

VEHICLE NO : SLK4933G
 MAKE/MODEL : MAZDA 2
 CHASSIS : MM6DL2SAAGW186313
 ENGINE NO : P520344101
 REG. DATE : 17-Jan-17
 CAPACITY : 1.5CC
 MILEAGE : 110991

Description	Qty	UOM	Repairer's Estimate	Revised Amount (Less 20%)
SPARE PARTS				
✓ 1 BOOT LID	1	ASSY	1,000.00	800.00 ✓ DDV
2 BOOT LID HINGE LH & RH	2	PCS	370.00	296.00 NNX
3 BOOT LID INNER TRIM	1	PC	350.00	280.00 NNX
4 BOOT LID INNER TRIM CLIPS	1	SET	50.00	40.00 NNX
✓ 5 BOOT LID TOP LOCK	1	PC	250.00	200.00 ✓ BT ✓
✓ 6 BOOT LID "MAZDA 2" EMBLEM	1	PC	100.00	77.50 80.00 } NEC ✓
✓ 7 BOOT LID "MAZDA" EMBLEM	1	PC	100.00	58.10 80.00 }
✓ 8 BOOT LID "SKYACTIV" EMBLEM	1	PC	100.00	69.30 80.00 }
✓ 9 BOOT LID REFLECTOR LH & RH @ 248.00	2	PC	900.00	496.00 720.00 BRV ✓
✓ 10 REAR BUMPER	1	PC	980.00	784.00 ✓ CRU ✓
11 REAR BUMPER RETAINER LH & RH	1	PC	120.00	48.00 96.00 ? BRV ✓
✓ 12 REAR BUMPER REFLECTOR LH & RH	2 @ 110.00	PCS	500.00	220.00 400.00 BRV ✓
✓ 13 REAR BUMPER STAY LH & RH	2 @ 45.00	PCS	150.00	90.00 120.00 BRV ✓
14 REAR BUMPER BRACKET CENTER	1	PC	120.00	96.00 ? BRV ✓
15 REAR END PANEL	1	PC	800.00	640.00 ? DDV ✓
16 REAR END PANEL BOOT LID CATCH	1	PC	50.00	40.00 BT ✓
17 REAR END PANEL TOP GARNISH	1	PC	150.00	120.00 DL ✓
18 SPARE TYRE PANEL	1	PC	1,050.00	840.00 ? RX ✓
19 SPARE TYRE PANEL TOP TRIM	1	PC	350.00	280.00 NNX
20 REAR FENDER LH & RH	2	PCS	1,800.00	1,440.00 RX
21 REAR FENDER INNER TRIM LH & RH	2	PCS	250.00	200.00 NNX
22 REAR FENDER INNER TRIM CLIPS	1	SETS	40.00	32.00 NNX
23 REAR FENDER UNDERSHIELD	1	PC	85.00	68.00 NNX
24 REAR FENDER UNDERSHIELD CLIPS	1	SET	50.00	40.00 NNX
✓ 25 REAR TAIL LAMP LH & RH @ 585.90	2	PC	1,600.00	1,171.80 1,280.00 BRV ✓
✓ 26 BOOT WEATHERSTRIP	1	PC	200.00	160.00 ✓ BT ✓
27 ANTENNAE SENSOR DSCN 6897	1	PC	250.00	150.00 200.00 ? BRV ✓
28 REAR BUMPER SIDE BRACKET	1	PC	150.00	70.00 120.00 ? BRV ✓
29 REVERSE CAMERA DSCN 6894 (No image when sat on)	1	PC	400.00	280.00 320.00 ? SC ✓
30 TRUNK OPEN SWITCH DSCN 6895	1	PC	150.00	95.00 120.00 ? SC ✓
31 LICENSE LAMP LH & RH	2	PCS	170.00	136.00 NNX
✓ 32 MUFFLER	1	PC	900.00	576.00 720.00 DDV ✓

NETT PRICE

✓ 32	REVERSE SENSOR WITH HOLDER	1	SET	250.00	200	250.00	duTV
✓ 33	NUMBER PLATE WITH HOLDER	1	SET	50.00		50.00	scr

LABOUR

34	LABOUR CHARGE TO REPAIR & REBUILD INCLUDING CUT & WELD WHERE NECESSARY; REMOVE & REPLACE REAR DAMAGE PARTS AS LISTED ABOVE	1.00	SRV	2,000.00		1200.00 2,000.00	
35	TO APPLY PUTTY AND SPRAY PAINT ON REAR PORTION AFFECTED AREAS	1.00	SRV	2,200.00		1200.00 2,200.00	
36	TO REMOVE AND CUT HOLES ON NEW BUMPER AND REPLACE REVERSE SENSOR	1.00	SRV	120.00		60.00 120.00	
37	TO REMOVE AND INSTALL REAR COMPARTMENT ATTACHMENTS & FITTINGS TO ENABLE REPAIRS	1.00	SRV	150.00		100.00 150.00	
38	TO CHECK ALL WIRINGS AND LIGHTS FUNCTION AND FOCUS	1.00	SRV	60.00		40.00 60.00	

TOTAL ESTIMATE

14,938.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Knownledged by Repairer

Signature:

? pic

Repair is part by part

Repair days 8

TGlim Min

97361577

17/4/19

1320 hrs

**JKS MOTOR WORKS PTE LTD**

8 KAKI BUKIT AVENUE 4, #03-45, Premier @ Kaki Bukit, Singapore, 415875

Company Reg & GST No. : 201407714K

TEL: 67026828 FAX: 6702 6829

EMAIL: accidentclaims@jksmotorworks.com.sg

J. K. S.
AUTOCORPORATION

Motor Claims Department
NTUC INCOME CO-OPERATIVE LIMITED
 75 Bras Basah Road, NTUC INCOME Centre
 Singapore 189557

REF NO : MT/1039614-002

VEH NO : YJ6366G ON 2 MARCH 2019 @ 18:00 AT CENTRAL

EXPRESSWAY CTE EXIT NO 11 TOWARDS AMK AVENUE 1

QUOTATION NO. : JKSQUOTE083

DATE : 10-Apr-19

VEHICLE NO : SLK4933G
 MAKE/MODEL : MAZDA 2
 CHASSIS : MM6DL2SAAGW186313
 ENGINE NO : P520344101
 REG. DATE : 17-Jan-17
 CAPACITY : 1.5CC
 MILEAGE :

ESTIMATE FOR : SLX4933G MAZDA 2

Description	Qty	UOM	Repairer's Estimate	Revised Amount (Less 20%)	
SPARE PARTS					
1 BOOT LID	1	ASSY	1,000.00 821	800.00	DDV
2 BOOT LID HINGE LH & RH	2	PCS	370.00	296.00	NNX
3 BOOT LID INNER TRIM	1	PC	350.00	280.00	NNX
4 BOOT LID INNER TRIM CLIPS	1	SET	50.00	40.00	NNX
5 BOOT LID TOP LOCK	1	PC	250.00	200.00 231	BT ✓
6 BOOT LID "MAZDA 2" EMBLEM	1	PC	52 100.00	80.00	} NEC ✓
7 BOOT LID "MAZDA" EMBLEM	1	PC	58.00 100.00	80.00	
8 BOOT LID "SKYACTIV" EMBLEM	1	PC	69.30 100.00	80.00	
9 BOOT LID REFLECTOR LH & RH @ 248 ✓	12	PC	900.00 426.00	720.00	BRV
10 REAR BUMPER	1	PC	480.00 700	384.00 784.00	CRUV
11 REAR BUMPER RETAINER LH & RH @ 31.70	1	PC	120.00 63.40	96.00	? NEC ✓
12 REAR BUMPER REFLECTOR LH & RH @ 50.40	2	PCS	500.00 100.80	400.00	BRV
13 REAR BUMPER STAY LH & RH @ 25.00	2	PCS	150.00 50.00	120.00	BRV
14 REAR BUMPER BRACKET CENTER	1	PC	120.00 65.00	96.00	? BT ✓
15 REAR END PANEL	1	PC	800.00 624.00	640.00	? DDV ✓
16 REAR END PANEL BOOT LID CATCH	1	PC	50.00	40.00	BT
17 REAR END PANEL TOP GARNISH	1	PC	150.00	120.00	DL
18 SPARE TYRE PANEL X R	1	PC	1,050.00 800.00	840.00	? X R
19 SPARE TYRE PANEL TOP TRIM	1	PC	350.00	280.00	NNX
20 REAR FENDER LH & RH 1092.00	2	PCS	1,800.00	1,440.00	R X
21 REAR FENDER INNER TRIM LH & RH	2	PCS	250.00	200.00	NNX
22 REAR FENDER INNER TRIM CLIPS	1	SETS	40.00	32.00	NNX
23 REAR FENDER UNDERSHIELD	1	PC	85.00	68.00	NNX
24 REAR FENDER UNDERSHIELD CLIPS	1	SET	50.00	40.00	NNX
25 REAR TAIL LAMP LH & RH @ 495.00 752	12	PC	1,600.00 990.00	1,280.00	BRV
26 BOOT WEATHERSTRIP	1	PC	200.00 150.00	160.00	W JV
27 ANTENNAE SENSOR	1	PC	250.00 170.00	200.00	? ✓ SC
28 REAR BUMPER SIDE BRACKET	1	PC	150.00 35.00	120.00	? BRV ✓
29 REVERSE CAMERA DM	1	PC	400.00 280.00	320.00	?
30 TRUNK OPEN SWITCH	1	PC	150.00 95.00	120.00	? SC ✓
31 LICENSE LAMP LH & RH	2	PCS	170.00	136.00	NNX
32 MUFFLER	1	PC	900.00 570.00	720.00	DDV ✓

NETT PRICE

32	REVERSE SENSOR WITH HOLDER	1	SET	250.00	200	250.00	cut ✓
33	NUMBER PLATE WITH HOLDER	1	SET	50.00	30.00	50.00	scr ✓

LABOUR

34	LABOUR CHARGE TO REPAIR & REBUILD INCLUDING CUT & WELD WHERE NECESSARY; REMOVE & REPLACE REAR DAMAGE PARTS AS LISTED ABOVE	1.00	SRV	2,000.00	1200.00 1000.00 1200.00	2,000.00	★
35	TO APPLY PUTTY AND SPRAY PAINT ON REAR PORTION AFFECTED AREAS	1.00	SRV	2,200.00	1200.00	2,200.00	
36	TO REMOVE AND CUT HOLES ON NEW BUMPER AND REPLACE REVERSE SENSOR	1.00	SRV	120.00	60.00	120.00	
37	TO REMOVE AND INSTALL REAR COMPARTMENT ATTACHMENTS & FITTINGS TO ENABLE REPAIRS	1.00	SRV	150.00	100.00	150.00	
38	TO CHECK ALL WIRINGS AND LIGHTS FUNCTION AND FOCUS	1.00	SRV	60.00	40.00	60.00	

TOTAL ESTIMATE

14,938.00

15658

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


 ? pic 26/4/19
 Repair is part by part
 Repair days 8 8 SA
 Ttlin lin
 97361577
 17/4/19
 1320 hrs



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19007385/Bsd3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 23-05-2019



ATTN : DAVID PHUA

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 5274Z	Veh. Inspected	SLK 4933G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1039614-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	11/04/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 2 1.5	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MM6DL2SAAGW186313	Colour	BLACK
Odometer	110991 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	KAPSEN	6 mm
L/H Front Tyre	205/50 R16	KAPSEN	6 mm
R/H Rear Tyre	205/50 R16	KAPSEN	6 mm
L/H Rear Tyre	205/50 R16	KAPSEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/04/2019	Inspect Date / Time	17/04/2019 (12:37 PM)
Survey held at	JKS MOTOR WORKS PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 4933G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	DENTED	1,000.00	821.00
2	BOOT LID HINGE LH & RH	NOT NECESSARY	370.00	-
1	BOOT LID INNER TRIM	NOT NECESSARY	350.00	-
1	SET BOOT LID INNER TRIM CLIPS	NOT NECESSARY	50.00	-
1	BOOT LID TOP LOCK	BENT	250.00	231.00
1	BOOT LID "MAZDA 2" EMBLEM	NECESSARY	100.00	52.00
1	BOOT LID "MAZDA" EMBLEM	NECESSARY	100.00	58.00
1	BOOT LID "SKYACTIV" EMBLEM	NECESSARY	100.00	69.30
2	BOOT LID REFLECTOR LH & RH	BROKEN	900.00	496.00
1	REAR BUMPER	CRUSHED	980.00	909.00
2	REAR BUMPER RETAINER LH & RH	NECESSARY	120.00	63.40
2	REAR BUMPER REFLECTOR LH & RH	BROKEN	500.00	100.80
2	REAR BUMPER STAY LH & RH	BROKEN	150.00	50.00
1	REAR BUMPER BRACKET CENTER	BENT	120.00	65.00
1	REAR END PANEL	DENTED	800.00	624.00
1	REAR END PANEL BOOT LID CATCH	BENT	50.00	50.00
1	REAR END PANEL TOP GARNISH	DISLODGE	150.00	150.00
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,050.00	-
1	SPARE TYRE PANEL TOP TRIM	NOT NECESSARY	350.00	-
2	REAR FENDER LH & RH	TO REPAIR SEE LABOUR	1,800.00	-
2	REAR FENDER INNER TRIM LH & RH	NOT NECESSARY	250.00	-
1	SETS REAR FENDER INNER TRIM CLIPS	NOT NECESSARY	40.00	-
1	REAR FENDER UNDERSHIELD	NOT NECESSARY	85.00	-
1	SET REAR FENDER UNDERSHIELD CLIPS	NOT NECESSARY	50.00	-
2	REAR TAIL LAMP LH & RH	BROKEN	1,600.00	990.00
1	BOOT WEATHERSTRIP	CUT	200.00	150.00
1	ANTENNAE SENSOR	SHORT CIRCUIT	250.00	170.00
1	REAR BUMPER SIDE BRACKET	BROKEN	150.00	35.00
1	REVERSE CAMERA	DAMAGED	400.00	280.00

Report Ref No. CS/INC19007385/Bsd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TRUNK OPEN SWITCH	SHORT CIRCUIT	150.00	95.00
2	LICENSE LAMP LH & RH	NOT NECESSARY	170.00	-
1	MUFFLER	DENTED	900.00	570.00
	LESS 20% DISCOUNT		-2,707.00	-1,205.90
			10,828.00	4,823.60
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR WITH HOLDER (SN)	CUT	250.00	200.00
1	SET NUMBER PLATE WITH HOLDER (SN)	SCRATCHED	50.00	30.00
			300.00	230.00
	LABOUR			
	LABOUR CHARGE TO REPAIR & REBUILD INCLUDING CUT & WELD WHERE NECESSARY; REMOVE & REPLACE REAR DAMAGE PARTS AS LISTED ABOVE. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL AND REAR FENDER LH & RH.		2,000.00	1,200.00
	TO APPLY PUTTY AND SPRAY PAINT ON REAR PORTION AFFECTED AREAS.		2,200.00	1,200.00
	TO REMOVE AND CUT HOLES ON NEW BUMPER AND REPLACE REVERSE SENSOR.		120.00	60.00
	TO REMOVE AND INSTALL REAR COMPARTMENT ATTACHMENTS & FITTINGS TO ENABLE REPAIRS.		150.00	100.00
	TO CHECK ALL WIRINGS AND LIGHTS FUNCTION AND FOCUS.		60.00	40.00
			4,530.00	2,600.00
GRAND TOTAL			15,658.00	7,653.60
RECOMMENDED COST OF REPAIRS (CONFIRMED)				7,653.60

Report Ref No. CS/INC19007385/Bsd3e2

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.