

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

Yi on me

VEHICLE NO : SHA 8206X (Supplementary)

DATE : 25.04.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (RH) <i>mainly broken</i>			\$ 1,388.00 ✓
	SUB TOTAL			\$ 1,388.00
	LESS 20%			\$ 277.60
	DISCOUNTED TOTAL			\$ 1,110.40
	<p><i>Yan</i></p> <p><i>DKK Auto</i></p> <p><i>25/04/2019.</i></p>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.