

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 8511Z

MAKE :

MODEL : HYUNDAI i40

DATE 25/4/2019 14:36

(FZ)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH) <i>X repair</i>			\$ 2,171.40
	Rear Fender Inner Lining (RH) <i>X</i>			\$ 169.30
	Rear Windscreen Moulding <i>X</i>			\$ 28.30
	Rear Door (RH) <i>✓</i>			\$ 2,201.10
	SUB TOTAL			\$ 4,570.10
	LESS 20%			\$ 914.02
	DISCOUNTED TOTAL			\$ 3,656.08
	Rear Fender Advertisement Logo (RH) <i>✓</i>			\$ 100.00 Nett
	Rear Windscreen Sealant <i>X</i>			\$ 46.00 Nett
	Rear Door Advertisement Logo (RH) <i>✓</i>			\$ 100.00 Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>✓</i>			\$ 80.00 Nett
				\$ 326.00
	Labour Charge			
	Panel Beating			\$ 560.00 <i>300</i>
	Spray Painting Charge			\$ 600.00 <i>400</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Towing Charge			\$ 60.00 <i>1</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 <i>50</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00 <i>X</i>
	Remove/Refix Reverse Sensor			\$ 80.00 <i>X</i>
	Transfer of Door			\$ 80.00 <i>50</i>
	TOTAL LABOUR			\$ 1,750.00
	ESTIMATE TOTAL			\$ 5,732.08
<i>Kahr (KAR)</i> <i>26/4/19 1140h</i> <i>3 days</i> <i>4s</i> <i>After Repair photo</i>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any modification(s) is allowed
- Supplementary item(s) must be resurveyed
- All subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: