

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

DATE 30/4/2019

M/S NAIG INSURANCE

DEAR SIR / MADAM

Estimate repair cost for SGN9561G (TOYOTA WISH)

TO SUPPLY :

- | | | | |
|-----|-------|---------------------------------------|-------|
| 01) | 1 PC | TAILGATE | 3-1/2 |
| 02) | 1 PC | TAILGATE LOCK | 10/10 |
| 03) | 1 PC | TAILGATE WEATHSTRIP | 10/10 |
| 04) | 1 PC | TAILGATE BADGE | 10/10 |
| 05) | 1 PC | REAR NUMBER PLATE LAMP | 11 |
| 06) | 1 PC | REAR NUMBER PLATE LAMP CHROME GARNISH | 10/10 |
| 07) | 1 PC | TAILGATE GLASS MOULDING | 10/10 |
| 08) | 2PCS | TAILAMP | 10/10 |
| 09) | 1 PC | REAR BUMPER | 10/10 |
| 10) | 13Pcs | REAR BUMPER CLIPS | 10/10 |
| 11) | 2PCS | REAR BUMPER REFLECTOR | 11 |
| 12) | 1 PC | REAR BUMPER SPONGE | 10/10 |
| 13) | 2PCS | REAR BUMPER SIDE BRACKET | 11 |
| 14) | 1 PC | REAR END PANEL | 3-1/2 |
| 15) | 1 PC | REAR END PANEL (INNER) | 10/10 |
| 16) | 1 PC | REAR END PANEL GARNISH | 10/10 |
| 17) | 1 PC | ANTENNA ELECTRICAL SWITCH | 11 |

LESS 25%

LIST PRICE

\$	1,428.40	—
\$	351.70	—
\$	319.20	—
\$	78.20	—
\$	55.10	X
\$	218.21	—
\$	288.00	—
\$	756.40	X
\$	731.60	—
\$	39.00	—
\$	90.40	X
\$	78.90	X
\$	158.40	X
\$	526.10	—
\$	104.40	X
\$	245.00	—
\$	123.60	X
\$	5,592.61	
\$	(1,398.15)	
\$	4,194.46	

7-4225-41
3169.25

not added
4/5 4200
4/5
2/5/19
Whiggle Murray

18)	REAR END PANEL SEALANT	rec	\$	60.00	50 S.N
19)	TAILGATE GLASS SEALANT	rec	\$	40.00	✓ S.N
20) 1set	PARKING SENSOR	shut	\$	280.00	200 S.N
21)	NO PLATE	svc	\$	40.00	X
22)	REMOVE AND RENEW TAILGATE GLASS		\$	120.00	✓
23)	SENSOR LABOUR		\$	80.00	50
24)	SPRAY PAINTING(mudguard, tailgate, panel, Bumper)		\$	1,100.00	900
25)	LABOUR CHARGE		\$	980.00	600
26)	TUFF COAT		\$	100.00	60
27)	WIRING CHECK		\$	25.00	✓
28)	TO REMOVE AND REFIX GARNISHES ,LUGGAGE TRIM ETC		\$	100.00	80
29)	REMOVE AND RENEW SENSOR		\$	80.00	X
			\$	7,199.46	

5284.25
4235

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: