


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:19

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013998 Date : 05/07/2019 Order : SKF1802J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120	
Regn No: SKF1802J (V 38777)	Regn Date: 20/08/2018	Mileage: 7248	WIP No.: 51562
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8V6J1068202	Engine: CHZ 464511	Dept: U
You have been assisted by :- UB-Kelvin Khoo (138)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	300.00	1.00	300.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR.	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V0941774D	HEADLIGHT (SHARE 5144) Less 020%	1.00	5029.00	4,023.20
X	A8V5821106A	FENDER Less 020%	1.00	777.50	622.00
X	A8V5807065R GRU	COVER (SHARE 51447) Less 020%	1.00	1830.00	1,464.00
X	A8V0821136A	SUPPORT Less 020%	1.00	87.30	69.84
X	A8V5807184	GUIDE (SHARE 51447) Less 020%	1.00	34.40	27.52
X	A3C0973737	HOUSING Less 020%	1.00	28.40	22.72
X	AN 0161857	POP-RIVET (SHARE 5144) Less 020%	5.00	3.00	12.00
X	AN 91022001	NUT Less 020%	4.00	1.50	4.80

Parts 6,246.08
Labour 0.00
Sublet 3,752.00
Menus 0.00
Lubricant 0.00

Sub-Total 9,398.08

7% GST 657.87

Grand Total 10,055.95



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKF 1802 J

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0541/2019/KK
4 May 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages


RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAM 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V6J1068202
Vehicle Regn No. : **SKF 1802 J**
Vehicle Mileage : 7248 KM
Vehicle Owner : Mr Tan Jung Hui
Certificate No : 1800100467
Own Damage Excess : \$642.00 (Inclusive 7% GST)
Accident Date : 26/4/2019
Place : Along Bukit Timah Road
Repair Cost : \$ 10,055.95
WIP No. : 51562
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : _____