



BLK 176, SIN MING DRIVE, #05-15, SIN MING AUTOCARE, SINGAPORE 575721  
Tel:(65) 6453 2235 (24 hrs), (65) 6457 8186 Fax:(65) 6452 0022

Date : 29.04.2019

Not Authorized

|                 |                      |
|-----------------|----------------------|
| Insured Vehicle | SJP4734L             |
| Insured         | CDM Rental & Leasing |
| Accident Date   | 30.031.2019          |
| Policy Number   |                      |

611 Pys 55506  
Pulmonary After Pains

Kenneth  
96910663

11 days

### Parts Replacement Estimate

| No | Product                  | Qty |        | Disc    | Ext Price |
|----|--------------------------|-----|--------|---------|-----------|
| 1  | Front Bumper             | 1   |        | mgc m   | 480.00    |
| 2  | FR Fender                | 1   |        | Bj      | 250.00    |
| 3  | FR Door                  | 1   |        | Bj      | 685.00    |
| 4  | FR Headlight             | 1   |        | Pu      | 280.00    |
| 5  | FR Mirror                | 1   |        | Pu      | 180.00    |
| 6  | RR Fender                | 1   |        | n       | 350.00    |
| 7  | RR Door                  | 1   |        | n       | 650.00    |
| 8  | FR Door Hinge            | 1   |        | Bj      | 150.00    |
| 9  | FR Door Stopper          | 1   |        | Pu      | 145.00    |
| 10 | FR Power Window Motor    | 1   |        | Jm      | 360.00    |
| 11 | FR Door Inner Panel      | 1   |        | SVC Bj  | 320.00    |
| 12 | FR Door Lock             | 1   |        | n       | 120.00    |
| 13 | FR Rocker Panel          | 1   |        | Bj      | 150.00    |
| 14 | FR Mudguard              | 1   |        | CM      | 95.00     |
| 15 | FR Rim                   | 1   |        | Bj      | 260.00    |
| 16 | FR Tyre                  | 1   |        | Pu      | 150.00    |
| 17 | FR Wheel Bearing         | 1   |        | n       | 100.00    |
| 18 | FR Knuckle Arm           | 1   |        | Bj      | 195.00    |
| 19 | FR Lower Arm             | 1   |        | Dis     | 210.00    |
| 20 | FR Linkage               | 1   |        | Dis Pu  | 110.00    |
| 21 | FR Suspension            | 1   |        | Bj      | 180.00    |
| 22 | Front Lower Cross Member | 1   |        | Bu Pu   | 322.00    |
| 23 | Steering Rack & Pinion   | 1   |        | BH/Pu n | 1150.00   |
| 24 | Clip                     | 30  | \$2.00 | n       | 60.00     |
|    |                          |     |        |         |           |
|    |                          |     |        |         |           |

208

Subtotal (Parts): **\$6952.00**

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



**Labour Charges**

| No | Labour Description                     | Price   |
|----|----------------------------------------|---------|
| 1  | To remove and refit damage parts & u/c | 3500.00 |
| 2  | To spray painting                      | 1800.00 |
| 3  | Headlight Focus                        | 100.00  |
| 4  | 4 Wheel Alignment                      | 150.00  |

Total (labour) \$5550

Total (parts & labour) \$12502.00

Add GST 7% \$875.14

**Grand Total \$13377.14**

Henry Khoo  
96356799