

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

Vic

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES190071

Date : 29/04/2019
 Vehicle Num. : SLK 8817H (LCR)
 Make/Model : HONDA VEZEL
 Chassis/Eng# :
 Accident Date : 20/04/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE <i>BUC /</i>		1,100.00
2.	1	REAR TAILGATE VEZEL EMBLEM <i>rec /</i>		56 84.60
3.	1	REAR BUMPER <i>DEF /</i>		865.00
4.	1	REAR WINDSCREEN GLASS MOULDING <i>rec /</i>		150 195.00
List TotalS\$:				2,244.60
20.00% Discount S\$:				448.92
				1,795.68
SPECIAL NETT ITEMS :				
1.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS <i>nm x</i>		30.00
2.	1SET	REAR BUMPER CLIP <i>rec /</i>		30.00
3.	1SET	REVERSE SENSOR <i>shorted /</i>		200 280.00
4.	1	WINDSCREEN SEALANT <i>rec /</i>		60 80.00
Special Nett Total S\$:				420.00
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS				120 180.00
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				50 180.00
WIRINGS CHECK AND RECTIFY WHERE NECESSARY				30 180.00
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHETN REAR END PANEL WHERE NECESSARY AND REPLACE ABOVE PARTS				500 800.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES190071

Date : 29/04/2019
 Vehicle Num. : SLK 8817H (LCR)
 Make/Model : HONDA VEZEL
 Chassis/Eng# :
 Accident Date : 20/04/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS		500 800.00
		Labour Total S\$:		2,140.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

E. & O.E.

Total S\$: 4,355.68
 =====

for WORLD AUTO PTE LTD

Total - \$3226.80/-

hwee jie - LKK
 30/4/19
 P/P 4 days
