

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

27/04/2019

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Attention :- XA039

Page # :- 1

Veh # :- SJP6831B

Veh Model :- HYUNDAI HD AVANTE 1.6 A

Estimate# :- CK419068

Claim # :-

ACC. Date :- 26/04/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	BOOT LID	1	PC 985.00	985.00
2.	BOOT LID LOGO	1	PC 21.00	21.00
3.	BOOT LID EMBLEM - AVANTE	1	PC 32.00	32.00
4.	BOOT LID EMBLEM - S	1	PC 20.00	20.00
5.	BOOT LID HINGE RH & LH	2	PCS 132.00	264.00
6.	BOOT LID LOCK	1	PC 118.00	118.00
7.	BOOT LID LOCK STRIKER	1	PC 18.00	18.00
8.	BOOT LID WEATHERSTRIP	1	PC 79.00	79.00
9.	TAIL LAMP ASSY RH & LH	2	PCS 282.00	564.00
10.	REAR END PANEL	1	PC 581.00	581.00
11.	REAR END PANEL TOP COVER	1	PC 50.00	50.00
12.	REAR BUMPER	1	PC 447.00	447.00
13.	REAR BUMPER SPONGE	1	PC 129.00	129.00
14.	REAR BUMPER REINFORCEMENT	1	PC 271.00	271.00
15.	REAR BUMPER REINFORCEMENT BRACKET RH & LH	2	PCS 79.00	158.00
16.	REAR BUMPER TOP BRACKET RH & LH	2	PCS 24.00	48.00
17.	REAR BUMPER LOWER BRACKETS	3	PCS 24.00	72.00
18.	REAR BUMPER RETAINER RH & LH	2	PCS 28.00	56.00
19.	REAR BUMPER CLIPS	10	PCS 3.50	35.00
20.	REAR FENDER RH (REPAIR)	1	PC	
LIST TOTAL S\$				3,948.00
20% DISCOUNT S\$				-789.60
				3,158.40

SPECIAL NET ITEMS :

- REVERSE SENSOR

1	SET	200.00	200.00
			200.00

SPECIAL NET TOTAL S\$

LABOUR :

TO CUT/WELD REAR END PANEL. KNOCK AND
STRAIGHTEN SPARE WHEEL PANEL. REMOVE AND
REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL
CONNECTION

SPRAY PAINT BOOT LID, HINGES, REAR END PANEL,
REAR BUMPER, SPARE WHEEL PANEL, REAR FENDERS

REMOVE & REFIT LUGGAGE COMPARTMENT INNER
TRIM, GARNISH, COVERINGS

REMOVE & REPLACE REVERSE SENSOR AND CHECK
FUNCTION

TO APPLY SEAL ON WELDING JOINTS

RUST PROOF AFFECTED AREAS

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claims on a "No Prejudice" basis
- No illegal claims to be allowed
- Suppliers to be approved by the insurance company
- is subject to the terms of the insurance company

Acknowledge by repairer

Signature:

Date:

600 900.00
600 1,000.00
40 60.00
30 80.00
40 80.00
30 60.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

27/04/2019

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Attention :- XA039

Page # :- 1 134732
Veh # :- SJP6831B
Veh Model :- HYUNDAI HD AVANTE 1.6 A
Estimate# :- CK419068
Claim # :-
ACC. Date :- 26/04/19
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			2,180.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,538.40

GST @ 7 % 387.69

AMOUNT DUE S\$ 5,926.09

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Tanpin 9249549
WP
Lapsum
Resum after repair
sure (hantoum
5 days
6/5/19 250pm