

ASSIGNMENT

DOI:

29/6/2019

Date / Time

11/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

GZ 2296E

Name of Insured

Lesson Equipment P/L

Insured Tel No.

HP:

Excess Sec II:SS

D.O.A:

11/04/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Naslan Bin Mohamed

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

19/19/4/1005/1468

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SKW 3080Y



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hua Hong.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SKW 3080Y. X

GZ 2296E. X

14/10/19 - FILE PASS TO TYPE MANDATE

28/2/2020 - FILE PASS TO HML TO LCO ST

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 10/12/2019

Confirm with: Ashley

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: NIL

If NO or B 28, Asst. Lia:

Repair Cost: (w/ ltr)

S\$ 1016.50

OIO HSI PARCELED TP

Loss of Rental (LOR) (w/ ltr)

S\$ 385.20

(

3 days) x \$120

Loss of Use (LOU):

S\$ -

(\$

x days)

Loss of Income (LOI):

S\$ -

(\$

x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400

Total:

S\$ 1403.70

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 1403.70

Name 1:

Hua Hong Private Limited

Payee 2 (Sole F.N.A.):

S\$

Name 2:

Payee 3 (Sole F.N.A.):

S\$

Name 3:

ASSIGNMENT

From

Date:

24/6/2019

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

SKW 3080Y

at Workshop m/s

Hua Hong

of

25 D Sengui Kendut Street 1

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11 am
(Not waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

1 up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKW 3080Y

Yr Regn:

26 Oct 2015

Type: ☒ M. Car ☐ M. Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

1356

Make:

Honda Odyssey

C.C

2356

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

150745

T/Radio: Insured / Std / NI / NA

Eng No:

150745

C/No:

JHMRC1890FC204964

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ Burnt

Steering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or

Brake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or

Modi: Nil ☒ S/Rim ☐ STD A/Rim or

Tyre Size:

F: 215/55 R17

R:

BS ☒ EXNOVA ☐ GY ☐ FS ☐ LIZA ☐ MIC ☐ OHTSU ☐ PIR ☐ SUMI ☐

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

11/4/19

D.O.A:

24/6/19

Survey held at

Hua Hong

Des. of Damages: ☒ Frt ☐ Rear ☐ O/S ☐ N/S ☐ UIC ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Confirmed L/S \$950 - 3 days of repair.
(Red \$ 456.24 / 32%)

Date/Time, File Pass 107



: Prel. Report

1)



: Final Report

Date/Time, File Return 107

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

5 + RS, 31

Phone

Value

10/11

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Wash and (\$

Report Format:

Lump Sum / T.C. 17



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 19/19/19/VC05/021685
Our ref: CC4/LPC19007708/Jda3

Date: 01/07/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKW 3080Y


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/06/2019 at the premises of M/s Hua Hong Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	1,406.24
Revised Estimate Amount	: S\$	950.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	950.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Front O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

ONG HWEE JIE
Licensed Appraiser



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 19/19/19/VC05/021685
Our ref: CC4/LPC19007708/Jda3

Date: 01/07/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKW 3080Y

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/06/2019 at the premises of M/s Hua Hong Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	1,406.24
Revised Estimate Amount	: S\$	950.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	950.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Front O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

ONG HWEE JIE
Licensed Appraiser

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2107H

Vehicle Details

Vehicle No.:	SKW3080Y
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	ODY55EY 2.4 EXV-S CVT 5R
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	K24W71012107
Chassis No.:	JHMRC1890FC204964
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$28,685.00
Original Registration Date:	26 Oct 2015
First Registration Date:	26 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$32,159.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2025
PARF Rebate Amount:	\$24,119.00

Intended COE Rebate Details

COE Expiry Date:	25 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$36,853.00
Total Rebate Amount:	\$60,972.00

The information contained herein is correct as at 25 Jun 2019

OK



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

02 May 2019

QUOT201905-000002
HHTPCLAIMS19-64

LONPAC INSURANCE BHD.
300 BEACH RD, #17-04/07
THE CONCOURSE
SINGAPORE 199555

Attn: Motor Claims Department

ACCIDENT INVOLVING SKW3080Y & GZ2296E ON 11/04/2019 AT 71 PIONEER RD (TUAS AMENITY CENTRE) CARPARK AT ABOUT 1230 HOURS

Insured : SALINA
Vehicle Registration No. : SKW3080Y
Vehicle Make : HONDA
Vehicle Model : ODYSSEY 2.4 EXV-S CVT SR
Vehicle Chassis No. : JHMRC1890FC204964
Policy No. : 5084615042-02
Date of Accident : 11/04/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper CUT ✓		\$ 696.30
2	10	Front Bumper Clip nec ✓	\$ 3.90	\$ 39.00 30
3	1	Front Bumper Retainer (RH) un x		\$ 22.50
				\$ 757.80
			Less 20%	\$ 151.56
				\$ 606.24
		To dismantle & change front bumper.		\$ 300.00 200
		To spray front bumper and front RH fender.		\$ 500.00 400
				\$ 1,406.24
			7% GST	\$ 98.44
			Total	\$ 1,504.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Authorised by Claims Dept

Hue Jie - LKK
24/6/19

U/S 3days

Total - \$950/-

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 2 May 2019 10:13 AM
To: assignments@lkkauto.com
Cc: Admin-D (LKKAuto)
Subject: FW: Accident involving SKW 3080 Y & GZ 2296 E on 11/04/2019 at 71 Pioneer Rd [External Confidential]
Attachments: RE: Accident involving SKW 3080 Y & GZ 2296 E on 11/04/2019 at 71 Pione... (35.7 KB); GIA REPORT 2 - TP LONPAC.pdf; GZ2296E.mp4

11-SSum@ 2/5/19
✓NI
✓Yvonne

Lonpac External - Confidential

Our Ref : 19/19/19/VC05/021685

Dear Nivitha,

Please proceed to survey and revert on liability.

We attached the video footage for your attention and you need to turn on the volume to hear the impact.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Yvonne Toh [mailto:yvonne@huahong.com.sg]

Sent: Thursday, 2 May, 2019 10:02 AM

To: GERALD POH WEE BIN

Cc: 'HH Jerleen Tang'

Subject: RE: Accident involving SKW 3080 Y & GZ 2296 E on 11/04/2019 at 71 Pioneer Rd [External General]

Dear Gerald,

We refer to the attached email.

Please find attached revised Police Report attached in SAS.

Kindly advise on liability.

Thank you.

Regards,

Yvonne Toh
Claims Department



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9688 | F. 6661 9699 | huahong.com.sg
f in

From: Yvonne Toh <yvonne@huahong.com.sg>
Sent: Tuesday, 30 April 2019 1:36 PM
To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>
Cc: 'HH Jerleen Tang' <jerleen@huahong.com.sg>
Subject: RE: Accident involving SKW 3080 Y & GZ 2296 E on 11/04/2019 at 71 Pioneer Rd [External General]

Dear Gerald,

Please refer to attached accident footage. Kindly turn on the volume.

Thank you.

Regards,
Yvonne Toh
Claims Department



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9688 | F. 6661 9699 | huahong.com.sg
f in

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 30 April 2019 11:22 AM
To: Yvonne Toh <yvonne@huahong.com.sg>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: Accident involving SKW 3080 Y & GZ 2296 E on 11/04/2019 at 71 Pioneer Rd [External General]

Lonpac External - General
WITHOUT PREJUDICE

Our Ref : 19/19/19/VC00/021685

Dear Yvonne,

Our insured has lodged a police report stating that he was not aware of any accident at the stated location mentioned.

Please furnish us with the video footage to ascertain if there was any collision.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Yvonne Toh [<mailto:yvonne@huahong.com.sg>]

Sent: Monday, 15 April, 2019 4:00 PM

To: MT_Claim_SG

Cc: 'Jerleen Tang'

Subject: Accident involving SKW 3080 Y & GZ 2296 E on 11/04/2019 at 71 Pioneer Rd

Dear Sir/Mdm

Kindly advise liability for this accident case.

Our insured claiming third party. GIA report as per attached.

Should you have any clarification, please contact us @ 6661 9688.

Thank you.

Regards

Yvonne Toh

Claims Department



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1 SINGAPORE 729332

T. 6661 9688 | F. 6661 9699 | W. huahong.com.sg



Mei Kwan (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Thursday, 4 July, 2019 11:39 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Jia Le (LKK Auto); CS A Team; Admin A
Subject: RE: Accident involving SKW 3080 Y & GZ 2296 E on 11/04/2019 at 71 Pioneer Rd [External Confidential]
Attachments: Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC REF: 19/19/19/VC05/021685
LKK REF: CC4/LPC19007708/Jda3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SKW 3080Y

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Our case handler in-charge is Jia Le and she can be contacted at DID: 6749 5792.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 2 May, 2019 4:27 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Subject: RE: Accident involving SKW 3080 Y & GZ 2296 E on 11/04/2019 at 71 Pioneer Rd [External Confidential]

Lonpac External - Confidential

Dear Mei Kwan,

Attached copy of insured's report for your attention.

The video footage has been emailed to your office and

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

Sent: Thursday, 2 May 2019 10:13 AM

To: assignments@lkkauto.com

Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: FW: Accident involving SKW 3080 Y & GZ 2296 E on 11/04/2019 at 71 Pioneer Rd [External Confidential]

Lonpac External - Confidential

Our Ref : 19/19/19/VC05/021685

Dear Nivitha,

Please proceed to survey and revert on liability.

We attached the video footage for your attention and you need to turn on the volume to hear the impact.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Yvonne Toh [<mailto:yvonne@huahong.com.sg>]

Sent: Thursday, 2 May, 2019 10:02 AM

To: GERALD POH WEE BIN

Cc: 'HH Jerleen Tang'

Subject: RE: Accident involving SKW 3080 Y & GZ 2296 E on 11/04/2019 at 71 Pioneer Rd [External General]

Dear Gerald,

We refer to the attached email.

Please find attached revised Police Report attached in SAS.

of any accident at the stated location mentioned.

Please furnish us with the video footage to ascertain if there was any collision.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Yvonne Toh [<mailto:yvonne@huahong.com.sg>]

Sent: Monday, 15 April, 2019 4:00 PM

To: MT_Claim_SG

Cc: 'Jerleen Tang'

Subject: Accident involving SKW 3080 Y & GZ 2296 E on 11/04/2019 at 71 Pioneer Rd

Dear Sir/Mdm

Kindly advise liability for this accident case.

Our insured claiming third party. GIA report as per attached.

Should you have any clarification, please contact us @ 6661 9688.

Thank you.

Regards

Yvonne Toh

Claims Department



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1 SINGAPORE 729332

T. 6661 9688 | F. 6661 9699 | W. huahong.com.sg



This email has been checked for viruses by AVG antivirus software.

www.avg.com




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19007708/Jda3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 02-03-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 2296E	Veh. Inspected	SKW 3080Y	
Policy No.	Z19VC05001564	Coverage (\$)	0.00	
Claim No.	19/19/19/VC05/021685	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	02/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JHMRC1890FC204964	Colour	GREY	
Odometer	150745	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	DUNLOP	6 mm	
L/H Front Tyre	215/55 R17	DUNLOP	6 mm	
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/04/2019	Inspection Date	24/06/2019	
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 3080Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CUT	696.30	696.30
10	FRONT BUMPER CLIP @\$3.90	NECESSARY	39.00	30.00
1	FRONT BUMPER RETAINER (RH)	NOT NECESSARY	22.50	-
	LESS 20% DISCOUNT		-151.56	-145.26
			606.24	581.04
LABOUR				
	TO DISMANTLE & CHARGE FRONT BUMPER.		300.00	200.00
	TO SPRAY FRONT BUMPER AND FRONT RH FENDER .		500.00	400.00
			800.00	600.00
GRAND TOTAL			1,406.24	1,181.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				950.00

Report Ref No. CC4/LPC19007708/Jda3n2

ONG HWEЕ JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.