

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
CHIN	IA TAIPING INSUI	RANCE (S) PTE LTD	Ref : CC6/CTI19007720	/Uds3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date: 04-05-2020 Code: CTI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJX 9360G	Veh. Inspected	SJX 3895U	
	Policy No.	DMPCSN3010431901	Coverage (\$)	0.00	
	Claim No.	SNM19D201968/C02	Excess (\$)	0.00	
	Assign From		Assign Date	02/05/2019	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VIOS (A)	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	MR053HY9305166779	Colour	SILVER	
	Odometer	138067	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
	L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
	R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
	L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	30/04/2019	Inspection Date	02/05/2019	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				